

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>WELL API NO.</b> 30-025-21444	
<b>5. Indicate Type of Lease</b> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
<b>6. State Oil &amp; Gas Lease No.</b>	
<b>7. Lease Name or Unit Agreement Name:</b> Ollie Boyd	
<b>8. Well No.</b> 1	
<b>9. Pool name or Wildcat</b> Drinkard	
<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
<b>1. Type of Well:</b> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
<b>2. Name of Operator</b> Western Oil Producers Inc	
<b>3. Address of Operator</b> P O Box 1498 Roswell, NM 88202	
<b>4. Well Location</b> Unit Letter <u>N</u> : <u>990</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>23</u> Township <u>22S</u> Range <u>37E</u> NMPM County <u>Lea</u>	
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions : Attach wellbore diagram of proposed completion or recompilation.

Waiting on plugging unit.

Anticipated action: 100' plug @ 6200' or cast iron bridge plug @ 6200' w/35 sks cement & tag. 10' plug @ top of San Andres, 100' plug @ top of Queens. 100' plug on top of salt section. 50' in & 50' out of 8 5/8" @ 1173'. 100 plug @ 250'-350'. Surface plug w/10 sks cement. Install dry hole marker and clean location.

AUG 2003  
H.C. FIELD  
Hobbs  
NCO

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Virginia L Long TITLE Soc - Treas DATE 8-12-03

Type or print name Virginia L Long Telephone No. 623-5070

(This space for State use)

APPROVED BY Gay W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE AUG 15 2003  
Conditions of approval, if any: