Submit 3 Copies To Appropriate District	State of Ne		•	•			n C-103
Office District 1	Energy, Minerals and	Natural Res		MACH A D	1310	May	27, 2004
1625 N. French Dr., Hobbs, NM 87240 District II OIL CONSERVATION DIVISION				WELL API NO. 30-025-37349			
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Type of Lease			
District III 1000 Rio Brazos Rd., Aztec, NM 87410				STATE X FEE			
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	·			6. State O	il & Gas Lea	se No.	
		LIMELLO		7 Y	ĭ	<u> </u>	Τ
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				/. Lease N		Agreement 1	Name:
PROPOSALS.) 1. Type of Well:				8. Well Nu	State "/ umber		,
Oil Well X Gas Well Other				11-Y			
2. Name of Operator				9. OGRID Number			
OXY USA WTP Limited Partnership				192463 10. Pool name or Wildcat			
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294				Hobbs: Wolfcamp			
4. Well Location	77210 1231		······································		5555, 11511.	Sump	/
Unit Letter J :	1484 feet from the	South	_ line and	1526	feet from the	<u>East</u>	line
Section 29	Township 18	-S Range	38-E	NMPM	С	ounty	Lea
	11. Elevation (Show wh		B, RT, GR, etc	.)			
Pit or Below-grade Tank Application	or Closuro 🗍	3647' GL	i		1	<u> </u>	
Pit type Depth to Groundwater		est fresh water v	vell Dist	ance from ne	arest surface w	ater	
Pit Liner Thickness: mil			1				
L				· · · · · · · · · · · · · · · · · · ·			
12. Check A	appropriate Box to Inc	dicate.Natu	e of Notice	Report o	r Other Da	ıta .	
NOTICE OF INT		110000	- •	•	IT REPOR		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK						LTERING CA	ASING [
<u> </u>							
TEMPORARILY ABANDON	CHANGE PLANS		MENCE DRILLIN	NG OPNS.		LUG AND BANDONME	ENT L
PULL OR ALTER CASING	MULTIPLE COMPLETION		IG TEST AND NT JOB				
OTHER:		☐ OTHE	R: Open add	itional p	ay in the 1	Wolfcamp	X
13. Describe proposed or completed	l operations. (Clearly state	all pertinent of	letails, and give	pertinent d	ates, includir	ng estimated	date
of starting any proposed work).							
or recompletion.							
					M. T.	1	•
					ć`	gradia Projector	
See Attachment							
					100		
				;		• •	
				1			
I hereby certify that the information a	bove is true and complete	to the best of	my knowledge	and belief.	I further certi	fy that any pit	or below-
grade tank has been/will be constructed or o							
SIGNATURE MUNIC STE	poem	F-mail add	ress: N	lark Stone	onspory co	TE8/2	8/06
Type or print name Mark Stephe	ns .	L-man add	qulatory Compress: N	igi k_2rebi	Telephon	e No. (713)	366-5158
For State Use Only				CENERAL	MANN	SEP 0 5	2006
APPROVED BY MISSING	Silian	TITLE	CHPERVISOR	1000	DAT	P 0 - 200	
Conditions of Approval, if any:			1 30.	1	AE	P 0 . 200	20
		0				. «AA	10

8/11/06 - 8/23/06:

MI x RU. NU BOP. POOH with rods x pump. RIH with 4-3/4" bit x scraper and clean out to 7830'. Circulate clean. RU Schlumberger WL and perf 7628'-34', 7649'-52', 7655'-57', 7659'-65', 7681'-82', 7693'-94', 7700'-04', 7719'-26', 7733'-34', 7738'-45', 7750'-52', 7759'-63', 7765'-68', 7774'-7782', 7791'-98', 7800'-13' (2 JSPF). RD WL x RIH with 5-1/2" packer and set at 7550'. Acidize 7628' - 7813' with 4700 gal. 15% HCL. RU swab equipment and recover 150 bbls spent acid. RIH with 235 jts. 2-7/8" production tubing x rods and 1.5 x 26 2-stage pump. Seat pump x space out rods. ND BOP x NU WH. RD x MO. Clean location and put well back on production.