

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr. Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. <u>041-10003</u> <u>30-004-110003</u>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Orbit Petroleum, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 720 W. Wilshire, Suite 115., Oklahoma City, OK 73116		7. Lease Name or Unit Agreement Name: State BA
4. Well Location Unit Letter <u>A A</u> : <u>990</u> feet from the <u>N</u> line and <u>990</u> feet from the <u>E</u> line Section <u>34</u> Township <u>7S</u> Range <u>35E</u> NMPM County <u>Roosevelt</u>		8. Well No. <u>1</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Todd Upper San Andres

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/30/06 MIRU.Nipple Down wellhead. Could not pull tbq. SDFN.

7/05/06 RU wireline. GIH w sinker bar and collar locator. Got down to 2410. POH w/ tools. RU pump. Load hole w/ 4 bbls. Pressure up to 1500 psi. Slow leak. Pumped 2 bbls/min. @ 900 psi. Total 30 bbls. RIH w/ sinker bar on wireline. Stopped @ 2410. Worked tbq. Tbg released. POH w/ 57 jts. tbq. Riggged up wireline. RIH w/ sinker bar and CL. Stopped @ 1732. RIH w/ gauge ring. Stopped @ 1500. SDFN.

7/06/06 RIH w. 3 7/8 overshot. Stopped @ 1550. Layed down 6 jts. Run 6 jts out of derrick. Pump 30 bbls. fresh water. Worked tbq. down to 1742'. Circ. hole w/ 100 bbls fresh water. could not get down past 1742'. Called Gary Wink w/ OCD.

Approved to Sqz. 100 sx. cement. RIH w/ 4 1/2 packer. Hit tight spot @ 1479'. POH w/ tbq. Left pkr. in hole. SDFN.

7/07/06 RIH w. 4 1/2 AD-1 PKR. Set @ 1426'. Sqz 100 sx cement. WOC. 4 hrs. Pressure up, held 300 psi. Establish 2 bbls/min. @ 700 psi. Release packer. POH to 1240 ft. Got communication. POOH w/ pkr. RIH open ended Tagged plug @ 1550'. Spot 25 sx cement. POOH w tbq. WOC SDFN.

7/10/06 RIH w/ tbq. Tagged plug @ 1340'. POOH w/ tbq. perf csg. @ 382'. Set Pkr. @ 30'. Establish Circulation, Circ. 110 sx. cmt down 1/2 & up 8 5/8 to surface. CWI, Cut off Wellhead, RD. Weld on Dry Hole Marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bob Wilcox P.G. TITLE Geologist DATE 8/28/06

Type or print name Bob Wilcox Telephone No. (505) 344-7373
(This space for State use)

APPROVED BY Chris Williams TITLE DISTRICT SUPERVISOR DATE _____

Conditions of approval, if any:

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

SEP 05 2006