Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-23459
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B-2229
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Phillips "E" State
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Water Injection	8. Well Number 14
2. Name of Operator	9. OGRID Number
ConocoPhillips Company ATTN: Celeste Dale	217817
3. Address of Operator	10. Pool name or Wildcat
4001 Penbrook Street Odessa, Texas 79762	Maljamar GB/SA
4. Well Location	
Unit Letter B : 660 feet from the North line and 1,98	
Section 15 Township 17-S Range 33-E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc. 4,160' GL; 4,170' RKB)
Pit or Below-grade Tank Application 🗵 or Closure 🔲	100 July 100
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well Dis	tance from nearest surface water N/A
	Construction Material STEEL
12. Check Appropriate Box to Indicate Nature of Notice,	
12. Check Appropriate Box to indicate Nature of Notice,	Report of Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☑ REMEDIAL WOR	K ALTERING CASING
— — —	ILLING OPNS.□ P AND A □
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB 🔲
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEI	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEI	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEING PROCE	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEI	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEING PROCE	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEING PROCE	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEING THE OIL CONSERVATION DIVISION LEGIT BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion OURE SEP Roceived Hobbs OCD OCD OCD OCD OCD OCD OCD OCD
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEING PROCE	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion DURE SEP Hobbis OCD Test and belief. I further certify that any pit or below-
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEING THE OIL CONSERVATION DIVISION LEGIT BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS.	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion DURE SEP Hobbis OCD Test and belief. I further certify that any pit or below-
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEI THE OIL CONSERVATION DIVISION LIUGT BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines ⋈, a general permit □	d give pertinent dates, including estimated date trach wellbore diagram of proposed completion DURE SEP Hobbis OCD Test and belief. I further certify that any pit or below-
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEING PROC	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion DURE SEP Hobbs OCD Ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan E.E. (Triple N Services) DATE 09/05/06
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEI THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS. I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed relosed according to NMOCD guidelines ☒, a general permit ☐ SIGNATURE ☐ TITLE James F. Newman, P. Type or print name James F. Newman E-mail address: jim@triple.	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion DURE SEP Hobbis OCD Ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan E.E. (Triple N Services) DATE 09/05/06 Inservices.com Telephone No. 432-687-1994
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEING PROC	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion DURE SEP Hobbs OCD Ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan E.E. (Triple N Services) DATE 09/05/06
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. SEE ATTACHED WELLBORE DIAGRAMS & PROPOSED PLUGGING PROCEI THE OIL CONSERVATION DIVISION LIGHT BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS. I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ SIGNATURE	d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion DURE SEP Hobbis OCD Ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan E.E. (Triple N Services) DATE 09/05/06 Inservices.com Telephone No. 432-687-1994

WELLBORE SKETCH

ConocoPhillips Company -- Mid-Continent BU/Odessa

S-10/70 Cored 357 from 4243-4600' 51/37/70 Post 4379-4384, 4428-433 and 4469-4474' wild JSPF	
County : Field: State New Mexico	
12-1/4" Hole	
12-1/4" Hole	
12-14* Hole	
API Number: 30-025-23459 State Lease State: Simulation History:	
Sistus: Situs: Interval Date Type Gale Sand Press Sand Press Sand Press Sand Press Sand	
Formation Tops:	# B-22
Formation Tops:	
Formation Tops:	
Formation Tops:	
Formation Tops:	ı
Formation Tops:	ISIP F
Formation Tops:	
Formation Tops:	
Formation Tops:	60 ho
Formation Tops:	2400 (
Formation Tops:	2600 1
Formation Tops:	2700 1
Formation Tops:	4100 2
Siz7770 IPP 48 BO, 4 BSW, GOR 1076 @ 90 BWPD @ 90 BW	
1/17/17 Converted to water Injection @ 90 BWPD @ 90# 4379-4474 4373-4474 4373-4474 4373-4474 4373-4474 4373-4474 4373-4474 7/1/10 15% NEFE HCI 1.500 200# RS 3183 7/1/10 200# RS 200#	
### ##################################	
7/2/01 Isolate csg lask @ 1033-1156' wi43 bbls cmt, Circ sx lead mix to surface and 81 sx out leak 4379-4474 7/11/01 15% NEFE HCI 1,500 200# RS 3183 7/10/08 Falled MiT test Reled MiT tes	3600 3
Second	
Second	50
7/10/06 Failed MIT test 8/23/06 Test casing from 1026' to 1152', casing is bad Propose setting CIBP @ 4252 TOC 4-1/2" cas @ 2,550' (T.S.) Base of Salt @ +/- 2,853' 7-7/8" Hole Grayburg 479 - 4384' w/4 JSPF - 20 holes 4426 - 4437' w/4 JSPF - 20 holes 4486' - 4437' w/4 JSPF - 20 holes 4486' - 4437' w/4 JSPF - 20 holes Base Salt	
8/23/06 Test casing from 1026' to 1152', casing is bad Top of Salt @ 1,865' TOC 4-1/2" cag @ 2,550' (T.S.) Base of Salt @ +/- 2,853' 7-7/8" Hole Gravburg 4/379' - 4384' w/4 JSPF - 20 holes 4/379' - 4384' w/4 JSPF - 20 holes 4/489' - 4474' w/4 JSPF - 20 holes 1	2594 4
Top of Salt @ 1,855' TOC 4-1/2" csg @ 2,550' (T.S.) Base of Salt @ +/- 2,853' 7-7/8" Hole Formation Tops: 4379' - 4384' w/4 JSPF - 20 holes 4428' - 4433' w/4 JSPF - 20 holes 4428' - 44433' w/4 JSPF - 20 holes 5	
TOC 4-1/2" csg @ 2,550' (T.S.) Base of Salt @ +/- 2,853' 7-7/8" Hole Formation Tops: 4379' - 4384' w/4 JSPF - 20 holes Rustler 1488' 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
### Base of Salt @ +/- 2,853' 7-7/8" Hole Grayburg	
### Rese of Salt @ +/- 2,853' 7-7/8" Hole Grayburg	
Base of Salt @ +/- 2,853' 7-7/8" Hole Grayburg = = 4379' - 4384' w/4 JSPF - 20 holes = = 4428' - 4433' w/4 JSPF - 20 holes = 3428' - 4433' w/4 JSPF - 20 holes = 4428' - 4474' w/4 JSPF - 20 holes = 4488' - 4474' w/4 JSPF - 20 holes = 3488' - 4474' w/4 JSPF - 20 holes = 3488' - 4474' w/4 JSPF - 20 holes = 3488' - 4478' w/4 JSPF - 20 holes = 3488' - 4474' w/4 JSPF - 20 holes	
### Rese of Salt @ +/- 2,853' 7-7/8" Hole Grayburg	
7-7/8" Hole Grayburg	
7-7/8" Hole	
7-7/8" Hole Grayburg Formation Tops: Rustler 1468'	
7-7/8" Hole Gravburg Formation Tops: Rustier 1468" 1468" 4428" 4433" w/4 JSPF - 20 holes Rustier 1468" 1469" - 4474" w/4 JSPF - 20 holes Base Salt 2307" - 2853"	
Grayburg Formation Tops: == 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4426' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: - == 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' - == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' - == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: - == 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' - == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' - == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: = = 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' = = 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' = = 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: == 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: = 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' = 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' = 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: = 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' = 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' = 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: = = 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' = = 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' = = 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: == 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: == 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
Grayburg Formation Tops: == 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4379' - 4384' w/4 JSPF - 20 holes Rustler 1468' == 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' == 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
== 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853'	
100 VII V W V V V V V V V V V V V V V V V V	
Post Contract Contrac	
Yates 2762'	
4-1/2" 11.6# N-80 LT&C @ 4,600' w/ 375 sx, TOC 2,550' by TS Queen 3738' Grayburg 4218'	



ConocoPhillips

Proposed Plugging Procedure

Phillips State "E" #14
Maljamar GB/SA Field
660' FNL & 1,980' FEL, Sec 15, T-17-S, R-33-E
API# 30-025-23459
Lea County, New Mexico

Casings:

8%" 24# casing @ 360' cmt'd w/ 300 sx, circulated 50 sx

4½" 11.6# casing @ 4,600' cmt'd w/ 375 sx, TOC 2,550' by T.S.

perforations 4,379 - 4,474'

- Notify BLM & NMOCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 1. Set steel pit and flow down well as needed. MIRU plugging equipment. ND wellhead and NU 6" 5,000# hydraulic BOP.
- 2. POOH w/ production equipment as present.
- 3. RIH w/ HM tbg-set CIBP on 2% workstring to 4,329. RU cementer and set CIBP @ 4,329. Circulate hole w/ 10 ppg plugging mud, pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 378' in 4½ 11.6# casing) 4,329 3,951'. Grayburg San Andres plug
- 4. POOH w/ tubing to 2,953' and pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 378' in 4½" 11.6# casing) 2,953 2,575'. POOH w/ tubing. Base of salt plug
- 5. RU lubricator and RIH w/ wireline, perforate 4½" casing @ 1,865'. POOH w/ wireline.
- 6. RIH w/ AD-1 packer to ~1,500°. Load hole w/ mud, set packer, and establish rate at less than 1,500 psi. Squeeze 40 sx C cmt w/ 2% CaCl₂ (1.32 ft³/sk yield, 52.8 ft³ slurry volume, calculated fill 156' in 7½" openhole) 1,865 1,709°. WOC & TAG this plug no deeper than 1,765°. POOH w/ packer. *Top of salt plug*
- 7. RIH w/ tubing to 1,156' and pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 378' in 4½" 11.6# casing) 1,156 771'. POOH w/ tubing.
- 8. RU lubricator and RIH w/ wireline, perforate 4½" casing @ 410'. POOH w/ wireline.
- 9. RIH w/ AD-1 packer to ~180'. Load hole w/ mud, set packer, and establish rate at less than 1,500 psi. Squeeze 50 sx C cmt w/ 2% CaCl₂ (1.32 ft³/sk yield, 66.0 ft³ slurry volume, calculated fill 195' in 7%" openhole) 410 215'. WOC & TAG this plug no deeper than 310'. POOH w/ packer. Surface casing shoe plug

- **10.** Circulate 15 sx C cmt (1.32 ft 3 /sk yield, 19.8 ft 3 slurry volume, calculated fill 227' in $4\frac{1}{2}$ " 11.6# casing) 50' to surface. **surface plug**
- **11.** RDMO location. Clean steel pit & haul fluids to disposal. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

PROPOSED PLUGGED WELLBORE SKETCH

ConocoPhillips Company -- Mid-Continent BU/Odessa

Date: September 4, 2006 RKB@ 4170 DF@ 4169 Subarea : Buckeye Lease & Well No. : No. 14 W GL @ Phillips State E 4160 660' FNL & 1980' FEL, Sec. 15, T-17-S, R-33-E Legal Description: NMPM Survey 15 sx C cmt 50' to surface County: Lea State: New Mexico Field: Maljamar (GB/SA) 12-1/4" Hole Date Spudded: April 26, 1970 Rig Released: May 11, 1970 API Number : 30-025-23459 State Lease # B-2229 Status: proposed plugged 8-5/8" 24# K-55 LT&C @ 360' w/ 300 sx, circ 50 sx Perforate/squeeze 50 sx C cmt **Stimulation History:** 410 - 310' TAG Max <u>Press</u> ISIP Rate Interval Date Type Sand Gals 5/10/70 Cored 357' from 4243-4600' 5/13/70 Perf 4379-4384, 4428-4433' and 4469-4474' w/4 JSPF, 60 holes 4469-4474 Super Mud Acid 2400 0.81 5/14/70 500 3050 4428-4433 Possible Casing leak 1,026 - 1,152' 5/14/70 Super Mud Acid 500 3000 2600 1.0 25 sx C cmt 1,156 - 771' 4379-4384 5/14/70 Super Mud Acid 500 3250 2700 1.2 Sqz csg lk 1,033 - 1,156 w/ 149 bbls cmt 4379-4474 5/15/70 Refined Oil 25,200 19,500 5750 4100 20.0 (Frac in 3 stages) 40 RCN Ball Sealers 5/27/70 IPP 48 BO, 4 BSW, GOR 1076 Converted to water Injection @ 90 BWPD @ 90# 1/17/77 2,000 200# RS 4379-4474 3/13/90 20% NEFE HCI 4000 3600 3.0 7/2/01 Isolate csg leak @ 1033'-1156' Squeeze thru leak 1033-1156' w/149 bbls cmt, Circ 50 sx lead mix to surface and 81 sx out leak 1,500 200# RS 4379-4474 7/11/01 15% NEFE HCI Failed MIT test 7/10/06 Perforate/squeeze 40 sx C cmt 1.865 - 1.765' TAG Test casing from 1026' to 1152', casing is bad 8/23/06 Top of Salt @ 1,865' Propose setting CIBP @ 4252' TAIPLE N SERVICES INC. PROPOSED PLUGGING PROCEDURE 1) CIBP w/25 sx C cmt 4,329 - 3,951' TOC 4-1/2" csg @ 2,550' (T.S.) 2) 25 sx C cmt 2,953 - 2,575' 3) Perforate/squeeze 40 sx C cmt 1,865 - 1,765' TAG 4) 25 sx C cmt 1,156 - 771' 5) Perforate/squeeze 50 sx C cmt 410 - 310' TAG Base of Salt @ +/- 2,853' 6) 15 sx C cmt 50' to surface 25 sx C cmt 2,953 - 2,575' Capacities 41/2" 11.6# csa: 11.468 ft/ft3 0.0872 ft3/ft 8%" 24# csg: 2 797 ft/ft3 0.3575 ft3/ft 71/4" openhole: 2 957 ft/ft3 0.3382 ft3/ft 121/4" openhole: 1.222 ft/ft3 0.8185 ft3/ft 7-7/8" Hole CIBP w/25 sx C cmt 4,329 - 3,951' Grayburg **Formation Tops:** 4379' - 4384' w/4 JSPF - 20 holes 1468 Rustler 4428' - 4433' w/4 JSPF - 20 holes Top Salt 1865' - 2307' 4469' - 4474' w/4 JSPF - 20 holes Base Salt 2307' - 2853' Yates 2762 4-1/2" 11.6# N-80 LT&C @ 4,600' w/ 375 sx, TOC 2,550' by TS Queen 3738 Grayburg 4218'

San Andres

4490'

PRTD:

TD:

4586

4600