

OCD-HOBBS

Form 3160-5
(April 2004)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1064-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NM0889
2. Name of Operator COG Operating LLC		6. If Indian, Allottee or Tribe Name
3a. Address 550 W. Texas Ave., Suite 1300 Midland, TX 79701	3b. Phone No. (include area code) 432-685-4372	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330' FNL; 1650' FWL Unit C, Sec 6, T26S, R38E		8. Well Name and No. M. D. Self #7
		9. API Well No. 30-025-37352
		10. Field and Pool, or Exploratory Area Tubb Drinkard
		11. County or Parish, State Lea County, NM


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other surface commingling
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	and off lease
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	measurement

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

SEE ATTACHED REQUEST FORM



SUBJECT TO
LIKE APPROVAL
BY STATE

PC-1165

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Phyllis A. Edwards		Title Regulatory Analyst
Signature <i>Phyllis A. Edwards</i>	Date 12/19/2005	

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Title Office	Date
--	-----------------	------

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**APPLICATION FOR SURFACE COMMINGLING,
OFF LEASE STORAGE AND MEASUREMENT APPROVAL**

COG Operating LLC is requesting approval for surface commingling and off-lease storage and measurement of oil and gas production from the following formation (s) and well (s) on

Federal Lease No: **NM 0889**

Lease Name: **M. D. Self**

<u>API #</u>	<u>Well #</u>	<u>Location</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>	<u>Formation</u>
30-025-37352	7	330' FNL & 1650' FWL	6	26S	38E	Justis Blinebry-Tubb-Drinkard

With oil and gas production from the following formation (s) and well (s) on

Federal Lease No: **NM 0889**

Lease Name: **M. D. Self**

<u>API #</u>	<u>Well No</u>	<u>Location</u>	<u>Sec</u>	<u>Twp</u>	<u>Rng</u>	<u>Formation</u>
30-025-12447	3	467' FNL & 467' FWL	6	26S	38E	Langlie Mattix; 7 Rivers-Queen-Grayburg
30-025-12449	5	330' FNL & 330' FWL	6	26S	38E	Justis Blinebry-Tubb-Drinkard
30-025-12450	6	1750' FNL & 330' FWL	6	26S	38E	Justis Blinebry-Tubb-Drinkard

Production from the wells involved is as follows:

<u>Well Name and No</u>	<u>BOPD</u>	<u>Oil Gravity</u>	<u>MCFPD</u>
M. D. Self #3	2	36.2	6
M. D. Self #5	7	36.2	4
M. D. Self #6	1	36.2	3

**BUREAU OF LAND MANAGEMENT
Roswell Field Office
2909 West Second Street
Roswell, New Mexico 88201
505-627-0272**

**Off-Lease Measurement, Storage, and Surface Commingling
Conditions of Approval**

Approval of surface commingling and off lease storage and/or measurement is subject to the following conditions of approval:

1. This agency shall be notified of any change in sales method or location of the facility.
2. This agency shall be notified of any spill or discharge as required by NTL-3A.
3. This agency reserves the right to modify or rescind approval whenever it determines continued use of the approved method may adversely affect the surface or subsurface environments.
4. Thi approval is subject to like approval by the New Mexico Oil Conservation Division (NMOCD).
5. Additional wells and/or leases require additional commingling approvals.
6. This approval does not constitute right-of-way approval for any off lease activities. Within 30 days, an application for right-of-way approval must be submitted to the Realty Section if not already done.