Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-06217
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTI	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	· · · · · ·	Eumont Hardy Unit 8. Well Number #016
1. Type of Well: Oil Well X	Gas Well Other	
2. Name of Operator	1 Cos Corn	9. OGRID Number 151228
3. Address of Operator	i Gas Corp	10. Pool name or Wildcat
PO Box 5	155 Santa Fe, NM 87502	EUMONT;YATES-7 RVRS-QUEEN
4. Well Location		_H,
Unit Letter I :	1980 feet from the SOUTH line and	660 feet from the EAST line
Section 36	Township 20S Range 37E	NMPM LEA County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	c.)
Pit or Below-grade Tank Application of		
. .	aterDistance from nearest fresh water wellD	
Pit Liner Thickness: mil		Construction Material
12. Check A	Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF IN	ITENTION TO: SUI	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
PERFURIN REINEDIAL WORK	PLUG AND ABANDON I I REMEDIAL WO	RK II ALTERING CASING II
TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIAL WO CHANGE PLANS COMMENCE DI	RK
		RILLING OPNS. P AND A
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS COMMENCE DI MULTIPLE COMPL CASING/CEMEI	RILLING OPNS. PAND A D
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS COMMENCE DI MULTIPLE COMPL CASING/CEMEI	RILLING OPNS. PAND A NT JOB X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp	CHANGE PLANS COMMENCE DI MULTIPLE COMPL CASING/CEMEI	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion.	CHANGE PLANS MULTIPLE COMPL CASING/CEME OTHER: REQU cleted operations. (Clearly state all pertinent details, a pork). SEE RULE 1103. For Multiple Completions: A	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK	CHANGE PLANS MULTIPLE COMPL CASING/CEME OTHER: REQU cleted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST SING TO 500PSI FOR 30 MINUTES – OK	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD	RILLING OPNS. PAND A NT JOB EST TA STATUS nd give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS	CHANGE PLANS MULTIPLE COMPL OTHER: REQU O	RILLING OPNS. PAND A NT JOB SEST TA STATUS X Ind give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS	CHANGE PLANS MULTIPLE COMPL OTHER: REQU O	RILLING OPNS. PAND A DEST TA STATUS X Not give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WI PRESSURE CHART IS ATTACH	CHANGE PLANS MULTIPLE COMPL OTHER: REQU Detected operations. (Clearly state all pertinent details, a brk). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST SING TO 500PSI FOR 30 MINUTES – OK TH NMOCD HED This Approval of Temporary Abandonment Expires	RILLING OPNS. PAND A DEST TA STATUS X Not give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Not 2345
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESSURE CHART IS ATTACH	CHANGE PLANS MULTIPLE COMPL OTHER: REQU letted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD HED This Approval of Temporary Abandonment Expires above is true and complete to the best of my knowled	RILLING OPNS. PAND A DEST TA STATUS X Not give pertinent dates, including estimated date Attach wellbore diagram of proposed completion of the completion of
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESSURE CHART IS ATTACH	CHANGE PLANS MULTIPLE COMPL OTHER: REQU Detected operations. (Clearly state all pertinent details, a brk). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST SING TO 500PSI FOR 30 MINUTES – OK TH NMOCD HED This Approval of Temporary Abandonment Expires	RILLING OPNS. PAND A NT JOB EST TA STATUS Attach wellbore diagram of proposed completion 12345 28/11 Ge and belief. I further certify that any pit or below.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESSURE CHART IS ATTACH	CHANGE PLANS MULTIPLE COMPL OTHER: REQU letted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD HED This Approval of Temporary Abandonment Expires above is true and complete to the best of my knowled	RILLING OPNS. PAND A NT JOB EST TA STATUS Attach wellbore diagram of proposed completion 12345 28/11 Ge and belief. I further certify that any pit or below.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WI PRESSURE CHART IS ATTACH I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a brk). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD This Approval of Temporary Abandon ment Expires above is true and complete to the best of my knowled closed according to NMOCD guidelines TITLE AGENT TITLE AGENT	RILLING OPNS. PAND A DEST TA STATUS X Indige stimated date Attach wellbore diagram of proposed completion of the complet
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WI PRESSURE CHART IS ATTACH I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name DEBBIE MCH	CHANGE PLANS MULTIPLE COMPL OTHER: REQU cleted operations. (Clearly state all pertinent details, a brk). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST ING TO 500PSI FOR 30 MINUTES – OK TH NMOCD HED This Approval of Temporary Abandorument Expires above is true and complete to the best of my knowled closed according to NMOCD guidelines , a general permit (11)	RILLING OPNS. PAND A DEST TA STATUS X Indige stimated date Attach wellbore diagram of proposed completion of the complet
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WI PRESSURE CHART IS ATTACH I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	CHANGE PLANS MULTIPLE COMPL OTHER: REQU letted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST SING TO 500PSI FOR 30 MINUTES – OK TH NMOCD HED This Approval of Temporary Abandonment Expires above is true and complete to the best of my knowled closed according to NMOCD guidelines , a general permit for the closed according to NMOCD guidelines , a general	RILLING OPNS. PAND A DEST TA STATUS X Ind give pertinent dates, including estimated date Attach wellbore diagram of proposed completion o
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESSURE CHART IS ATTACH I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name DEBBIE MCF For State Use Only APPROVED BY:	CHANGE PLANS MULTIPLE COMPL OTHER: REQU letted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST SING TO 500PSI FOR 30 MINUTES – OK TH NMOCD HED This Approval of Temporary Abandonment Expires above is true and complete to the best of my knowled closed according to NMOCD guidelines , a general permit for the closed according to NMOCD guidelines , a general	RILLING OPNS. PAND A DEST TA STATUS X Ind give pertinent dates, including estimated date Attach wellbore diagram of proposed completion o
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 9/27/2006 NOTIFY GARY WINK 9/28/2006 PRESSURE TEST CAS WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESS BY BUDDY HILL WITNESSURE CHART IS ATTACH I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name DEBBIE MCH For State Use Only	CHANGE PLANS MULTIPLE COMPL OTHER: REQU letted operations. (Clearly state all pertinent details, a ork). SEE RULE 1103. For Multiple Completions: A WITH NMOCD OF PENDING TA TEST SING TO 500PSI FOR 30 MINUTES – OK TH NMOCD HED This Approval of Temporary Abandonment Expires above is true and complete to the best of my knowled closed according to NMOCD guidelines , a general permit for the closed according to NMOCD guidelines , a general	RILLING OPNS. PAND A DEST TA STATUS X Indige stimated date Attach wellbore diagram of proposed completion of the complet

