

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

OCD-ARTESIA

FORM APPROVED
OMB NO. 1004-0135
EXPIRES: NOVEMBER 30, 2000

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APU) for such proposals

SUBMIT IN TRIPLICATE

1a. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other _____

2. Name of Operator
DEVON ENERGY PRODUCTION COMPANY, LP

3. Address and Telephone No.
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-8198

4. Location of Well (Report location clearly and in accordance with Federal requirements)*
**330 FNL & 1650 FEL
SEC 3 T18S R27E, UNIT B**

5. Lease Serial No.

NMLC065478B

6. If Indian, Allottee or Tribe Name

7. Unit or CA Agreement Name and No.

8. Well Name and No.

Falcon 3 B Federal 20

9. API Well No.

30-015-33193

10. Field and Pool, or Exploratory

Red Lake Glorieta-Yeso, NE

12. County or Parish 13. State

Eddy

NM


CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☒ Recomplete	☐ Other
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

Devon Energy Production Company, LP hereby requests approval to recomplete to the Queen-Grayburg-San Andres per the following procedure:

1. MIRU PU. TOH with rods and pump. ND tree, NU BOP. TOH with tubing.
2. Pick up RBP and RIH on tubing. Set RBP at +1- 2850'. TOH with tubing.
3. PU bailer and RIH on tubing. Dump 10 sand on top of RBP. TOH with tubing.
4. MIRU pump truck. Pressure test RBP and casing to 4000 psi.
5. RIH with 3-1/8" casing gun and perforate the San Andres w/ 40 holes from 1800'-2500'. TOH with wireline, RDMO same.
6. MIRU BJ. Acidize & frac San Andres perfs.
7. Open well up and flow back frac load until well dies.
9. RIH with SN, with nothing below it. Set SN +/-15' below bottom perf.
10. RIH with pump and rods. Hang well on and put well to test to battery.



14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Name **Norvella Adams**
Title **Sr. Staff Engineering Technician**

Date **9/13/2006**

(This space for Federal or State Office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any:

Note: To U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations to any matter within its jurisdiction.

*See Instruction on Reverse Side

APPROVED FOR 3 MONTH PERIOD
ENDING 12/19/06

