

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other
2. Name of Operator
Forest Oil Corporation
3. Address and Telephone No.
707 17th Street, Suite 3600, Denver, CO 80202
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit A, 660' FNL & 660' FEL. Sec: 15, T: 17S, R: 31E,



5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Skelly Unit

8. Well Name and No.

Skelly Unit No. 108

9. API Well No.

30-015-20406

10. Field and Pool, or Exploratory Area

Grayburg Jackson

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☐ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/21/06 MIRU Rig and cementing equipment

7/25/06 RU pulling unit, NDWH. NU BOP. WIH w/ tbg.. Tagged CICB @ 3281'. Load hole, Spot 125 sx cement @ 3281 to 2077'. Cug out cellar. (hole in surface casing.) Spot 125 sx. cement @ 2077 to 873'. POH w/ tbg. CWI. WOC over night.

7/26/06 Tagged plug @ 1125'. Circ. hole w/ 160 sx cement @ 1125' to surface. POH w/ tbg. ND BOP Dug out cellar. Cut off WH. Install Dry hole marker. Rig down equipment. Cut off anchors.

Denied - Reference NMOCD
Rule 19.15. 4. 202 B (3)

[Handwritten signature]

*Inspected by Phil
Hawkins on 8-22-06.
Pit not closed.*

14. I hereby certify that the foregoing is true and correct

Signed *AD Hight*

Title *SENIOR PRODUCTION FOREMAN*

Date *8/17/06*

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____ Date _____