

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 0-041-10015
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. LC-060978
7. Lease Name or Unit Agreement Name: Milnesand San Andres Unit
8. Well No. 125
9. Pool name or Wildcat Milnesand (San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Thompson, J. Cleo

3. Address of Operator
PO Box 12577, Odessa, TX 79768-2577

4. Well Location
Unit Letter **E** : **1980** feet from the **North** line and **660** feet from the **West** line
Section **7** Township **8S** Range **35E** NMPM County **/Roosevelt**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

9/13/06 MIRU pulling unit and cement equipment

9/14/06 RIH w/ tbg. tagged existing plug # 4520. Circ. hole w/ mud laden fluid. Spot 20 sx. plug @ 4122. POH. WOC SDFN.

9/15/06 Tagged plug @ 3805. Per. 4 1/2 scg. @ 2750. Set AD -1 Pkr. @ 2491. Pressured up to 1500 psi. POOH w/ pkr. RIH open ended to 2760. Spot 25 sx. cement POH, WOC SDFN.

9/18/06 Tagged plug @ 2376. Perf. 4 1/2 @ 2250. Set AD-1 pkr. @ 1966. Estab. rate 1.5 bbls/min @ 1000 psi. Sqz. 80 sx cmt. Closed well in WOC 4 hrs. Tagged plug @ 2142. Perf 4 1/2 csg. @ 440. ND BOP WH. SDFN.

9/19/06 Circulate 140 sx cmt. down 4 1/2 and up 8 5/8 to surface. WOC 3 hrs. Cut off Wellhead, Install Dry Hole Marker. rig down clean location.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John P. Hughes TITLE Foreman

DATE 10-4-06

Type or print name John P. Hughes
(This space for State use)

Telephone No. 432-550-8887

APPROVED BY Gary W. Wink TITLE _____ DATE _____

Conditions of approval, if any:

OC FIELD REPRESENTATIVE II/STAFF MANAGER

OCT 13 2006