

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-041-10043
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. LC-060978
7. Lease Name or Unit Agreement Name: MSU
8. Well No. 133
9. Pool name or Wildcat Milnesand (San Andres)
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Thompson, J. Cleo

3. Address of Operator
PO Box 12577, Odessa, TX 79768-2577 (432) 550-8887

4. Well Location
Unit Letter **G** : **1980** feet from the **North** line and **1980** feet from the **East** line
Section **7** Township **8S** Range **35E** NMPM County **Roosevelt**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

9/19/06 MIRU pulling unit and equipment.

9/20/06 Rig up Nipple up BOP. POH w/ 124 jts. tbg. Tbg. parted. RIH w/ work string tbg. Received verbal approval from E. L. Gonzales w/ OCD to spot 50 sx plug on top of fish. Pumped 50 sx. plug @ 3844. POH w/ 60 jts. Pressured up to 700 psi. WOC SDFN.

9/21/06 Tag plug @ 3597. POH w/ tbg. SDFN

9/25/06 Perf. 4 1/2 csg. @ 2750. RIH w/ 4 1/2 AD-1 packer. Set @ 2450. Pressured up to 1500 PSI. Held pressure. POH w. packer. GIH open ended. Spot 25 sx cement @ 2750. POH w/ 60 jts. WOC SDFN.

9/26/06 Tagged plug @ 2353. Perf. 4 1/2 csg. @ 2250. Set packer @ 1942. Sqz. 80 sx. cement plug. WOC Tag @ 2137. Perf csg. @ 477. ND BOP NU wellhead. Circ. 140 sx. cmt. down 4 1/2 and up to surface of 8 5/8. WOC. SDFN.

9/27/06 Set 10 sx. surface plug. Cut off wellhead. Install Dry Hole Marker. Clean location Rigged down.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John P. Hughes TITLE Foreman DATE 10-4-06

Type or print name John P. Hughes Telephone No. 432-530-8887

(This space for State use)

APPROVED BY Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE
Conditions of approval, if any

OCT 13 2006