

On _____
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.: 30 025 29352

5. Indicate Type of Lease
STATE ☒ FEE

6. State Oil & Gas Lease No.
B 9560

7. Lease Name or Unit Agreement Name
N.M. "BG" St. NCT-1

8. Well Number: 7

9. OGRID Number: 213190

10. Pool name or Wildcat
Saunders Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator: CrownQuest Operating, LLC

3. Address of Operator:
c/o P.O. Box 953, Midland, TX 79702

4. Well Location

Unit Letter I : 1980 feet from the South line and 660 feet from the East line

Section 14 Township 14S Range 33E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.): 4188'

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls: Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: _____

SUBSEQUENT REPORT OF:

REMEDIAL WORK _____ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A

CASING/CEMENT JOB

OTHER: _____

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Proposed T/A procedure:

Notify NMOCD district office.

Move in and rig up wireline. RIH w/4.75" gauge ring to 9810'.

Run in hole w/10,000 psi CIBP and set 9750'. Top of cement is circulated to surface.

Run in hole w/dump bailer and dump 20' of cement on top of CIBP.

Rig down wireline and rig up pump truck.

Load & test CIBP to 500 psi for 30 minutes.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE _____ TITLE Regulatory Agent DATE 10-9-06

Type or print name Ann E. Ritchie E-mail address: ann.ritchie@wtor.net Telephone No.: 432 684-6381

For State Use Only


APPROVED BY: Larry W. Wink TITLE OCD FIELD REPRESENTATIVE II/STAFF MANAGER DATE OCT 16 2006

Conditions of Approval (if any): _____

New Mexico BG State NCT-1#7

Current Status

10-9-06



WI
NRI

1
0.875