Submit 3 Copies To Appropriate District Office	State of New I			Form C-10
District I	Energy, Minerals and Na	itural Resources	WELL API NO.	May 27, 200
1625 N. French Dr., Hobbs, NM 87240 District II	OIL CONCEDUATE			.30192
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION 1220 South St. 1		5. Indicate Type of	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM		STATE 5	
District IV		107505	6. State Oil & Ga	
1220 S. St. Francis Dr., Santa Fe, NM 87505	_		0. State On & Ga	5 Lease NO.
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well X Gas Well 2. Name of Operator <u>BP America Production Comp</u> 3. Address of Operator <u>P.O. Box 1089 Eurice NM E</u> 4. Well Location Unit Letter <u>F</u> : <u>Section</u> 33 Pit or Below-grade Tank Application	Other Other	N OR PLUG BACK TO A -101) FOR SUCH 2 13 14 15 16 77 78 78 10 15 16 78 78 78 10 15 16 78 78 78 10 15 16 78 78 78 78 10 15 16 78 78 78 78 78 78 78 78 78 78 78 78 78	WASHINGTON 33 8. Well Number 9. OGRID Numbe 00 10. Pool name or ARTESIA CUEEN (1650 feet fro NMPM	10 r 778 Wildcat
Pit type Depth to Groundwater		resh water well Dia	tance from nearest sur	face water
Pit Liner Thickness: mil				
PR Liner I nickness: Ini	Delow-Grade Talk: Volu	areoois; Construction	on wraterial	
12. Check A NOTICE OF INT PERFORM REMEDIAL WORK		SUB REMEDIAL WORK	SEQUENT RE	
				ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB		
OTHER: Convert from Producer	to Injector X	OTHER:		[
 Describe proposed or completed of starting any proposed work). or recompletion. 				
		-2876'		
TD: 4000' PED: 3956'				
ID: 4000' PED: 3956' BP America Production Com this well from a production	pany has been granted ve	rbal permission by G		
BP America Production Com	pany has been granted ve	rbal permission by G		
BP America Production Com this well from a producti	pany has been granted ve on well to an injection	whal permission by G well as per the atta	iched wellwork pi	rocedure.
BP America Production Com this well from a production I hereby certify that the information a	pany has been granted ve on well to an injection bove is true and complete to the	well as per the atta	ached wellwork pa	rocedure.
BP America Production Com this well from a producti	pany has been granted ve on well to an injection bove is true and complete to the closed according to NMOCD guided	well as per the atta	ached wellwork pa	rocedure.

SIGNATURE		IIILE <u>Administrative</u>	DATE DATE U.11.00
Type or print name Vicki Owens		E-mail address:	owensvl2@bp.com Telephone No. 505.394.1650
For State Use Only NMOCD			
APPROVED BY	/01	TITLE	DATE
Conditions of Approval, if any:			



WORKOVER PROCEDURE

Well Information

Lease & Well No.	Field	Paykey No.	AFE No.	
Washington State "33" #10	Artesia	ZAXN18DRLG	X5-0040R	
Drilled	TD	PBD	Datum	
1999	4150'	4109'	GL 3673' KB 3680'	
Legal	S – T – R	County	State	
2267' FNL & 1650' FWL	33 – T17S – R28E	Eddy	New Mexico	
Prepared By	Date	Approved By	Date	
J. L. White	August 24, 2006			

Wellbore Data

Casing	Size	Weight	Grade	Depth	Cmt	тос
Surface	85/8"	24#	J55	530'	325	Surface
Intermediate	None					
Production	51⁄2"	17#	J55	4009'	250/560	Surface

Plugs: N/A

Tubing: 93 jts 2 7/8", 6.5 ppf, J-55, SN @ 3002', 1 – 4' Perf Sub, 3 mud joints, O/A 3105.26'

Packer: No TAC

Perfs: 1411'- 2084', 2364'- 2876'

History: Well drilled in March of 1999 as a Queen-Grayburg-San Andres producer.

Scope of Work: Convert well to injector.

PROCEDURE

1. Notify NMOCD prior to rigging up for witnessing. MIRUPU.

Hazard	Effect		Mitigation
Pulling Unit Equipment Fail	Possible injury or death to	>	Inspection of derrick
Objects falling from derrick	I personnel damage to equipment		Pre-job inspection of rig after RU.
Objects family from demok	or wellbore		Assure guy wire anchors have been tested

2. Unseat pump and pump sufficient 2% KCL water down tbg to put well on vacuum.

- 3. TOH with rods and pump, laying down. Send pump into pump shop for inspection.
- 4. NDWH and NUBOP with 2 7/8" x 2 3/8" variable rams. TOH with tubing.
- 5. P/U 4 ¾" workover bit and RIH to 3400'.
- 6. RIH with CIBP and set at 3400', dump bail 20' of cement on top of plug. TOH w/ 2 7/8", laying 2 7/8" down.
- 7. GIH w/ 5¹/₂" -17# Arrowset 1-X pkr (external nickel plated / IPC) with WL guide on btm and on/off tool w/ 1.78" profile on 23/8" 4.7# EUE 8R J-55 tbg w/ TK-70 IPC.

Hazard	Effect	Mitigati	on
Dropped pipe in hole	Possible damage to well	>	Pipe handling practices – slips, clamps, tongs, complete MU/BO before lifting as appropriate
Dropped pipe in derrick	Possible injury or death to	×	Line of fire practices
Dropped pipe in deflick	personnel, damage to equipment	>	Inspection of lifting equipment
Loss of well control	Possible injury to personnel,	>	Install pressure control – BOP's (change pipe rams)
	damage to wellbore, damage to environment	>	Have TIW valve on floor – capable of stabbing in 4 $\frac{1}{2}$ " LTC & full opening
		≻	Frequent BOP drills
Falling from height	Possible injury or death to	>	Use work platform
	personnel	×	100% tie-off

- Set pkr @ approx 1300' +/- and space out. Rig up slick line unit and set 1.78" plug in profile. Release from on/off tool and circulate packer fluid to backside – 2% KCL water with corrosion inhibitor. Latch back onto packer.
- 9. ND BOP and install WH equip. Pull 10K tension on pkr. Install 23/8" full opening NACE trimmed valve.
- 10. **Notify NMOCD 48 hours prior to test.** Test annulus to 600 psi and chart for 30 minutes for submitting to NMOCD. Pull profile plug with slick line.
- 11. RU to tbg and pump 50 BW to assure tbg is clear and capable of taking required rate. Limit pump pressure to 250 psi and rate to 2 BPM.
- 12. RD & RPU.
- 13. Complete *Well Handover Form* with a Production representative. Provide a copy for Production, fax copy to Midland office and send the original to the well file.

Washington State "33" #10 Artesia (Queen - Grayburg - San Andres)

.

API No. 30-015-30192

2267' FNL & 1650' FWL Sec 33 - T17S - R28E Eddy County, New Mexico

Proposed WB Design for WI Service

