State of New Mexico

Form C-103 Revised 1-1-89

Submit 3 copies to Appropriate District Office

Energy, Minerals and Natural Resources Department

DISTRICT I	OIL CONSERVATION DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088	30-025-36500	
DISTRICT II P.O. Box Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE ✓ FEE ☐	
DISTRICT III		6. State Oil / Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410	TOTO AND DEPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESEI	TICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO RVOIR. USE "APPLICATION FOR PERMI C-101) FOR SUCH PROPOSALS.	7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UNIT	
1. Type of Well: OIL GAS WELL WELL	OTHER		
Name of Operator CHEVRON U	ISA INC	8. Well No. 110	
Address of Operator 15 SMITH R	D, MIDLAND, TX 79705	Pool Name or Wildcat Vacuum Grayburg San Andres	
4. Well Location Unit Letter M: 653 Feet From The South Line and 20 Feet From The West Line			
Section 1 Township 18S Range 34E NMPM Lea COUNTY			
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3997'			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION	ON TO:	JBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OP	COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CASING TEST AND CEMEN	NT JOB	
OTHER:	OTHER: PLU	GBACK PORTION OF HORIZONTAL-RTP ✓	
8-30-06: TAG UP @ 4573'. TURN BIT Y 7/8" WS TO 1867'. 8-31-06: TIH W/F FISH FR 4578-4630'. 9-05-06: TIH W/BIT & 2 7/8" TBG. WO 2646. 9-06-06: TIH W/GAUGE RING TO 4351 ABOVE WINDOW @ 4269. 9-07-06: 9-11-06: RBP SET @ 4857'. PMP 28 B TBG TO 4188'. TIH W/RODS. 9-12-09-13-06: MOVE IN COIL TBG UNIT. 9-15-06: TIH W/SONIC HAMMER ON 010,300 GALS). SCALE INHIB SQZ: 3059-18-06: MIRU PU. RU SWAB. 9-19-06: TIH W/BIT, & TBG TO TAG T9-20-06: TIH W/PKR, SN, 136 JTS 2 7.9-22-06: TIH W/SWAB. REL PKR @ 4.9-25-06: PU SN, TBG, TAC. MOVE IN 9-26-06: PU GAS ANCHOR, PMP, & R	COIL TBG. ON WTR TO 4811. ON ACID FR 4820-4350, 4350- 5 GALS . OP OF OH RBP @ 4849. TIH W/BIT & TBG TO 1868'. SITE PLUG @ 4300'. BROKE CIRC. DISPL W/100 BFW. DRII /8" TBG TO 4243'. RU SWAB. TAG SAND LINE @ 3800. 243'. EOT @ 1875'.	TIH W/TBG & TAG @ 4578. WASH OVER G. TIH TO TAG @ 4606. TOH W/TOOL TO G. RUN BIT TO 4918. MILL @ 4886. PUT BIT JLL PLUG, TBG SUB, PERF SUB, 134 JTS 2 7/8" OWN. 4820. PMP SCALE INHIB FR 4820-4353. (ACID- LL OUT PLUG. PUSH DN TO 4606':255	
		1264	
I hereby certify that the information above is true and complete SIGNATURE SIGNATURE WASE SIGNATURE SIGNAT	TITLE Regulatory Specialist	DATE 10/3/2006	
TYPE OR PRINT NAME D	enise Pinkerton	Telephone No. 432-687-7375	
(This space for State Use)	, = (

APPROVED CONDITIONS OF APPROVAL, IF ANY: TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGETE OCCISOR 12006.