

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-37188
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	MITTIE WEATHERLY
8. Well No.	8
9. Pool Name or Wildcat	PENROSE SKELLY GRAYBURG
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3477' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH RD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>C</u> : <u>1140'</u> Feet From The <u>NORTH</u> Line and <u>1690'</u> Feet From The <u>WEST</u> Line Section <u>17</u> Township <u>21-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3477' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: C/O, ADD PERFS IN GRAYBURG & ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-24-06: MIRU KEY 331. UNSEAT PUMP.
7-25-06: PU 101 JTS 2 7/8" WS & TAG @ 3772'. POOH W/S/OE, UP TO 3585'. MOVE IN BLOW DOWN LINE.
7-26-06: DRILL W/S/OE, WASH PIPE, BMPR SUB, JARS, 101 JTS 2 7/8" WS. TAG @ 3772 TO 4122'. POH TO 3585.
7-27-06: PUMP 70 BBLS TO KILL WELL. TIH & TAG @ 3772. LATCH ON. JAR LOOSE. TIH W/BIT.
7-28-06: TAG @ 4131. WASH DN 4131 TO 4273, PBTD. POH TO 3529'.
7-31-06: PUMP KILL FLUID DN WELL. TAG @ 4265. NO FILL.
8-01-06: PERF 3656-64, 3676-80, 3706-09, 3724-32, 3784-90, 3954-58, 3962-68, 3974-80. TIH W/PPI TOOLS, 128 JTS WS TO 4008'. PUH TO 3645. SET PKR.
8-02-06: SPOT 23 BBLS ACID IN TBG. FLUSH TBG W/100 BBLS. TRY TO WASH OUT TRASH.
8-03-06: ACIDIZE 3656-3980' W/73000 GALS 15% HCL. SET PKR.
8-04-06: SWAB 4 RUNS.
8-07-06: SWAB. REL PKR.
8-08-06: TIH W/DRAIN VALVE, 2 JT CAVITY, DESANDER, SN, 16 JTS, TAC, PROD TBG. TIH W/1.750 INSERT PUMP & RODS. LOAD & TEST WELL. RIG DOWN. FINAL REPORT



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Pinkerton TITLE Regulatory Specialist DATE 8/14/2006
TYPE OR PRINT NAME Denise Pinkerton Telephone No. 432-687-7375

(This space for State Use)

APPROVED Chris Williams TITLE
CONDITIONS OF APPROVAL, IF ANY:

OC DISTRICT SUPERVISOR/GENERAL MANAGER
DATE

OCT 23 2006