

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

March 4, 2004

WELL API NO.
30-025-05562-00-00

5. Indicate Type of Lease
STATE ☒ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
JO

8. Well Number
2

9. OGRID Number
13046

10. Pool name or Wildcat
EUMONT QUEEN Y-SR-QN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
LANEXCO, INC.

3. Address of Operator
1105 WEST KANSAS, JAL, NM 88252

4. Well Location
Unit Letter M : 990 feet from the SOUTH line and 990 feet from the WEST line
Section 6 Township 19S Range 37E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3722

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng
feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

CASING TEST AND CEMENT JOB ☐ ABANDONMENT

OTHER: ☐

OTHER: Place back on production ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 8-8-06: Rig up pulling unit. 8-9-06: Shoot tubing slips free. Pulled out of hole with production tubing. Run in hole with bit and casing scraper. Tag at 3860'. Pulled out of hole with tubing and bit. Shut down overnight. 8-10-06: Run in hole with sn on 126 joints 2 3/8" tubing. SN at 3848'. Rig down pulling unit. 8-10-06: Lay flowline.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Charles Mann TITLE PRODUCTION SUPT. DATE 8-14-06

Type or print name CHARLES MANN E-mail address: Telephone No 505-395-3056

(This space for State use)

APPROVED BY Chris Williams TITLE DISTRICT SUPERVISOR/GENERAL MANAGER DATE OCT 23 2006
Conditions of approval, if any:

So No. 2

8/10/06

← 8 $\frac{3}{8}$ " 28# @ 1429' cmt'd w/ 650 SXS

126 lbs 2 $\frac{3}{8}$ " lbs

SN @ 3848'

CSG perfs: 3600-3625, 3636-3645, 3672-3688, 3700-3710,
3782-3824, 3832-3862.

← Top fl @ 3860'

← 5 $\frac{1}{2}$ " 14# @ 3884' cmt'd w/ 1260 SXS
Cmt Top @ 1636'