Form 3160-5 (August 1999)

Conditions of approval, if any

its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APROVED OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS Lease Serial No. 13 14 15 16 17 18 79 NMNM103263 Do not use this form for proposals to drill or to re-enter an If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE Unit or CA Agreement Name and No. O 1a. Type of Well Oil Well ✓ Gas Well Other 8 Well Name and No. Stock Tank 15 Fed Com 1 2. Name of Operator **DEVON ENERGY PRODUCTION COMPANY, LP** 9. API Well No. 30-005-63371 Address and Telephone No. Field and Pool, or Exploratory 20 North Broadway, Oklahoma City, OK 73102 Wildcat 4. Location of Well (Report location clearly and in accordance with Federal requirements) 12. County or Parish 13. State NM SEC 15 T15S R28E, Unit L Chaves NWSW 1980 FSL 660 FWL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deepen Production (Start/Resume) ✓ Notice of Intent Well Integrity Fracture Treat Reclamation Alter Casing Other Subsequent Report New Construction Recomplete Casing Repair Plug and Abandon Temporarily Abandon Change Plans Final Abandonment Notice ✓ Plug Back Water Disposal Convert to Injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) Devon Energy Production Company, LP respectfully requests approval to reenter and recomplete this well as follows. 1. MIRU PU. ND wellhead and NU BOP. Release packer at 8772' and TOOH with tubing. 2. MIRU. Wireline set CIBP at 8850'. Dump bail 35' cement on top of bridge plug. 3. RIH with casing gun and perforate Strawn at 8707-8711' with 4 SPF 0.42" EDH. RDMO. 4. TIH with tubing and packer and set packer at +/- 8700'. 5. Swab test. If Strawn perforations are unsuccessful, wireline set CIBP at 8700' and dump bail 35' cement on top of bridge plug. 6. RIH with guns and perforate the Wolfcamp at 7174-7184' with 4 SPF 0.42" EHD. RDMO. 7. TIH with tubing and packer and set packer at +/- 7150'. 8. Swab test well. MIRU and acidize well per recommendation. 9. Open well and flow back load. Swab if necessary. RDMO PU. reby certify that the foregoing is true and correct Name Norvella Adams Signed Sr. Staff Engineering Technician 10/6/2006 Date PETROLEUM ENGINEER OCT 10 2006 Approved by

Date

