Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office		
District I	Energy, Minerals and Natural Resources	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		30-025-37823
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Sunta 1 0, 1111 07505	
87505		35602
SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	_
PROPOSALS.)	TION FOR PERMIT" (FORM C-101) FOR SUCH	GEN MONTCALM 25 STATE
· · · · · · · · · · · · · · · · · · ·	as Well 🛛 Other	8. Well Number 1
2. Name of Operator		9. OGRID Number
-	RSON PETROLEUM LP	141928
	AWER 1416	10. Pool name or Wildcat
	R, TX 79550	10. I ool name of whiteat
4. Well Location		
Unit Letter H_: 198	30feet from theNORTHline and1	260 feet from the EAST line
Section 25	Township 17-S Range 33-E	NMPM County LEA
	11. Elevation (Show whether DR, RKB, RT, GR, e	tc.)
	4088' GR	
Pit or Below-grade Tank Application or	Closure 🗌	and a second second in the second
Pit type Synthetic Depth to Groundwater 1	50'_Distance from nearest fresh water well_1200'_ Distance	e from nearest surface water 50' to high mark of Playa
Lake Pit Liner Thickness: 12,000		
		bbls; Construction Material Synthetic
12. Check Ap	ppropriate Box to Indicate Nature of Notic	e, Report or Other Data
NOTICE OF INT		JBSEQUENT REPORT OF:
	PLUG AND ABANDON	<u> </u>
		DRILLING OPNS. 🗗 PAND A 🛛
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	ENT JOB
OTHER:	OTHER:	
13. Describe proposed or complete	ted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated dat
of starting any proposed work	x). SEE RULE 1103. For Multiple Completions:	Attach wellbore diagram of proposed completio
or recompletion.	1 1 1	
06/14/06 Moved in rigged up. Spude 06/15/06 431' - Drilled	ded well	
Giroulated 101 av to	. Ran 10 jts 13-3/8" 48# H40 casing, set @440'.	Cemented w/500 sx Premium Plus w/2% CaCl.
06/17/06 440' - Waiting on cement	o pit. Plug down @5:00 p.m. MST.	
06/18/06 1200' - Drilled & surveyed		
06/19/06 2160' - Drilled & surveyed		
06/20/06 2809' - Drilled & surveyed		0324.25
06/21/06 2849' – Drilled. Trip for Bi		John Contract St.
06/22/06 3191' - Drilled & surveyed	(12/4) & change BIA.	
06/22/06 3536' - Drilled & surveyed		000
06/24/06 3804' - Drilled.		A STICLE
06/25/06 4085' - Drilled & surveyed		li beviece∧
06/26/06 4381' - Drilled.		
06/27/06 4589' - Drilled & surveyed		
00/2//00 4589 - Dimed & surveyed		
I hereby certify that the information ab	ove is true and complete to the bast of my knowle	doe and hall of the second second second
grade tank has been/will be constructed or clo	ove is true and complete to the best of my knowle sed according to NMOCD guidelines 🖾, a general permit	age and belief. I further certify that any pit or below- \Box or an (attached) alternative OCD approximately \Box
	sed according to throed guidennes 🖂, a general per lint	□ or an (attached) alternative OCD-approved plan □.
SIGNATURE Later men	TITLE Enginee	DATE /0/3/06
		DAIE 10/3/00
Type or print name	E-mail address:	Telephone No.
For State Use Only		
11/ 4	akin '	MENERAL MANAGER ULI 2 5 2006
APPROVED BY: Mus	1) TITLE TITLE TITLE TIPERVISOR	DATE
	OC DISTRICT OUT	GENERAL MANAGER OCT 2 5 2006

7

Page 2

	- Drilled, surveyed & trip for bit #4 (12 ¹ / ₄ ")
06/29/06 4810'	- Drilled & started running casing.
06/30/06 4810'	- Ran 120 jts 9-5/8" 40# J55 & N80 LTC casing, set @4810'. Cemented w/1600 sx HLLPP + 5% salt & 1/4#/sk flocele.
	Tailed w/250 sx + 1% CaCl. Circulated 19 sx to the pit. Plug down @9:00 p.m. MST 06/29/06.
07/01/06 4810'	- NU & test BOP (waited on cement). Drilled cement.
07/02/06 5560'	- Drilled & surveyed. Bit #5 (8-3/4")
07/03/06 6337'	- Drilled & surveyed.
07/04/06 6990?	- Drilled & surveyed.
	- Drilled & surveyed.
	- Drilled & surveyed.
	- Drilled, surveyed & trip for bit #6 (8-3/4").
	- Drilled & surveyed.
	- Drilled, surveyed & trip for bit #7 (8-3/4")
07/13/06 10,870'	
-	- Drilled & surveyed.
07/15/06 11,700'	
07/16/06 11,970'	
	- Drilled &surveyed.
	- Drilled, trip, inspected drill collars & tested BOP.
	- Trip for bit #8 (8-3/4"), nipple up & test BOP, drilled.
07/20/06 12,500'	
	- Drilled, circulated waiting on loggers.
07/22/06 12,680'	
07/23/06 12,680'	
07/24/06 12,680'	- Rig repair. - Drilled, surveyed, circulated & laid down drill collars & drill pipe.
	- Finished laying down drill collars & drill pipe, rigged up casing crew & started running7" casing.
	- Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250
	- Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1 st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m.
07/27/06 12,680'	- Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1 st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2 nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m.
07/27/06 12,680'	- Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1 st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2 nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. – Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680'	 Ran 300 jts 7' 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760'	 Ran 300 jts 7' 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8").
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922'	 Ran 300 jts 7' 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8").
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162'	 Ran 300 jts 7' 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled. Drilled & surveyed.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled. Drilled & surveyed. Drilled, surveyed & trip for bit #11.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7' 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled & surveyed. Drilled & surveyed & trip for bit #11. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7' 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled. Drilled & surveyed & trip for bit #11. Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled. Drilled & surveyed & trip for bit #11. Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled. Drilled. Drilled, surveyed & trip for bit #11. Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled. Drilled, surveyed. Drilled, surveyed & trip for bit #11. Drilled. Drill
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jis 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled. Drilled, surveyed & trip for bit #11. Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jis 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 - 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled. Drilled, surveyed & trip for bit #11. Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drille
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drille
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H.SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill collars & pipe. Drilled & trip in hole for bit #10 (6-1/8"). Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill collars & pipe. Drilled. Drilled.
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H.SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled. <l< th=""></l<>
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H.SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill pipe. Drilled. <l< th=""></l<>
07/27/06 12,680' 07/28/06 12,680' 07/29/06 12,680' 07/30/06 12,760' 07/31/06 12,922' 08/01/06 13,162' 08/02/06 13,375' 08/03/06 13,462' 08/04/06 13,590'	 Ran 300 jts 7" 26# P110 LTC casing w/14 centralizers, set @12,630', DV tool @10,002'. Cemented 1st stage w/250 sx Interfill-H-SBM @11.9 ppg. Tailed w/100 sx Permian Basin Super H @13.2 ppg. Plug down @1:00 p.m. Cemented 2nd stage w/550 sx Interfill-H @11.9 ppg & tailed w/100 sx Premium @15.6 ppg. Plug down @7:30 p.m. Nipple up & tested BOP, changed out liners & swabs, jetted pits & picked up drill collars & pipe. Drilled cement, float & guide shoe (bit #9 – 6-1/8"). Circulated & picked up drill collars & pipe. Drilled. Drilled.

- 08/06/06 13,674' Cudd personnel arrived on location @5:30 a.m. At 7:00 a.m. observations revealed no gas escaping from under drilling floor, minimal condensate mist & vapors eliminating from discharge of separator. Assessed conditions at wellsite & formulated plan for condensate retrieval & cleanup. Ordered appropriate equipment to begin clean up operations. At 11:00 a.m. personnel were cleared to return to wellsite. Constructed retaining dikes to contain & collect condensate hauled & dispersed chat on location. Removed condensate on pits with vacuum trucks. At 6:00 p.m. location clean up was completed. Spotted Halliburton pump truck & began unloading kill mud. At 8:00 p.m. Halliburton began pumping kill mud. Pumped 660 bbls of 14 ppg drilling mud. By 9:20 p.m. well was effectively killed.
- 08/07/06 13,674' Circulated hole. Worked drill pipe, began to pull on drill pipe. At 7:30 a.m. drill pipe parted 16' down on second joint below kelly. Well stable. Released Cudd Pressure Control team. Began inspection of BOP's & ordered fishing tools. BOP inspection revealed cut out 3¹/₂" pipe rams, cut out & significantly damaged Hydril. Ordered new BOP stack & casing packer. Made up casing packer w/equalizing valve on drill pipe & set in 7" casing @39'. Removed damaged BOP stack. Made up & nipple up BOP stack.
- 08/08/06 13,674' Fishing & rig repair.
- 08/09/06 13,674' Fishing for drillpipe.
- 08/10/06 13,674' Fishing.
- 08/11/06 13,674' Fishing.
- 08/12/06 13,674' Fishing.
- 08/13/06 13,674' Fishing on drill collars. .
- 08/14/06 13,674' Fishing.
- 08/15/06 13,674' Fishing.
- 08/16/06 13,674' Fishing.
- 08/17/06 13,674' Fishing.
- 08/18/06 13,674' Fishing.
- 08/19/06 13,674' Fishing.
- 08/20/06 13,674' Top of fish @12,531'. Set CIBP @12,512'. Ran Scientific gyro survey from 12,510' to surface.
- 08/21/06 12,512' Trip to check kick off plug. .
- 08/22/06 12,512' Picked up Baker 3° Whipstock. Ran in the hole with gyro tool. Set whipstock @90° azimuth. Started milling.
- 08/23/06 12,512' Trip to inspect drill collars & window mill.
- 08/24/06 12,477' Milled on whipstock & casing from 12,471' 12,477'.
- 08/25/06 12,478' Milling window @5 fph.
- 08/26/06 12,478' Circulated hole. Trip out with mills.
- 08/27/06 12,486' Tripped in hole with 6-1/8" bit (#13). Drilled & milled through window from 12,480' to 12,484'.
- 08/28/06 12,480' Trip for directional tools.
- 08/29/06 12,535' Time drilled from 12,480' 12,493'. Slide drilled from 12,493' 12,504'. Rotary drill from 12,504' 12,535'.
- 08/30/06 12,691' Slide drilling & rotate from 12,539 to 12,575'.
- 08/31/06 12,862' Drilled & surveyed
- 09/01/06 13,004' Drilled, surveyed & trip out for bit & motor.
- 09/02/06 13,037' Trip for bit #14 (6-1/8") & drilled.
- 09/03/06 13,165' Drilled.
- 09/04/06 13,360' Drilled.
- 09/05/06 13,480' Drilled & surveyed.
- 09/06/06 13,650' Drilled & surveyed.
- 09/07/06 13,661' Drilled & trip in hole for bit & motor
- 09/08/06 13,673' Trip for bit #15 (6-1/8"). Drilled 12' & bit quit drilling.

- 09/09/06 13,673' Trip for bit #16 (6-1/8").
- 09/10/06 13,710' Drilled.
- 09/11/06 13,737' T.D. Drilled. Trip & laid down BHA to log
- 09/12/06 13,737' Logged to 13,512' & tool stopped. Ran in the hole with bit.
- 09/13/06 13,737' Worked tight hole. Rigged up logger's & logged to13,750' logger's depth.
- 09/14/06 13,737' Trip out of hole to pick up 5" liner
- 09/15/06 9/21/06 Waiting on draw works drum to repair rig
- 09/22/06 13,737' Finished rig repair & tripping in hole.
- 09/23/06 13,737' Trip, circulating & rig repair.
- 09/24/06 13,737' Trip to run liner
- 09/25/06 13,737' Rig repair
- 09/26/06 13,737' Rig repair & circulating on bottom w/liner. Ran 35 jts of 5" 18# P110 SJ2 liner with packer & hanger
- 09/27/06 13,737' Set liner 1' off bottom. Rigged up Halliburton. Pumped 20 bbls of weighted spacer. Pumped 150 sx of premium H + .6% Halad-344 + .3% Halad-413 + .3% CFR-3 + .3% HR-7. Displaced casing with 450 bbls of fresh water. Checked casing, had no flow. Pulled out of the hole & laid down drill pipe.
 - Top of liner @12,154'

Bottom of shoe @13,731'

09/28/06 Rig released @5:00 a.m. 09/28/06.