

Submit 3 Copies To Appropriate District Office  
District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. <b>30-041-20048</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>Orbit</b>		6. State Oil & Gas Lease No.
3. Address of Operator <b>720 W. Wilshire, Suite 115., Oklahoma City, OK 73116</b>		7. Lease Name or Unit Agreement Name: <b>State BA</b>
4. Well Location Unit Letter <b>A</b> : <b>1980</b> feet from the <b>N</b> line and <b>660</b> feet from the <b>E</b> line Section <b>34</b> Township <b>7S</b> Range <b>35E</b> NMPM County <b>Roosevelt</b>		8. Well No. <b>2</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc)		9. Pool name or Wildcat <b>Todd Upper San Andres</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103 For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation

7/10/06 MIRU.

7/11/06 Rig Up wireline. RIH with 5 1/2 gauge ring. Stopped at 2768 ft. POH. RIH with 1 11/16 sinker bars. Stopped at 2768 ft. POH with tools. SDFN.

7/12/06 RIH w/ knothed collar, perf. sub and 127 jts. 2 3/8 tubing. Tag solid. RU Pump circulate 30 bbls. mud laden fluid. Work tubing down 4100 feet. Circulate hole with mud laden fluid. Spot 25 sacks cement. POH w/ 60 jts tbgs. CWI, WOC, SDFN.

7/13/06 Tag plug at 3991 ft. PUH to 3549 ft. Load Hole, spot 25 sx cement at 3549 ft. to 3308 ft. POH w/ tubing. Perf. 5 1/2 casing at 1949 ft. POH with w. RIH w/ 5 1/2 AD-1 packer. Set at 1667 ft. estab. rate 2 barrels per minute. 900 PSI sqz 50 sacks cement CWI w/ 1100 PSI. WOC 4 hrs. Released packer. POH RIH open ended. Cement soft POH w/ 24 jts. CWI, WOC, SDFN.

7/14/06 Tag plug at 1831 ft. POH w/ tubing. Perf. 5 1/2 casing at 332 ft. Set packer at 30 ft. Estb. circulation. POH w/ packer. Install 5 1/2 by 2 inch swedge. Circulate 110 sacks cement. Down 5 1/2 casing up to surface of 8 5/8 casing. WOC 4 hours, dug out cellar, cut off well head, install dry hole marker. Rig down moved off.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bob Wilcox P.G. TITLE Geologist DATE 8/28/06  
Type or print name Bob Wilcox Telephone No. (505) 344-7373  
(This space for State use)

APPROVED BY Gary W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE OCT 26 2006  
Conditions of approval, if any:

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.