FORM APPROVED Form 3160-5 **UNITED STATES** OMB No. 1004-0135 Expires January 31, 2004 (September 2001) DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** Lease Serial No. LC058408B **SUNDRY NOTICES AND REPORTS ON WELLS** Do not use this form for proposals to drill or to re-enter an If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side N/A Type of Well Well Name and No. Oil Well Gas Well Other JOHNS B Name of Operator API Well No. CHISOS, LTD. 30-025-00698 3b. Phone No. (include area code) 1221 LAMAR SUITE 1600, HOUSTON TX 77010-1039 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNDESIGNATED QUEEN 11. County or Parish, State 660 FSL & 1980 FEL, Sec. 26, T17S-R32E LEA, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION ☐ Acidize Deepen ☐ Water Shut-Off Production (Start/Resume) Notice of Intent ☐ Well Integrity Fracture Treat Reclamation Alter Casing Casing Repair New Construction Recomplete Subsequent Report Change Plans Plug and Abandon XX Temporarily Abandon ☐ Final Abandonment Notice Convert to Injection Plug Back ☐ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days Attach the Bond under which the work with the pertained of provide the Bond to the while below the state of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Operation completed 6/4/03: RU Computalog electric line. Set CIBP @ 3500'. Dump bailed 35' cement on top of plug. RU Western hot oil truck. Filled casing with FSW. Fluid level at 1000'. Pressured up on casing, held 500 psi for 30 minutes. CHART ATTACHED. Wellbore diagram also attached. Request for extension for P&A for one year for evaluation of future utility as SWD UCD I hereby certify that the foregoing is true and correct Name (Printed/Typed) John Abeln 6/9/03 Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

GWW

which would entitle the applicant to conduct operations thereon.

ioric sco.) Me G. Lara

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

Approved by

(hisos L+d 6-4-03 TOLUS B #3 40584088 MI-PO-1000-8-96MIN

By. WATSON INC. St. WINTER
RECORDER/ 96 Min Clock
1000# Spring

CURRENT WELLBORE SCHEMATIC

ELEV = 3952'

