

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised June 10, 2003

WELL API NO.  
30-025-22796

5. Indicate Type of Lease  
STATE ☒ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Bunin

8. Well Number  
01

9. OGRID Number  
018687

10. Pool name or Wildcat  
Wantz Abo

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Ralph C. Bruton

3. Address of Operator

3500 Acoma, Hobbs, NM 88240

4. Well Location

Unit Letter D : 660 feet from the ~~660~~ N line and 660 feet from the W line

Section 18 Township 21S Range 3E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3461 KB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒


CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Clean location - test or replace anchors. Set CIBP at 7073', cap with 35' cement. Spot 100' plug: 4196' - 4296'.
2. Spot 100' plug: 1652' - 1752'.
3. Perf at 900' - squeeze to obtain 100' plug, 900' - 800', across 10 3/4" at 850'. Tag plug at 800'.
4. Spot surface plug - 60' to surface. Install dry hole marker. Clean location.

→ SPOT 100'  
PLUG F/400-300  
(FRESH WATER PLUG)  
Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ralph C. Bruton TITLE Owner/Operator DATE 11/6/06

Type or print name Ralph C. Bruton E-mail address: tgray@valornet.com Telephone No. 505-390-0366

(This space for State use)

APPROVED BY Hayden W. Wink TITLE \_\_\_\_\_ DATE NOV 17 2006  
Conditions of approval, if any: