	, OC	D-HOBBS			
Form 3160-5 (April 2004) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Serial No. LC- 058697B		
Do not use th abandoned w	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TR	 7. If Unit or CA/Agreement, Name and/or No. 8920003410 				
1. Type of Well	8. Well Name and No. MCA Unit #381				
2. Name of Operator ConocoPhilli	9. API Well No. 30-025-30348				
3a Address 3300 N. "A" Street, Bldg. 6 #24		3b. Phone No. (inclu 432-688-6884	de area code)	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Maljamar GB/SA 11. County or Parish, State		
Unit Letter K; 2,515 FSL & 1,720 FWL, Section 30, T-17-S, R-32-E			Lea, New Mexico		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION		T	YPE OF ACTION		
Notice of Intent	Acidize	Deepen	Production (Si	tart/Resume) Water Shut-Off Well Integrity	
	Casing Repair	Fracture Treat New Construction	Reclamation Recomplete	Other	
Subsequent Report	Change Plans	Plug and Abandon		bandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	I	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation. have been completed, and the operator has determined that the site is ready for final inspection.) See attached wellbore diagrams & proposed plugging procedure. SEEE ATTACHED FUK CONDITIONS OF APPROVAL					
14. I hereby certify that the fore Name (Printed/Typed) James F. Newma		Title	Engineer, Triple N St	ervices, Inc. 432-687-1994	
$\nabla \Lambda_{1}$	- K				
Signature	THIS SPACE FOR F				
		EDERAL OR	STATE OFFICE	+ TOPOVED	
Approved by			Title	Attende	
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.		the subject lease	Office	NOV 1 5 2006	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. (Instructions on page 2) FREDERICK WRIGHT					
GWW					



Top Salt @ 1,300' estimated

7

RKB @

DF @

GL@

== **z**3

PBTD @ 4110'

4400'

TD @

Base Salt @ 2,600' estimated

5-1/2" RBP @ 4110'

	Gravburg 5th Zone	
XX	4081 4083 4085 4087 Sqz'd w/150 sx	
	Grayburg 6th	Formation Tops;
zz	4172-4174 4178-4180	Rustler
==	4199-4201 4203-4216	Top Salt
2 2	4222-4240 4244-4256	Tansil
*	CIBP @ 4280'	Yates
	San Andres 7th	Seven Rivers
	4302-4308 - 14 holes	Queen
==	4315-4324 - 20 holes	Grayburg
	4328-4332 - 10 holes	Grayburg 6th
*		San Andres
69) 	7-7/8" Hole	
*	5-1/2" 17# K-55 @ 4400'	

Cmťd w/2500 sx Cl C & H, circ 335 sx TOC @ Surface

NOTE: Hit water flow at 4157' while drilling.

Formation Tops;	
Rustler	1290'
Top Salt	
Tansill	2490'
Yates	2653'
Seven Rivers	3076'
Queen	3540'
Grayburg	3720'
Grayburg 6th	4167'
San Andres	4306'



ConocoPhillips

Proposed Plugging Procedure

MCA Unit #381 API #30-025-30348 Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

Casings: 13³/₈" 61# casing @ 1,210' cmt'd w/ 320 sx, circulated 5¹/₂" 17# casing @ 4,400' cmt'd w/ 2,500 sx, circulated

- TA'd w/ RBP set @ 4,110' (set 08/09/88)
- Notify BLM & NMOCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- **1.** Set steel pit and flow down well as needed. MIRU plugging equipment. ND wellhead and NU 6" 5,000# hydraulic BOP.
- RIH w/ 2³/₈" workstring, tag PBTD. RU cementer & circulate hole w/ plugging mud. Pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 252' in 5¹/₂" 17# casing) 4,110 3,852'.
- 3. POOH w/ tubing to 2,600'. Load hole w/ mud and pump 25 sx C cmt (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 361' in 252' in 5½" 17# casing) 2,600 2,348'. base of salt plug
- 4. POOH w/ tubing to 1,300'. Load hole w/ mud and pump 40 sx C cmt (1.32 ft³/sk yield, 46.2 ft³ slurry volume, calculated fill 354' in 252' in 5½" 17# casing) 1,300 946'. WOC & TAG this plug no deeper than 1,160'. POOH w/ tubing. Top of salt & surface casing shoe plug
- RIH w/ four 1-11/16" link-jet perforating charges on wireline, and perforate four squeeze holes @ 50'. POOH w/ wireline. ND BOP, NU wellhead. Circulate 30 sx C cement (1.32 ft³/sk yield, 39.6 ft³ slurry volume, calculated fill 68' in 13%" 61# casing) 50' to surface. *surface plug*
- **6.** RDMO location. Clean steel pit & haul fluids to disposal. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

PROPOSED PLUGGED WELLBORE SKETCH

•

ConocoPhillips Company -- Permian Basin Business Unit



SUNDRY NOTICE SPECIAL STIPULATIONS

- 1. Approval is granted to plug this well with the following modifications to the proposed procedure:
- 2. The Top of salt and surface casing shoe plug should be set at 1550' for top of salt @ 1500'.
- 3. All of these plugs below the surface plug must be tagged.
- 4. The surface plug must be at least 100' and 25 sacks of cement.

<u>Engineering</u> <u>can be reached at 505-706-2779 for any variances that might be necessary.</u>

F Wright 11/15/06