

Form 3160-5
(April 2004)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT1021 N. French Drive
Hobbs, NM 88249FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator UHC New Mexico Corp

3a. Address
P.O. Box 450 Artesia, NM 88211-04503b. Phone No. (include area code)
505-746-4448

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter L 1980 feet from the South line and 660 from the North line
Sec 30 Township 7S Range 32E NMPM

5. Lease Serial No.

NM 15019

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Cone Federal #17

9. API Well No.

30-041-20498

10. Field and Pool, or Exploration Area
Tomahawk San Andres

11. County or Parish, State

Roosevelt N.M.

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|---|---|---|--|---|
| <input type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input checked="" type="checkbox"/> Other Remedial workover |
| | <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | |
| | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

11-13-06 Weld bell nipple on. RIH w/ notch collar bailer and tbg, tag @ 3400' could not make any hole. Turn on tbg. torks up when turning. POOH w/ tbg and bailer, standing back tbg. Secure well and call for spears. Shut down.

11-14-06 RIH w/ cable spear and tbg to a depth of 3400'. Tag fish, turn on tbg. Catch fish, POOH w/ tbg and spear, standing back tbg. Do not have fish. Start back in hole w/ spear and tbg. Secure well and shut down due to high winds.

11-15-06 RIH w/ cable spear and tbg, tag @ 3400'. Turn on tbg tork up, POOH w/ tbg and spear standing back tbg. Stand by for reverse unit and tools. Secure well and shut down.

11-16-06 Rig up reverse unit, start in hole w/ shoe, 1 jt wash pipe, 6 drill collars, and 97 jts 2 3/8 tbg. Tag @ 3486', pull up 2' ans start trying to circulate hole. Pump 600 bbls water. Start circ. hole, set down on plug. Start milling, circ. to surf. Secure well and shut down.

11-21-06 Comments: POOH w/ tbg & fishing tool. Laid down fish (1 - 8' 2 3/8 tbg, 1jt 2 3/8 tbg., S.N., 4' perf sub 10' mud jnt.) Laid down drill collars, jars and bumper sub. Pickup bailer w/ notch collar. RIH to 4175', tag up. Tried to bail out. Didn't make any hole. POOH w/ tbg & bailer. RIH w/ pkr and 90 jts tbg. Set pkr, tested csg to 500psi. Held OK. POOH w/ pkr RIH w/ S.N. and 124 jts tbg. ND BOP & secure well. Rig

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Ronnie Grado (rgrado@lothian.us)

Title Production Tech

Signature

Date

11-27-06

ACCEPTED FOR RECORD FOR FEDERAL OR STATE OFFICE USE

Approved by

DAVID R. GLASS

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 42 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW