Submit 3 Copies 10 Appropriate Dis Office District I	Biate of INEW MEXICO			Form C-103 May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.			
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-22004			
District III 1220 South St. Francis Dr. 1200 Rio Brazos Rd., Aztec, NM 87410			5. Indicate Type of Lease STATE X F	EE 🗆		
<u>District IV</u> Santa Fe, NM 87505			6. State Oil & Gas Lease I			
1220 S. St. Francis Dr., Santa Fe, NM _87505				OG-534		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name State WE K		
1. Type of Well: Oil Well X Gas Well Other				8. Well Number 1		
2. Name of Operator SDX Resources, Inc.				9. OGRID Number 020451		
3. Address of Operator				10. Pool name or Wildcat		
P. O. Box 5061, Midland, TX 79704				Osudo, Morrow, S. (20451) Osudo, Wolfcamp, S. (82280)		
4. Well Location						
Unit Letter F: 1980 feet from the North line and 1980 feet from the West line						
Section 15	Township	21S	Range 35E		County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3599' GR						
Pit or Below-grade Tank Application or Closure						
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water 30.31						
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
				SEQUENT REPORT		
			IK LING OPNS.□□ P AND	ANG CASING D		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			TJOB ∏\́∕⇔	_ <i>\%</i> /		
	-	_		- \\\^2\(\rac{2}{6}\(\rac{1}{6}\)	171312121 X	
OTHER:	completed operations (Clearly	state all	OTHER: Reque	st TA Status	1. 51 31 3 × 1	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompletion.						
11/7/06 MIRU	pulling unit. Bleed well do	wn.				
· ·	11/8/06 Load each tbg string w/30 bbls & csg w/60 bbls. Unflange well & set BOP. POOH w/ 103					
5 0	jts tbg. SDFD.					
	,					
	RU Slickline & RIH w/gauge ring, tag @ 11,678'. RIH w/1.7" bit.					
	· · · · · · · · · · · · · · · · · · ·					
	D Packer @ 11,740'. RIH w/tbg cutter & cut 2 3/8" tbg @ 10,780'. RD wireline & SDFD.					
11/16/06 TOOH w/342 + 21 jts tbg.						
	6 1/2" bit to clean.				•	
	eline & set CIBP @ 10,780)'. Dur	np 35' cement o	n top of CIBP.		
	NMOCD 24 hrs prior to pro		-	•		
11/22/06 Pressur	e test casing & plug to 560	psi for	30 minutes as p	er NMOCD requirement	nts.	
Chart a	ttached. Request TA status	S.		his Approval of Temp		
Abandonment Expires I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.						
SIGNATURE	Mell 'Lana		Engineer		E 11/28/06	
Nick Hood, XOG Operating, LLC, Agent for SDX Resources, Inc.						
Type or print name For State Use Only	٨	E-mail a	ddress: nhood@xo	goperating.com Telephone	No.	
. 1			ELI D REPRE	goperating.com Telephone SENTATIVE II/STAFF MAN	432-683-3171	
APPROVED BY: Conditions of Approval (if an	ywww.	TITLE_	OC LILLO MEI ME	TO TO THE	E 0 7 2006	
-	V				- - -	

