Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	Revised March 25, 1999 WELL API NO.
1625 N. French Dr., Hobbs, NM 87240 <u>District II</u> OIL CONSERVATION DIVISION	30-025-25727
District III 2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	STATE STATE STATE
2040 South Pacheco, Santa Fe, NM 87505	<ol> <li>State Oil &amp; Gas Lease No. B-1565</li> </ol>
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name:
1. Type of Well:     Oil Well       Oil Well     Gas Well   Other Injection	Central Vacuum Unit
2. Name of Operator	8. Well No.
Chevron U.S.A. Inc.	71
3. Address of Operator 15 Smith Road - Midland, Texas 79705	9. Pool name or Wildcat Vacuum Grayburg San Andres
4. Well Location	Vacuum GrayDurg San Antires
Unit Letter G 2630 feet from the North line and	2623 feet from the East line
Section 36 Township 17s Range 34E	NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc. 4003' GL	r.)
11. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI	NG OPNS. DPLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION	
OTHER: OTHER: Failure;	Packer 252627200 Repair Csg
<ul> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompilation.</li> <li>07-16-03 MIRU.</li> <li>07-17-03 Released 4-1/2" G-6 packer &amp; pulled tbg.</li> <li>07-18-03 Change out tbg string; TIH w/136 jts 2-3/8" duo-line tbg to found a leak in 4-1/2" csg just above slips &amp; packing on 8-07-21-03 TIH w/4-1/2" RBP &amp; 80 jts 2-3/8" tbg to 2498'. Set plug.</li> <li>07-22-03 ND BOP &amp; 4-1/2" csg head. Speared csg. Released spear &amp; i: 07-23-03 MIRU back hoe &amp; dug out around 8-5/8" csg down to 5'. Inspending out to 8' deep.</li> <li>07-24-03 Repaired 4-1/2" csg &amp; 8-5/8" csg. Installed new 8-5/8" head</li> </ul>	4322: Pre-test csg to 500# & 5/8" csg; was corroded internally.
in 8-5/8" head. Pulled into 4-1/2" csg & released spear. 07-25-03 Released RBP & TOH laying down 2-3/8" ws. PU new pkr & TIH	
Set pkr & pre-test csg to 500#; lost 135 psi in 15 min. Re (CONTINUED ON PAGE 2)	
I hereby certify that the information above is true and complete to the best of my knowledge and belief	
SIGNATURE Furra Rinner TITLE Regulatory Speci	alistDATE08-26-03
Type or print name Laura Skinner	Telephone No. 432-687-7355
(This space for State use) APPROVED BY Hay W. Winks OCIFIELD REPRESENTATION Conditions of approval, if any	IVE II/STAFF MANAGER AUG 2 9 2003

## CENTRAL VACUUM UNIT NO. 71 PAGE 2

- 07-28-03 TIH w/4-1/2" CIBP & pkr to 4316' w/ws. Set CIBP @ 4308'; test plug to 500 psi for 5 min (good). Release pkr.
- 07-29-03 Run csg inspection log from 4286' to surface.
- 07-30-03 TIH w/4-1/2" pkr to isolate hole in 4-1/2" csg. After isolating holes between 1079' to 1141' and from 475'-506', surface csg stayed static. Well flowing back red bed. TOH w/pkr. TIH w/2-3/8" tbg open ended to 1139'.
- 07-31-03 Spotted 50 sacks cement Class C from 1140'-821'. Installed swage & valve in 4-1/2" csg. Squeezed top holes from surface w/200 sacks Class C cement.
- 08-01-03 PU new bit, DC & tbg to tag cement @ 410'. Drld 253' cement to 663'.
- 08-04-03 Drld cement to 680'. TIH w/blade bit, DC, ws & drld cmt to 885'. Circulated clean.
- 08-05-03 Drld cement from 885' to 1150'. TIH w/4-1/2" csg scrapped & 2-3/8" tbg to 4305'.
- 08-06-03 PU new bit & TIH w/dc & ws to tag CIBP @ 4310'. Pushed plug & clean out to 4768' (PBTD). Circulated clean. TOH w/ws to 4265'.
- 08-07-03 TIH w/4-1/2" pkr, sn & tbg to 4301'. Test csg to 500#; leaked off; same leak.
- 08-08-03 Acidize perfs from 4343' to 4712' w/6000 gals 15% HCL. Release pkr & TOH w/ws & lay down pkr. TIH w/bit, dc & ws to tag @ 4382'.
- 08-11-03 Finished laying down ws & dc's. PU new pkr & 2-7/8" duo-line tbg & TIH to 4289'. Set pkr & got off pkr.
- 08-12-03 Cement in 2-7/8" duo-line tbg in 4-1/2" csg w/210 sacks Class C cement. Shear pump out plug @ 3400#; pumped 1000 gals HCL acid & flushed w/30 bbls FW. Flow well over nite.
- 08-13-03 TIH to set plug; seated plug & got off. Load & test 2-7/8" liner to 2500 psi four times; no test. TIH to retrieve plug to inspect (good). TIH w/new plug & sealted in profile nipple. Load & test liner to 2500 psi for 30 min (good). TIH to retrieve plug. Rig down. FINAL REPORT.

Original chart w/copy attached.

