## OCD-HOBBS

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

## BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5.	<ol><li>Lease Serial No.</li></ol>					
	NMNM90578					

			•
6.	If Indian	. Allottee or Tribe Name	

abandoned we	is form for proposals to ill. Use Form 3160-3 (APD	6. If Indian, Allottee or Tribe Name						
SÜBMIT IN TR	PLICATE - Other løstru	7. If Unit or CA/Agreement, Name and/or No.						
Oil Well Gas Well	1 O4			O THE NAME OF THE OWNER OWNER OF THE OWNER O				
2. Name of Operator	→ Oiner	8. Well Name and No.						
-	Consultants,	Reed Sanderson Unit 12						
3a. Address P.O. Box	1708	3b. Phone No. (include	area code)	30-025-04185				
Hobbs NM 882	241	505-392-69		10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec.	, T., R., M., or Survey Description	)	<del></del>	Eumont Yates Seven Ryrs On				
Section 3, T-20 SW SE 660' FSL	OS, R-36E 2310' FEL			11. County or Parish, State Lea County, NM				
12. CHECK AP	PROPRIATE BOX(ES) TO	D INDICATE NATU	RE OF NOTICE, R	EPORT, OR OTHER DATA				
TYPE OF SUBMISSION			PE OF ACTION					
	Acidize	Deepen	D 2 1 1 10					
Notice of Intent	Acting  Alter Casing	Fracture Treat	Production (Star					
· D.	Casing Repair	New Construction	Recomplete	☐ Well Integrity ☐ Other				
Subsequent Report	Change Plans	Plug and Abandon	Temporarily Ab	_ 51.01				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	andon				
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160.4 shall be filled once testing has been completed. Final Abandonment Notices shall be filled only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  1. MIRU. NUBOP.  2. TIH w/tbg OE to 3500'. Circ w/gelled brine mud.  3. Spot 25 sxs cement on CIBP @ 3500'. POOH.  4. Spot 25 sx cmt plug @ 2580'. Tag plug.  5. Spot 25 sx cmt plug @ 1375'.  6. RU wireline. Perf 5 ½" csg w/4 holes @368'.  7. Set 5½" cement retainer @318'.  8. Circ/squeeze 70 sxs cement into 5½" x 8 5/8" annulus.  9. Set 50' surface plug.  10. Cut off wellhead. Install dryhole marker.  11. Clean location.								
14. I hereby certify that the foregoin Name (Printed/Typed)	ng is true and correct							
Larry Scott		Title P	resident					
Signature Marred	Scott	Date 1	1/30/06	ACCEPTED FOR RECORD				
	THIS SPACE I	FOR FEDERAL OR S	TATE OFFICE USE					
Approved by		Т	itle	Date DEC 1 3 2006				
Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant to	al or equitable title to those righ	ce does not warrant or	ffice	WESLEY W. INGRAM				
Title 18 U.S.C. Section 1001 and T States any false, fictitious or fraudu	itle 43 U.S.C. Section 1212, make lent statements or representations	e it a crime for any person as to any matter within its i	knowingly and willfully urisdiction.	to make to any department or agency of the United				