

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

1. Type Of Well
☐ Oil Well ☐ Gas Well ☒ Other Disposal

2. Name Of Operator
Ray Westall Operating

3a. Address
P.O. Box 4 - Loco Hills, New Mexico 88255

4. Location Of Well
330' FSL E 1650' FEL Sec. 30 Twp 23S, Rng 34E UL D

5. Lease Serial Number:
NMNM 68821

6. If Indian, Allottee or Tribe Name:

7. If Unit or CA/Agreement, Name and /or No:

8. Well Name and Number:
Federal 30 #2

9. API Well Number:
30-025-29069

10. Field and Pool, or Exploratory Area:
SWD Delaware

11. County or Parrish, State
Lea County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice Of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Test	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	<u>pressure</u>
	<input type="checkbox"/> Convert To Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	<u>test well</u>

13. Describe Proposed Or Completed Operation (clearly state all pertinent details, including estimated start date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in multiple completion or re-completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

12/13/06 - changed out packer - set new packer @ 8109'
pressure tested - witnessed by Buddy
Hill-OCD Hobbs.

14. I hereby certify that the forgoing is true and correct
Name (printed/typed) Rene Mathews

Title Accounting
Date 12/14/06

Signature Rene Mathews

Approved by Wayne W. Wink
Conditions of approval, if any, are attached. Approval of this notice
does not warrant or certify that the applicant holds legal or equitable
title to those rights in the subject lease which would entitle the
applicant to conduct operations thereon.

OCD FIELD REPRESENTATIVE II/STAFF MANAGER

Office

Date DEC 26 2006

DEC 21 2006

Wesley W. Ingram
PETROLEUM ENGINEER

GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

Ray Westall

0-30-23-34

12-13-06
BR 222K B. H. H.

Federal 30
#2

30 MIN.

Hughes SERV.
1000#
60 MIN.

Last Cal. 1-25-05
D & L Meter.

