Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-38023 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE X FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH North Hobbs G/SA Unit PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other 516 9. OGRID Number 2. Name of Operator Occidental Permian Limited Partnership 157984 10. Pool name or Wildcat 3. Address of Operator P.O. Box 4294. Houston, TX 77210-4294 Hobbs: Grayburg - San Andres 4. Well Location Unit Letter 480 feet from the South line and 1275 feet from the West Section 13 Township 18-S Range 37-E **NMPM** County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3677' GR Pit or Below-grade Tank Application or Closure Pit type ___ ____ Depth to Groundwater __ __ Distance from nearest fresh water well ______ Distance from nearest surface water Pit Liner Thickness: Below-Grade Tank: Volume_ bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON 🔲 REMEDIAL WORK ALTERING CASING CHANGE PLANS TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB \square OTHER: OTHER: Run 5-1/2" Production Casing 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion 123456 or recompletion. See Attachment I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan TITLE Regulatory Compliance Analyst DATE 10/20/06 SIGNATURE_ Mark Stephens@oxy.com E-mail address: Mark Stephens Type or print name Telephone No. (713) 366-5158 For State Use Only

DATE

APPROVED BY

Conditions of Approval, if any:

10/17/06 -

10/19/06: Drill to TD at 4450'. RU casing crew and run 115 jts. 5-1/2", 15.5#, J-55, LT&C casing with 10 centralizers and set at 4450'. RU Halliburton and cement first stage with 250 sx. Premium Plus. Drop bomb, open DV tool, and circulate 131 sx. to surface. Circulate 4 hours between stages. Cement second stage with 550 sx. Interfill 'C' (lead) and 100 sx. Premium Plus (tail). Circulate 89 sx. to surface off second stage. ND BOP and set casing slips. Cut off casing and install tubinghead. Jet and clean pits and RD.

Release drilling rig at 4:30 p.m., 10/19/06.