Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Latural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-09258 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	0. 5 5 5 5 5 5
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	,,
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State A A/C 1
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 44
2. Name of Operator	9. OGRID Number
Petrohawk Operating	
3. Address of Operator	10. Pool name or Wildcat
1000 Louisiana, Suite 5600 Houston TX 77002	Jalmat, Tansill, Yates, 7rvrs (pro gas)
4. Well Location	
Unit Letter B: 660 feet from the N line and	1980 feet from theEline
Section 4 Township 23S Range 36E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3470' RKB	
Pit or Below-grade Tank Application ☐ or Closure ☐	
Pit type Depth to Groundwater Distance from nearest fresh water well Dis	stance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; C	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
1101102 01 11112111011	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TO A COMMENCE DE	
	ILLING OPNS. P AND A
TEMPORARILY ABANDON	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	IT JOB
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	IT JOB
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	ell and give pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	ell and give pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	oll Solution III Solution III Solution III Solution III Solution III III III III III III III III III I
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	oll Solution III Solution III Solution III Solution III Solution III III III III III III III III III I
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	ell and give pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	oll Solution III Solution III Solution III Solution III Solution III III III III III III III III III I
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657')	oll Solution III Solution III Solution III Solution III Solution III III III III III III III III III I
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657')	oll Solution III Solution III Solution III Solution III Solution III III III III III III III III III I
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes.	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness)	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness)	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness)	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness) 5. Request 5 year T/A status. This Approval of Temporary Abandonment Expires	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness) 5. Request 5 year T/A status. This Approval of Temporary Abandonment Expires	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion get and belief. I further certify that any pit or below-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness) 5. Request 5 year T/A status. This Approval of Temporary Abandonment Expires	and give pertinent dates, including estimated date ttach wellbore diagram of proposed completion get and belief. I further certify that any pit or below-
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness) 5. Request 5 year T/A status. This Approval of Temporary Abandonment Expires	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
PULL OR ALTER CASING	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 1-8-07
OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness) 5. Request 5 year T/A status. This Approval of Temporary / Abandonment Expires I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ SIGNATURE SIGNATURE Sisk E-mail address: jsisk@petrohawk.complete to the construction of the production Forematical	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 1-8-07
OTHER: OTHER: T/A we	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 1-8-07 Telephone No.505-394-2574
OTHER: OTHER: OTHER: OTHER: T/A we 13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1. Set CIBP @ 3580'. (Current Perfs: 3628'-3657') 2. Load casing w/ 2% KCL water. 3. Test casing 550# for 30 minutes. 4. Record test on chart. (Buddy Hill Witness) 5. Request 5 year T/A status. This Approval of Temporary Abandonment Expires I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit Constructed or print name of the production foremation and the production foremation and the production forematically and the production foremation and the production forematically and the production	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 1-8-07 Telephone No.505-394-2574
OTHER: OTHER: T/A we	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 1-8-07 Telephone No.505-394-2574

