Submit 3 Copies To Appropriate District	State of	New Mexico		Form C-103	
Office District I	Energy, Minerals and Natural Resources		May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-025-24164		
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III	1220 South St. Francis Dr.		STATE STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM			1149417		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Warrior State		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 2		
2. Name of Operator			9. OGRID Number		
Finley Resources, Inc.			180387		
3. Address of Operator			10. Pool name or Wildcat Eumont: Yates-7 Rivers-Queen		
1308 Lake Street, Ste. 200, Fort Worth, Texas 76102			Eumont: Yates-/ Rivers-Q	ueen	
4. Well Location					
Unit Letter 0 : 4545' feet from the North line and 1980' feet from the East line					
Section 2 Township 21S Range 35E NMPM County Lea					
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3598' KB					
Pit or Below-grade Tank Application or Closure					
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐					
TEMPORARILY ABANDON					
PULL OR ALTER CASING	MULTIPLE COMPL	☐ CASING/CEME	NT JOB		
OTHER:		OTHER:	MIT	\bowtie	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
CTL. Key circ pkr fluid down tbg & out csg. Start to pressure up csg & water started coming out around well head. Dig down to 8-5/8"					
well head. [5-1/2" csg had hole 1" above 8-5/8" well head, also 5-1/2" weld on slip collar leaking, came off while removing BOP.]					
NDBOP. Wait on welder. Welder repaired hole in 5-1/2" csg. Reweld 5-1/2" slip collar. NUWH. Called Buddy Hill w/ NMOCD about MIT test. He was unable to make it, but said go ahead w/ test. Key pump truck pressure up to 520# for 35 minutes. Draw straight line.					
Passed MIT. Flange up 8-5/8" well head. Cover up hole. Clean location. RDMO.					
i abbed iviti i i iange up o ovo wen	noun cover up nove cove		, as a second discountry of the second		
			18192	23.	
		, ,		1637	
This Appr	Valueting to lavor	12/22/11		12	
This Approval of Femporary /2/22/1/ Abandonment Expires					
			2111213 M 1 213	5 55 N	
				<u>. 87</u>	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. Of urther certify that any put or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.					
SIGNATURE 11	bunce	TITLE: Western District M	anagerDATE1/3/	06	
Type or print name For State Use Only	nce E-mail address:	jim.nance@finleyresources OC FIELD REFRESENTA	.com Telephone No. (817) ATIVE WATAFF MANA (817)	231-8727	
APPROVED BY:). Wink	TITLE	TATE		

