Office	State of New Mexi	co	Form C-103
District I	Energy, Minerals and Natura	Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELI	L API NO.
District II 1301 W Grand Ave. Artesia NM 88210	istrict II 801 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-01012
District III	1220 South St. Francis Dr.		licate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		\ <u>-</u>	STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Pe, INIVI 675	6. Sta	te Oil & Gas Lease No.
87505	6	22324253	
SUNDRY NOT	ICES AND REPORTS ON WELLS	6 - 7. Lea	ase Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OF PLUG	BEK TO A State I	
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	SALS TO DRILL OR TO DEEPEN OF PLUG CATION FOR PERMIT" (FORM C-101) FOR	SUCH NOT 8. WE	ell Number 1
1. Type of Well: Oil Well	Gas Well Other	Mil Mil	
2. Name of Operator	Cas wen Graner	200	RID Number
Paladin Energy Corp.	\io	16407	
3. Address of Operator	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		ool name or Wildcat
10290 Monroe Drive, Suite 301, D	allas, Texas 75229		y, Penn
4. Well Location		10168193	,,
	660 foot from the Court 1	1 ((0)	
			et from the <u>East</u> line
Section 34			MPM Lea County
	11. Elevation (Show whether DR, R	KB, RT, GR, etc.)	
Pit or Below-grade Tank Application 🔲 o	4258' GR		
			
Pit type <u>Steel tAnks</u> Depth to Ground	dwater_60'Distance from nearest fresh w	ater well_1/2 mile' Distar	ice from nearest surface water <u>playa-</u>
2000' Pit Liner Thickness:	mil Below-Grade Tank: Volume	bbls; Constructi	on MaterialSynthetic
12 Check	Appropriate Box to Indicate Nati	re of Notice Penert	or Other Date
12. CHECK F	appropriate Box to indicate Nati	ne of Nonce, Report	of Other Data
MOTICE OF IN	TENTION TO:	OUDOFOU	
NOTICE OF IN		SUBSECU	ENT REPORT OF
	!		ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON F	EMEDIAL WORK	☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING (☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK	PLUG AND ABANDON	EMEDIAL WORK	☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING (☐ ALTERING CASING ☐ DPNS.☐ P AND A ☐ ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB THER: Add Perforat	☐ ALTERING CASING ☐ DPNS.☐ P AND A ☐ ☐ ions
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or comp	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give port	DPNS. P AND A Discourse P AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THER: 13. Describe proposed or comp	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give port	☐ ALTERING CASING ☐ DPNS.☐ P AND A ☐ ☐ ions
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY ABANDON TO THE TEMPOR	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give port	DPNS. P AND A Discourse P AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THEM: 13. Describe proposed or compof starting any proposed we or recompletion. 11/8/2006 – 1/5/2007	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed by the performance of	ALTERING CASING DPNS. P AND A Discourse P AND A Description Descri
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THEM: 13. Describe proposed or compof starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent details. Attach well on from at 10,280-300', and the performent details.	Acidized with 1500 gallons 15% HCL.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THEM: 13. Describe proposed or compof starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no pro	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent details. Attach well on from at 10,280-300', at Eagley, Penn from 10.	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THEM: 13. Describe proposed or compof starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no pro	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent details. Attach well on from at 10,280-300', at Eagley, Penn from 10.	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THEM: 13. Describe proposed or compof starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no pro	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent details. Attach well on from at 10,280-300', at Eagley, Penn from 10.	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING THER: 13. Describe proposed or compof starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent details. Attach well on from at 10,280-300', at Eagley, Penn from 10.	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THEM: 13. Describe proposed or compof starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no pro	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent details. Attach well on from at 10,280-300', at Eagley, Penn from 10.	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING THER: 13. Describe proposed or compof starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent details. Attach well on from at 10,280-300', at Eagley, Penn from 10.	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMP	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give proposed to the proposed of th	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMP	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent of the performent at 10,280-300', at the Bagley, Penn from 10, at	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMP	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent of the performent at 10,280-300', at the Bagley, Penn from 10, at	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod Initial 24 hr. test on 1/5/2007: 5 Bo I hereby certify that the information grade tank has been/will be constructed or	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give proposed to the proposed of th	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMP	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING OF ASING/CEMENT JOB OTHER: Add Perforate tinent details, and give performed to the performent of the performent at 10,280-300', at the Bagley, Penn from 10, at	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING THER: 13. Describe proposed or compost of starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod Initial 24 hr. test on 1/5/2007: 5 Bo I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB OTHER: Add Perforationent details, and give potential performent of the Bagley, Penn from 10, 280-300°, And the Bagley, Penn from 10, and with current Penn potential permit or an (attention & Production & Production of the Bagley in	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod Initial 24 hr. test on 1/5/2007: 5 Both Interest of the information grade tank has been/will be constructed or SIGNATURE.	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB THER: Add Perforat inent details, and give per completions: Attach well on from at 10,280-300', attach well of my knowledge and become with current Penn per of my knowledge and become and permit or an (attach well) o	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'. Lief. I further certify that any pit or belowached) alternative OCD-approved plan DATE 1/17/2007 Telephone No. 214-654-0132
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING THER: 13. Describe proposed or compost of starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod Initial 24 hr. test on 1/5/2007: 5 Bo I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB THER: Add Perforat inent details, and give per completions: Attach well on from at 10,280-300', attach well of my knowledge and become with current Penn per of my knowledge and become and permit or an (attach well) o	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'. Lief. I further certify that any pit or belowached) alternative OCD-approved plan DATE 1/17/2007 Telephone No. 214-654-0132
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod Initial 24 hr. test on 1/5/2007: 5 Both Interest of the information grade tank has been/will be constructed or SIGNATURE.	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB THER: Add Perforat inent details, and give per completions: Attach well on from at 10,280-300', attach well of my knowledge and become with current Penn per of my knowledge and become and permit or an (attach well) o	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'. Lief. I further certify that any pit or belowached) alternative OCD-approved plan DATE 1/17/2007 Telephone No. 214-654-0132
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DULL OR ALTER CASING THER: 13. Describe proposed or compost starting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod Initial 24 hr. test on 1/5/2007: 5 Bo I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name David Plaisant For State Use Only APPROVED BY:	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB THER: Add Perforat inent details, and give per completions: Attach well on from at 10,280-300', attach well of my knowledge and become with current Penn per of my knowledge and become and permit or an (attach well) o	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'. Lief. I further certify that any pit or belowached) alternative OCD-approved plan DATE 1/17/2007 Telephone No. 214-654-0132
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: 13. Describe proposed or compostarting any proposed we or recompletion. 11/8/2006 – 1/5/2007 R/U Pulling Unit, N/D tree, N/U BO no break down, no flow back, no proback 25 bbls water, died. Install Rod Initial 24 hr. test on 1/5/2007: 5 Bo I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name David Plaisant For State Use Only	PLUG AND ABANDON	EMEDIAL WORK OMMENCE DRILLING O ASING/CEMENT JOB THER: Add Perforat inent details, and give per completions: Attach well on from at 10,280-300', attach well of my knowledge and become with current Penn per of my knowledge and become and permit or an (attach well) o	Acidized with 1500 gallons 15% HCL, 172-10,182'. Swab well in, flowed perforations from 8,682-9,034'. Lief. I further certify that any pit or belowached) alternative OCD-approved plan DATE 1/17/2007 Telephone No. 214-654-0132