UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-HOBBS

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

•			•
	Y	Carrial No.	

	1	- 0	122	2	31

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

LC-032233 (A)
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE -	7. If Unit or CA/Agreement, Name and/or N								
1. Type of Well X Oil Well Gas Well Other 2. Name of Operator Occidental Permian Limited Partner 3a. Address P.O. Box 4294, Houston, TX 77210- 4. Location of Well (Footage, Sec., T., R., M., or Survey I 1657' FSL & 620' FEL, Sec. 30, Let 1810' FSL & 622' FEL, Sec. 30, Let 12. CHECK APPROPRIATE TYPE OF SUBMISSION	8. Well Name and No. North Hobbs G/SA No. 546 Unit 9. API Well No. 30-025-36280 10. Field and Pool, or Exploratory Area Hobbs; Grayburg-San Andres 11. County or Parish, State Lea Co. NM								
X Notice of Intent	Acidize	Deepen	Production	(Start/Resume) Water Shut-Off					
Subsequent Report	Alter Casing	Fracture Treat	Reclamatio	n Well Integrity					
	Casing Repair	New Construction	Recomplete						
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporaril	Addictonal ray &					
	Convert to Injection	n Plug Back	Water Disp	Acid Treat					
following completion of the involved operations. If the operation results in a multiple completion or recompleted in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) 1) MI x RU. POOH with ESP production equipment. 2) Clean out to PBTD at 4366' x circulate well clean. 3) Run CNL/GR/CCL log from PBTD to +/- 3300'. 4) RU WL and perforate at 4098'-4108', 4176'-4179', & 4270'-4276' (2 JSPF, 19.5 gram select fire casing guns). 5) RIH with PPI tool and acidize 4098'-4276' with approx. 3000 gal. 15% PAD acid. 6) Swab or flow back spent acid. 7) RBIH with ESP production equipment. 8) ND BOP and RD x MO. Put well back on production and clean location.									
 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 		Title							
Mark Stephens	Regula:	tory Compli	ance Analyst						
Mark Stephen	Date 2/1/07		APPROVED						
	ERAL OR STATE OFFI	CE USE	Alli						
Approved by	Title		Date 7 2007						
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon									
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section States any false, fictitious or fraudulent statements or repr	n 1212, makes it a crime esentations as to any ma	for any person knowingly and ter within its jurisdiction.	d willfully to mal	PETROLEUM ER OFNIE BRied					