

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised June 10, 2003

WELL API NO. 30-025-26556

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name  
Lucky Larry

8. Well Number  
1

9. OGRID Number  
147179

10. Pool name or Wildcat  
Caprock; Mississippian, North

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Chesapeake Operating, Inc.

3. Address of Operator 2010 Rankin Hiway  
Midland, TX 79701

4. Well Location  
Unit Letter O : 660 feet from the South line and 1980 feet from the East line  
Section 5 Township 12S Range 32E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4404 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/02/06 MIRU Gray WL. RIH w/CIBP set @ 8,570', dump 4 sx cmt on top of plug RD Gray, load csg, test plug to 1000# 15 mins OK.

8/03/06 RIH, tag cmt @ 8540, displace hole w/gel mud. MIRU Gray WL, perforate squeeze holes 6170 - 6171, 4 spf, load csg, press. up to 1000#, wait 30 mins, no leak off.

8/06/06 Spot 30 sx cmt @ 6185', tag plug @ 5967'. POOH< MIRU WL, perf squeeze holes @ 3749 - 3750', 4 spf, jRDWL, RIH w/pkr, set @ 3250', break circ on 8 5/8", pump 60 sx cmt, squeeze 30 sx into 8 5/8" SI 2 hrs. rel. pkr. POOH. Tag plug @ 3400'. Spot 30 sx cmt to 1532' circ cmt to surface. RD BJ.

8/08/06 Install dry hole marker, clean location. Well is plugged and abandoned.

Approved as to **plugging** of the Well Bore.  
Liability under **bond** is retained until  
surface **restoration** is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Brenda Coffman TITLE Sr. Regulatory Comp. Specialist DATE 02/01/2007

Type or print name Brenda Coffman

E-mail address: bcoffman@chkenergy.com

Telephone No. (432)687-2992

(This space for State use)

APPROVED BY Hayden Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE FEB 15 2007

Conditions of approval, if any: