Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
District 1 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	May 27, 2004
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-20267 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	$\frac{1}{1} \frac{1}{5} \frac{1}$
PROPOSALS.)	8. Well Number and 2
1. Type of Well: Oil Well     Gas Well     OtherSWD       2. Name of Operator	9 OGRID Number
Chesapeake Operating Inc.	147179
3. Address of Operator 2010 Rankin Hwy Midland, TX 79701	10. Pool name or Wildcat SWD; Abo
4. Well Location	
Unit Letter I : 1980 feet from the South line and 660 feet from the East line	
Section 17 Township 17S Range 37E	NMPM CountyLea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3770 GR	
Pit or Below-grade Tank Application       or Closure         Pit type       Depth to Groundwater       Distance from nearest fresh water well	anaa fuom naavast surfaas watar
	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK D PLUG AND ABANDON X REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING  MULTIPLE COMPL CASING/CEMENT	Г ЈОВ 🗌
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	tach wendere diagram of proposed compretion
Chesapeake, respectfully, request permission to P&A this well per the attached procedure.	
	1314151617181930112232425 1314151617181930112232425 1016819904 10016819904 10016819904 10016819904 10016819904 1001232425 100123245 1001235 1001235 100125 10015 10015 10015 10015 10015 10015 10015 10015 10000
	2 <sup>13</sup>
THE O'L CONSERVATION DIVISION MUST	
	Sa * tob
BEGINNING OF PLUGGING OPERATIONS.	· · · · · · · · · · · · · · · · · · ·
	The second s
I hereby certify that the information above is true and complete to the best of my knowledge	e and belief. I further certify that any nit or below-
grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit	or an (attached) alternative OCD-approved plan [X].
SIGNATURE SIGNATURE TITLE Regulatory Tech.	DATE 01/29/2007
	ikenergy.com Telephone No.(432)687-2992
For State Use Only	
APPROVED BY: Law W. Wink TITLE MERINA	
Conditions of Approval (if thy):	
	FEB 1 5 2007

## Shipp 2-17 SWD Lea County, New Mexico Plugging Procedure

Date: January 24, 2007

Location: 1980' FNL & 660' FEL Sec. 17-T17S-R37E

Production Casing: 5 1/2" 15.5, 17 & 20# J-55 & N-80 3,451-8,945'

**PBTD/TD:** 9,196'/ 9,200'

Current Perfs: San Andres 5028-5059' Abo 9,122-9,200' (OH)

## **Recommended Procedure:**

- 1. MIRU PU. NDWH/NUBOP. Release packer & POH w/ tbg.
- 2. RIH w/ open ended tbg to 9,196'. Set 50 sxs bottom plug from 8,750-9,200'. Tag plug.
- 3. Pull tbg up to 6,500' and set a 25 sxs cement plug.
- 4. Pull tbg up to 5109' and set a 25 sxs cement plug.
- 5. Pull tbg up to 3629' and set a 25 sxs casing shoe plug. Tag plug.
- 6. Pull tbg up to 3202' and set a 25 sxs base of salt cement plug.
- 7. Pull tbg up to 2137' and set a 25 sxs top of salt cement plug.
- 8. Pull tbg up to 400'. Fill casing back to surface with cement. POH w/ tbg. Top off casing with cement.
- 9. RD and move off. Install dry hole marker and cut off dead men. Restore location.

## CURRENT WELLBORE SCHEMATIC CHESAPEAKE OPERATING INC.

PROPOSED P & A



encernomas