Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-20314
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B-1497
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	East Vacuum GB/SA Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Tract 2622
1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other	8. Well Number 086
2. Name of Operator	9. OGRID Number 217817
ConocoPhillips Company	
3. Address of Operator P. O. Box 51810, Midland, TX 79710-1810	10. Pool name or Wildcat
	Vacuum Grayburg/San Andres
4. Well Location	
Unit Letter C : 990 feet from the North line and 23	· · · · · · · · · · · · · · · · · · ·
Section 26 Township 17S Range 35E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3910' GR	
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDista	nce from nearest surface water
	nstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, I	Penart or Other Data
12. Check Appropriate Box to indicate Nature of Notice, I	Report of Other Data
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRIL	LING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB 🗌
OTHER: OTHER: Repair D	H failure & return to production
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att	ach wellbore diagram of proposed completion
or recompletion.	1819202122233
9/12/06 – 11/6/06 – Perform downhole work per the attached daily summary of work.	BENERS CON STAND
	Guoti La B
11/7/06 - Returned well to production - test on 11/9/06: 11 BO/D, 14 MCF/D, 850 BW/D.	an an an an
	in the second
	15342626
hereby certify that the information above is true and complete to the best of my knowledge	
grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] of	or an (attached) alternative OCD-approved plan [].
SIGNATURE	<u>t</u>
Type or print name Celeste Dale <u>Celeste Dale</u> E-mail address:	Telephone No. (432) 688-6884
For State Use Only Celeste Date Celeste Date Celeste Date Celeste Concordination Celester Celeste Concordination Celester Celeste	receptione 140. (452) 088-0884
\mathcal{H}	
APPROVED BY: Jan W. WMR OFFELD REPRESENTATIVE	II/STAFF MANAGERAFED
Conditions of Approval (if any):	

300252031400 LE Ground Elevation (ft) 3,910.00 Report Start Date La 9/11/2006 Di Time Log Ion (hrs) Report Start Date La 9/12/2006 Di 7000 Di Report Start Date La 9/12/2006 Di 7000 Di Report Start Date La 9/12/2006 Di Start Date La 9/13/2006 Di Start Date La 9/13/2006 Di Report Start Date La 9/13/2006 Di Corr A Pur (hrs) La Report Start Date La 9/14/2006 Di A A Pit La 9/14/2006 Di A A Pur (hrs) La	state/Province S EA NEW MEXICO S Original Spud Date Rig Release Date 9/25/1963 Initial Spud Date Rig Release Date 10/24/19 st 24hr Summary 10/24/19 Initial Spud Date Rig Release Date 10/24/19 st 24hr Summary Initial Spud Date Rig Release Date Initial Spud Date 9/25/1963 10/24/19 st 24hr Summary Initial Spud Date Rig Release Date Initial Spud Date 9/25/1963 10/24/19 ast 24hr Summary Initial Spud Date Rig Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI Initial Spud Date Spits 2 7/8" tbg to fish. SI ast 24hr Summary Spits 2 7/8" tbg to fish. SI Spits 2 1/2" TAC, & 53- 1" D Rods, & 117- 7 SION (Pump is stuck in bottom jt.) ast 24hr Summary Spite to location, conduct JSA, & Tailgate Spite to location, conduct JSA, & Tailgate ast 24hr Summary Spite to location, conduct JSA, & Tailgate Spite to location, conduct JSA, & Tailgate ast 24hr Summary Spite to location, conduct JSA, & Tailgate Spite to location, conduct JSA, & Tailgate ast 24hr Summary Spite to location, co	63 e Safety Meeting. MIRUPU. 1" ponys x 22', & 53-1" rods Il charging up. Attempt to ble Operation Safety Meeting, & Orientation ien another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON	N/S Dist (ft) 990.00 Attempt to unseat x 1325', & 14- 7/8 eed down pressure n. Attempt to blee ntered oil. RU swa ckle down csg. St	N/S Ref N Longitude (DMS) Trod pump, wit " rods x 350'.F e off csg. SION d down pressu ab line, swab t	thout success. Back RU Reverse Unit, att NE ure off csg(200psi), I bg down flowline.RI
300252031400 LE Sround Elevation (ft) 3,910.00 Report Start Date La 9/11/2006 Di Time Log Dur (hrs) Report Start Date La 9/12/2006 Di Start Date La 9/12/2006 Di Start Date La 9/12/2006 Di Start Date La 9/13/2006 Di Start Date La 9/13/2006 Di Start Date La 9/13/2006 Di Corr (hrs) Signal Report Start Date La 9/14/2006 Di Qur (hrs) La Signal La 9/14/2006 Di Dur (hrs) La	EA NEW MEXICO S Original Spud Date 9/25/1963 Rig Release Date 10/24/19 ast 24hr Summary rrive to location, conduct JSA, & Tailgate obds & TOH w/ 1 1/2" Polish rod x 26', 4- o kill well by pumping 10# down csg, we ast 24hr Summary rrive to location, conduct JSA, Tailgate S as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary rrive to location, conduct JSA & Tailgate & 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 SION (Pump is stuck in bottom jt.) ast 24hr Summary rrive to location, conduct JSA, & Tailgate & 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 SION (Pump is stuck in bottom jt.)	Sec. 26, T-17S, R-35E Latitude (DMS) 63 e Safety Meeting. MIRUPU. 1" ponys x 22', & 53-1" rods Il charging up. Attempt to ble Operation Safety Meeting, & Orientation ten another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON Operation e Safety Meeting. Kill well, tri /8" D Rods, 12- 1" Guided Ro	990.00 Attempt to unseat x 1325', & 14- 7/8 red down pressure n. Attempt to blee ntered oil. RU swa ckle down csg. St	N Longitude (DMS) t rod pump, witt " rods x 350'.F e off csg. SION d down pressu ab line, swab th prods/tbg ou	2,307.00 N thout success. Back RU Reverse Unit, att Ire off csg(200psi), I bg down flowline.RI ut of hole(147 jts 2 3
round Elevation (ft) 3,910.00 eport Start Date 9/11/2006 Dur (hrs) eport Start Date 9/12/2006 Gamma Start Date 9/12/2006 Dur (hrs) eport Start Date 9/13/2006 Crime Log Dur (hrs) Eport Start Date 9/13/2006 Crime Log Dur (hrs) Eport Start Date 9/14/2006 Crime Log Dur (hrs) Eport Start Date 9/14/2006 Crime Log Dur (hrs)	Original Spud Date 9/25/1963 Rig Release Date 10/24/19 ast 24hr Summary rrive to location, conduct JSA, & Tailgate bds & TOH w/ 1 1/2" Polish rod x 26', 4- b kill well by pumping 10# down csg, we ast 24hr Summary Prive to location, conduct JSA, Tailgate S as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary Prive to location, conduct JSA & Tailgate & 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 SION (Pump is stuck in bottom jt.) ast 24hr Summary Prive to location, conduct JSA, & Tailgate & 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 SION (Pump is stuck in bottom jt.)	Latitude (DMS) 63 e Safety Meeting. MIRUPU. 1" ponys x 22', & 53-1" rods Il charging up. Attempt to ble Operation Safety Meeting, & Orientation ten another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON Operation	Attempt to unseat x 1325', & 14- 7/8 red down pressure n. Attempt to blee ntered oil. RU swa	t rod pump, wit " rods x 350',F e off csg. SION d down pressu ab line, swab t	thout success. Back RU Reverse Unit, att NE ure off csg(200psi), I bg down flowline.RI
3,910.00 eport Start Date 9/11/2006 Di ro to Fime Log Dur (hrs) eport Start Date 9/12/2006 Di Sv Fime Log Dur (hrs) eport Start Date 9/13/2006 D Fime Log Dur (hrs) eport Start Date 9/13/2006 C Fime Log Dur (hrs) Eport Start Date 9/14/2006 C Fime Log Dur (hrs) Eport Start Date Start	9/25/1963 10/24/19 ast 24hr Summary brive to location, conduct JSA, & Tailgate ods & TOH w/ 1 1/2" Polish rod x 26', 4- o kill well by pumping 10# down csg, we ast 24hr Summary Drive to location, conduct JSA, Tailgate S as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary Drive to location, conduct JSA & Tailgate S 1/2" TAC, & 53- 1" D Rods, & 117- 7 BION (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgate S 1/2" TAC, LD bit & scraper. Pic	63 e Safety Meeting. MIRUPU. 1" ponys x 22', & 53-1" rods ill charging up. Attempt to ble <i>Operation</i> Safety Meeting, & Orientation ten another 40 to kill well. to f hole w/ 2 7/8" tbg, encou ON <i>Operation</i> e Safety Meeting. Kill well, tri 8" D Rods, 12- 1" Guided Ro	x 1325', & 14- 7/8 eed down pressure n. Attempt to blee ntered oil. RU swa ckle down csg. St	t rod pump, wit " rods x 350'.F e off csg. SION d down pressu ab line, swab t	thout success. Back RU Reverse Unit, att NE ure off csg(200psi), I bg down flowline.RI
9/11/2006 Dur ro to ro to "ime Log La Dur (hrs)	ast 24hr Summary Drive to location, conduct JSA, & Tailgate obs & TOH w/ 1 1/2" Polish rod x 26', 4- o kill well by pumping 10# down csg, we ast 24hr Summary Drive to location, conduct JSA, Tailgate St as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary Drive to location, conduct JSA & Tailgate S 1/2" TAC, & 53-1" D Rods, & 117-7 SION (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgate S 1/2" TAC, LD bit & scraper. Pic	1" ponys x 22', & 53-1" rods Il charging up. Attempt to ble Operation Safety Meeting, & Orientation en another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON Operation	x 1325', & 14- 7/8 eed down pressure n. Attempt to blee ntered oil. RU swa ckle down csg. St	" rods x 350'.F e off csg. SION d down pressu ab line, swab t	RU Reverse Unit, att NE ure off csg(200psi), I bg down flowline.RI
9/11/2006 Dur ro to ro to "ime Log La Dur (hrs)	ast 24hr Summary Drive to location, conduct JSA, & Tailgate obs & TOH w/ 1 1/2" Polish rod x 26', 4- o kill well by pumping 10# down csg, we ast 24hr Summary Drive to location, conduct JSA, Tailgate St as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary Drive to location, conduct JSA & Tailgate S 1/2" TAC, & 53-1" D Rods, & 117-7 SION (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgate S 1/2" TAC, LD bit & scraper. Pic	1" ponys x 22', & 53-1" rods Il charging up. Attempt to ble Operation Safety Meeting, & Orientation en another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON Operation	x 1325', & 14- 7/8 eed down pressure n. Attempt to blee ntered oil. RU swa ckle down csg. St	" rods x 350'.F e off csg. SION d down pressu ab line, swab t	RU Reverse Unit, att NE ure off csg(200psi), I bg down flowline.RI
ro to to ime Log Dur (hrs) aport Start Date 9/12/2006 Di ga 9/12/2006 Di ga via start Date 9/13/2006 Di fime Log Dur (hrs) aport Start Date 9/14/2006 Di fime Log Dur (hrs) aport Start Date 9/14/2006 Di fime Log Dur (hrs) aport Start Date Di fime Log Dur (hrs)	bds & TOH w/ 1 1/2" Polish rod x 26', 4- b kill well by pumping 10# down csg, we ast 24hr Summary Drive to location, conduct JSA, Tailgate 3 as & oil. Pump 40 bbl 10# down csg, tr IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary Drive to location, conduct JSA & Tailgate 5 1/2" TAC, & 53-1" D Rods, & 117-7 BION (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgate st 24hr Summary Drive to location, conduct JSA, & Tailgate Ast 24hr Summary Drive to location, conduct JSA, & Tailgate 604'(44' fill). TOH, LD bit & scraper. Pic	1" ponys x 22', & 53-1" rods Il charging up. Attempt to ble Operation Safety Meeting, & Orientation en another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON Operation	x 1325', & 14- 7/8 eed down pressure n. Attempt to blee ntered oil. RU swa ckle down csg. St	" rods x 350'.F e off csg. SION d down pressu ab line, swab t	RU Reverse Unit, att NE ure off csg(200psi), I bg down flowline.RI
Dur (hrs) aport Start Date 9/12/2006 Dr 9/12/2006 Dr 9/12/2006 Dr 9/12/2006 Dr 100 Dur (hrs) aport Start Date 9/13/2006 Dr 100 Dur (hrs) aport Start Date 9/14/2006 Dr 100 C 100 Dur (hrs) Dur (hrs) Dr 100 D	Drive to location, conduct JSA, Tailgate 3 as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary Drive to location, conduct JSA & Tailgate & 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 iION (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgate 604'(44' fill). TOH, LD bit & scraper. Pic	Safety Meeting, & Orientation ten another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON Operation e Safety Meeting. Kill well, tri /8" D Rods,12- 1" Guided Ro	ntered oil. RU swa	ab line, swab t	bg down flowline.Rl
aport Start Date 9/12/2006 9/12/2006 9/12/2006 9/13/2006 9/13/2006 5 Time Log Dur (hrs) aport Start Date 9/14/2006 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1	Drive to location, conduct JSA, Tailgate 3 as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary Drive to location, conduct JSA & Tailgate & 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 iION (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgate 604'(44' fill). TOH, LD bit & scraper. Pic	Safety Meeting, & Orientation ten another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON Operation e Safety Meeting. Kill well, tri /8" D Rods,12- 1" Guided Ro	ntered oil. RU swa	ab line, swab t	bg down flowline.Rl
9/12/2006 Di ga N Sv "ime Log Dur (hrs) eport Start Date La 9/13/2006 D & Sime Log Dur (hrs) eport Start Date La 9/14/2006 D 44 pr Lc "ime Log Dur (hrs)	Drive to location, conduct JSA, Tailgate 3 as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary Drive to location, conduct JSA & Tailgate & 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 iION (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgate 604'(44' fill). TOH, LD bit & scraper. Pic	en another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON <i>Operation</i> e Safety Meeting. Kill well, tri /8" D Rods,12- 1" Guided Ro	ntered oil. RU swa	ab line, swab t	bg down flowline.Rl
Ga N Sv Dur (hrs) eport Start Date 9/13/2006 D Srime Log Dur (hrs) eport Start Date 9/14/2006 D Cime Log Dur (hrs)	as & oil. Pump 40 bbl 10# down csg, th IDWH, NUBOP. Release TAC, Start out wab. TOH w/ 58 jts 2 7/8" tbg to fish. SI ast 24hr Summary rive to location, conduct JSA & Tailgate & 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 SION (Pump is stuck in bottom jt.) ast 24hr Summary rive to location, conduct JSA, & Tailgat 604'(44' fill). TOH, LD bit & scraper. Pic	en another 40 to kill well. t of hole w/ 2 7/8" tbg, encou ON <i>Operation</i> e Safety Meeting. Kill well, tri /8" D Rods,12- 1" Guided Ro	ntered oil. RU swa	ab line, swab t	bg down flowline.Rl
Dur (hrs)	Prive to location, conduct JSA & Tailgate 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 HON (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgat 604'(44' fill). TOH, LD bit & scraper. Pic	s Safety Meeting. Kill well, tri /8" D Rods,12- 1" Guided Ro	ckle down csg. St ds & Rod pump.	rip rods/tbg ou Had to saw off	it of hole(147 jts 2 3 f 4 rods to get out of
eport Start Date La 9/13/2006 D & S Fime Log Dur (hrs) eport Start Date La 9/14/2006 D 4(pr Lc Fime Log Dur (hrs)	Prive to location, conduct JSA & Tailgate 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 HON (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgat 604'(44' fill). TOH, LD bit & scraper. Pic	s Safety Meeting. Kill well, tri /8" D Rods,12- 1" Guided Ro	ckle down csg. St ds & Rod pump.	rip rods/tbg ou Had to saw off	It of hole(147 jts 2 3 f 4 rods to get out of
9/13/2006 D & S Fime Log Dur (hrs) eport Start Date La 9/14/2006 D 44 pr Lc Fime Log Dur (hrs)	Prive to location, conduct JSA & Tailgate 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 HON (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgat 604'(44' fill). TOH, LD bit & scraper. Pic	/8" D Rods, 12- 1" Guided Ro	ckle down csg. St ods & Rod pump.	rip rods/tbg ou Had to saw off	It of hole(147 jts 2 3 f 4 rods to get out of
9/13/2006 D & S Fime Log Dur (hrs) teport Start Date La 9/14/2006 D 44 fime Log Dur (hrs)	Prive to location, conduct JSA & Tailgate 5 1/2" TAC, & 53- 1" D Rods, & 117- 7 HON (Pump is stuck in bottom jt.) ast 24hr Summary Drive to location, conduct JSA, & Tailgat 604'(44' fill). TOH, LD bit & scraper. Pic	/8" D Rods, 12- 1" Guided Ro	ckle down csg. St ods & Rod pump.	rip rods/tbg ou Had to saw off	It of hole(147 jts 2 3 f 4 rods to get out of
Dur (hrs) eport Start Date La 9/14/2006 D 4(t pr Lc Fime Log Dur (hrs)	Prive to location, conduct JSA, & Tailgat 604'(44' fill). TOH, LD bit & scraper. Pic	Operation			
9/14/2006 D 46 pr Lc Fime Log Dur (hrs)	Prive to location, conduct JSA, & Tailgat 604'(44' fill). TOH, LD bit & scraper. Pic				
9/14/2006 D 46 pr Lc Time Log Dur (hrs)	Prive to location, conduct JSA, & Tailgat 604'(44' fill). TOH, LD bit & scraper. Pic				
Dur (hrs)	ost 80 psi in 30 min. SION		Packer. Set RBP	@ 4353', Pack	ker @ 4298'. Bleed
Dur (hrs)				······································	
		Operation			·······
eport Start Date La	ast 24hr Summary				
(2 Pi tb	Drive to location, conduct, JSA, TSM, & 20psi). Had some oil & gas flow back. P 'ump 20 bbl 10# down int. csg, apparer og out of derrick. Reverse circ. 105 bbl lotify MSO of surf line to pit venting. SIC	ressure test 5 1/2" csg to 50 htly communicating w/ surf cs 10# down 5 1/2" back up thro	0 psi for 30 min(lo sg. TOH w/ & LD 1	ost 10psi). 10 jts 2 7/8" tbj	g, RIH w/ 5 stands 2 ack. J&M initiate on
Time Log		Operation			
Dur (nrs)	<u> </u>	Operation	15 - 1 ^{9 - 1} - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		
9/18/2006 D lu 17	ast 24hr Summary Drive to location, conduct JSA, TSM, Go Jbricator. RIH & run CBL from 4000' to s 700'(Gamma spike) & 130'Travel time o // 2 7/8" oet(146 Jts). SION	surface. TOC behind 5 1/2" o	sg is @ 2150'. Po	ossible suspicio	ous spots are at
Time Log					
Dur (hrs)		Operation		,	
9/19/2006 D gr up	ast 24hr Summary Drive to location, conduct JSA, Tailgate : reen, 9- red band). RD scanning eqpt. F p & RIH w/ 5 1/2" packer, 2 7/8" SN, & a ntermediate csg. Pressure up to 500 psi	RUWL, RIH & shoot 2 holes approx 2000' of 2 7/8" tbg. S	in 5 1/2" @ 2110' et packer @ 2000	(csg collar @ 2	2098'). CƠH, RDŴI
	· · ·				
Dur (hrs)		Operation			
9/20/2006 D pa ap 20	ast 24hr Summary Drive to location, conduct JSA, Tailgate S acker, testing tbg to 5000 psi. All tbg te pparent corrosion visible, had some oily 000'. Pressure down tbg to 500 psi, the Pump 30 bbl 10# down int. Repeat pump	sted good.RD testers. RU hy / dirt). Send debris to CRI. C n surge pressure off in atterr	drovac service & over void w/ blow	clean out arou sand. TOH wi	ind wellhead. (No ith packer to and set
		· · · · · · · · · · · · · · · · · · ·	······		·····

EAST VACUU	M GB-SA UN	IT 2622-086			DOWNHOLE FAI	
			Daily 9	Summary		mersible Pump)
API / UWI	County	State/Province		gal Location	N/S Dist (ft) N/S Ref	E/W Dist (ft) E/W Ref
300252031400	LEA	NEW MEXICO	Sec. 26	, T-17S, R-35E	990.00 N	2,307.00 W
Ground Elevation (ft) 3.910.00	Original Spud (9/25/1		Date 1/1963	Latitude (DMS)	Longitude (D	(MS)
3,510.00	5/20/	10/2-	1000			
Time Log						
Dur (hrs)				Operation		
Report Start Date	Last 24hr Summary					
9/21/2006	Drive to location then reset pkr @ Tie onto interme trickle(1/10 bpm	2000'. Alternately paid ate csg, close surfa	ressure & s ace csg val tbg via sho	surge off pressure lve, then pump 50	gram. Release packer, displace on tbg. bbl fresh water @ 2bpm w/ 200 e back onto tbg & pressure to 50	psi.Had very small
Time Log				0	········	
Dur (hrs)				Operation		<u> </u>
Report Start Date 9/22/2006	Spot 4 bbl 15% Pressure up on	acid across shot hole tbg to 500 psi. Had 1	e @ 2110 [°] . /10bpm flo	TUH w/ pkr & set a w up intermediate	gram. TOH w/ tbg & packer. TIH @ 1830'. Release pkr, pressure down tb prevented further well work. SIO	g against 5 1/2" to 500 psi,
Time Log Dur (hrs)		······		Operation		
Report Start Date 9/25/2006	RIH to shoot 4 h RIH w/ WL & sh	oles(.41"). COH w/ V oot 4 holes @ 1680'.	VL. Tie ont Tie onto	o & pressure up to	am, & Orientation. TOH w/ tbg & 500 psi on 5 1/2" csg without co om return up int). No significant i	onnecting up intermediate.
Time Log		· · · · · · · · · · · · · · · · · · ·		0		
Dur (hrs)				Operation		Arean 2911
Report Start Date 9/26/2006	Orientation. RU @ 2110', 2050', int & pump 20 b	pump truck w/ 12 bb	l 15% HCL 0' & set pk 200 psi. No	Acid, & shower tra	ion, conduct JSA, Tailgate Safe ailer. TIH w/ pkr to 2120'. Spot 1 tbg to 1000 psi. No communicat // 5 1/2". Tie back onto tbg & try	2 bbl acid across perf holes ion w/ intermediate. Tie onto
Time Log	•					
Dur (hrs)				Operation		
Report Start Date 9/27/2006					gram. TOH, LD tbg & pkr. NDB e. Shut in well. Waiting for ceme	
Time Log						
Dur (hrs)				Operation		
Report Start Date 10/3/2006	csg, lay bleed of half frac tank. Cl next 108 sx(358	ff line to half frac tank lose Surface valve, s	c. Open sui queeze 22). Pressure	rface valve, pump 3 more sx class c went sharply up t	ram & Orientation RU cement 37sx Class C Neat Cement(9 t down intermediate @ 1 1/2 bpm o 320 psi. Cease pumping, clos	bbl slurry) til cmt circulated @ w/ 240 psi. Add 2% CCL for
Time Log	· · · · · · · · · · · · · · · · · · ·					
Dur (hrs)			******	Operation		
Report Start Date	Last 24hr Summary					
10/25/2006		i, conduct interactive nside well head. RU r			afety Meeting, & Go program. N . SION	/IRUPU. NDWH, NUBOP.
Time Log		······································				
Dur (hrs)				Operation		
I						
WellView®				Page 2	- Pon	ort generated on 1/30/2007
Wenview "					T(E)	

LEA NEW MEXICO Sec. 26, T-17S, R-35E 990.00 N 2,307.00 W Original Spud Date Rig Release Date Latitude (DMS) Longitude (DMS) Longitude (DMS) 9/25/1963 10/24/1963 Latitude (DMS) Longitude (DMS) Longitude (DMS) Last 24hr Summary Drive to location, Conduct JSA, participate in Tailgate Safety Meeting, & Go program. TIH w/ 4 3/4" bit & drill collars. Drill o cement from surface to 88', fell out of cement, continue in hole to 200'. TOH, stand back drill collars, LD bit. Pick up & TIH v/ 40 jts 2 7/8" OET. SION Operation Last 24hr Summary Utast 24hr Summary Drive to location, conduct JSA, & Tailgate Safety Meeting. TIH w/ 28 jts 2 7/8" tbg(68 total) to 2128'. RU cementers. Tie on
9/25/1963 10/24/1963 Last 24hr Summary Drive to location, Conduct JSA, participate in Tailgate Safety Meeting, & Go program. TIH w/ 4 3/4" bit & drill collars. Drill o cement from surface to 88', fell out of cement, continue in hole to 200'. TOH, stand back drill collars, LD bit. Pick up & TIH 40 jts 2 7/8" OET. SION
Drive to location, Conduct JSA, participate in Tailgate Safety Meeting, & Go program. TIH w/ 4 3/4" bit & drill collars. Drill o cement from surface to 88', fell out of cement, continue in hole to 200'. TOH, stand back drill collars, LD bit. Pick up & TIH 40 jts 2 7/8" OET. SION Operation
Last 24hr Summary
tbg, load w/ 2 bbl 10# brine. Spot 75 sx C Neat cmt(w/ fresh water as slurry) from 2128' up to 1403'. Displace w/ 7 1/2 bbl 1 Wash up, RD cementers. TOH w/ tbg, close BOP blinds. RU reverse unit, load & pressure csg to 500 psi. Lost no pressure 1 hr. SIOWE
Operation
Last 24hr Summary Drive to location, conduct JSA, participate in Tailgate safety Meeting, & Go program. TIH w/ 4 3/4" bit, 6- 3 3/4" DC, & 40 jt 7/8" tbg. Tag top of cmt @ 1418'. Pressure test csg to 500 psi for 15 min. Drill out to 1655'. TOH to 1600'. SION
Operation
Last 24hr Summary Drive to location, conduct JSA, participate in Tailgate Safety Meeting, & Go program. Resume drilling out down to 2030'. To to 2000'. SION
Operation
Last 24hr Summary Drive to location, conduct JSA, Tailgate Safety Meeting, participate in Go program. Drill out cement from 2030' to 2060', pressure test csg to 500 psi for 15 min. Drill out from 2060' to 2114'. Fell out of cmt @ 2114'. Pressure test csg to 500 psi for 15 min. TIH to 4300'. Reverse sand off RBP @ 4337. TOH, LDDC. TIH w/ csg scraper & bit to 2130'. RU chart recorder, pressure test csg to 500 psi for 30 min.(lost 40 psi) SION
Operation
Last 24hr Summary Drive to location, conduct JSA, & Tailgate Safety Meeting, & Go program. Pressure test csg w/ chart for 30 min, lost 20 psi TOH w/ scraper & bit. TIH w/ ret tool, release RBP @ 4337', TOH, LD tbg & RBP. Pick up, & TIH w/ 135 its 2 7/8" prod. tbg
TOH in stands to 1800' as kill string. SION
TOH in stands to 1800' as kill string. SION
TOH in stands to 1800' as kill string. SION Operation Last 24hr Summary Drive to location, perform JSA, participate in Tailgate Safety Meeting, & Go program.TOH w/ kill string. RU testers, spooler ESP tech. TIH w/ sensor x 4.10', EPP Motor x 20.77', Seal x 5.58', Intake x 2.60', Pump x 13.55', 2 7/8" Lifting sub x 4.00', 140 jts 2 7/8" tbg x 4385.14'(testing to 5000 psi). Cut cable, RD testers, spooler & tech. SIOWE
TOH in stands to 1800' as kill string. SION Operation Last 24hr Summary Drive to location, perform JSA, participate in Tailgate Safety Meeting, & Go program.TOH w/ kill string. RU testers, spooler ESP tech. TIH w/ sensor x 4.10', EPP Motor x 20.77', Seal x 5.58', Intake x 2.60', Pump x 13.55', 2 7/8" Lifting sub x 4.00'.
TOH in stands to 1800' as kill string. SION Operation Last 24hr Summary Drive to location, perform JSA, participate in Tailgate Safety Meeting, & Go program.TOH w/ kill string. RU testers, spooler ESP tech. TIH w/ sensor x 4.10', EPP Motor x 20.77', Seal x 5.58', Intake x 2.60', Pump x 13.55', 2 7/8" Lifting sub x 4.00', 140 jts 2 7/8" tbg x 4385.14'(testing to 5000 psi). Cut cable, RD testers, spooler & tech. SIOWE
TOH in stands to 1800' as kill string. SION Operation Last 24hr Summary Drive to location, perform JSA, participate in Tailgate Safety Meeting, & Go program.TOH w/ kill string. RU testers, spooler ESP tech. TIH w/ sensor x 4.10', EPP Motor x 20.77', Seal x 5.58', Intake x 2.60', Pump x 13.55', 2 7/8" Lifting sub x 4.00', 140 jts 2 7/8" tbg x 4385.14'(testing to 5000 psi). Cut cable, RD testers, spooler & tech. SIOWE Operation Last 24hr Summary Last 24hr Summary M. Bishop, Drive to location, conduct JSA< Tailgate Safety Meeting, & Go program. RDBOP. NUWH. Splice & install wiring