

***See Instruction on Reverse Side**

SUNDRY NOTICE SPECIAL STIPULATIONS

1. Our records show that this well has been Shutin or T/Ad since 1992; except for a period from 2003-2006, when production was reported, with a CIBP @ 3289, which was reported as being set on 2/7/97 and still in place per the 1/3/07 sundry. **This does not include approval of T/A status.** The following stipulations apply to this well.
2. **This well must be brought back into service within 30 days, with a BLM witnessed test to demonstrate same, or a plug and abandon procedure must be submitted within that same time frame.**

Engineering
can be reached at 505-706-2779 for any variances that might be necessary.

F Wright 1/26/07