

Form 3160-5
(February 2005)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 20075. Lease Serial No.
NM-02127 B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
Lea Federal Unit, Well No. 249. API Well No.
30-025-3821210. Field and Pool, or Exploratory Area
Lea Bone Spring

11. County or Parish, State

Lea County, New Mexico

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well
☐ Oil Well ☐ Gas Well ☐ Other2. Name of Operator
Samson Resources Company3a. Address
Samson Plaza - Two West Second St., Tulsa, OK 741033b. Phone No. (include area code)
918-591-1822

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

810' FSL & 519' FWL of Section 12, T-20-S, R-34-E

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Fish & Sidetrack
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

As we discussed, below is the information requested:

TD - 4067 feet
 Fish - Bit, 3 pt, rnr, shock sub, DC, 3 pt rnr, DC = 115 feet
 Top of Fish = 3910 feet
 Will pump 600 sx Premium Plus Cmt + 0.75% CFR-3 Mixed @ 16.5 ppg & 1.0 lb/sx
 Spot Cmt from 3880 ft to 3300 ft.
 Will sidetrack well off Cmt Plug

Please contact Brennan Short, Drilling Engineer, with any questions at (918) 591-1621.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Brad P. Hargrove

Title Senior Landman

Signature

Date

2/23/07

APPROVED

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

FEB 26 2007

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Wesley W. Ingram
PETROLEUM ENGINEER

(Instructions on page 2)

GWW