Form 3160-5 (February 2005)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

J.	۴.	2.00	-	4.5	, sè		٠.	- 1	3.1	1 1	•
						NAI					

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

_			_
-	T	0 - 1 - 1	*T-
Э.	Lease	бепаі	NO.
	NIM 1	ソロトン	

SUNDRY NOTICES AND REPORTS ON WELLS

6. If Indian, Allottee or Tribe Name

i bilig Aribini VA 🌡

SUBM	IT IN TRIPLICATE - Other	instructions on page 2.	7. If	Unit of CA/Agree	ment, Name and/or No.
. Type of Well					
Oil Well Gas V	Well Other		F	Vell Name and No. ederal "27" A #1	
. Name of Operator H. L. Brown operating, LLC	OGRID 213179		9. A 30	PI Well No. 0-041-20832	
a. Address		3b. Phone No. (include area c	, I	Field and Pool or F	•
300 W. Loiusiana Midland, TX 79701		(432) 688-3727	'	N. Bluitt (Wolfcan	np)
<ul> <li>Location of Well (Footage, Sec., T., 660' FNL &amp; 1980 FWL Sec 27, T-7-S, R-37-E</li> </ul>	,R.,M., or Survey Description)		į.	Country or Parish, Roosevelt, NM	State
12. CHE	CK THE APPROPRIATE BO	X(ES) TO INDICATE NATU	RE OF NOTICE, R	EPORT OR OTHI	ER DATA
TYPE OF SUBMISSION		Т	YPE OF ACTION		
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamation	(Start/Resume) on	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplet	æ	Other
	Change Plans	Plug and Abandon		ly Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Dis	posal	
following completion of the invol- testing has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4 Intermediate - 8-5// Production 5-1/2"	work will be performed or proved operations. If the operation I Abandonment Notices must be or final inspection.)  8# H-40 @ 519' casing - cm 8" 32# J-55 @ 3810' - cm to 17# N-80 @ 9200' - TOC @	ne filed only after all requirement to surface to surface to 5475' by temp survey	ion or recompletion	n in a new interval,	a Form 3160-4 must be filed once completed and the operator has
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4 Intermediate - 8-5/P Production 5-1/2" CIBP @ 7650" w/ 3 1/6/0" P&A procedure: 1. Load hole w/ 9.0	work will be performed or proved operations. If the operation I Abandonment Notices must be final inspection.)  18# H-40 @ 519' casing - cm 18" 32# J-55 @ 3810' - cmt 18" 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 2000 1b/gal mud.	wide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface to surface	ion or recompletion	a in a new interval, mation, have been	a Form 3160-4 must be filed once
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4 Intermediate - 8-5/Production 5-1/2" CIBP @ 7650" w/ 3 Fig. C.  P&A procedure: 1. Load hole w/ 9.0 2. Cut off and pull 3. Tag cement plu	work will be performed or proved operations. If the operation of Abandonment Notices must be final inspection.)  18# H-40 @ 519' casing - cm 18" 32# J-55 @ 3810' - cmt to 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 200 0 lb/gal mud.  15-1/2" casing @ 5400', spoug.	wide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface to surface to surface to 5475' by temp survey 03, csg test winessed by BLM of 100' Class "C" cmt plug act	ion or recompletion	n in a new interval,	a Form 3160-4 must be filed once completed and the operator has
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4 Intermediate - 8-5/Production 5-1/2" CIBP @ 7650" w/ 3 Fig. C.  P&A procedure: 1. Load hole w/ 9.0 2. Cut off and pull 3. Tag cement plu	work will be performed or proved operations. If the operation I Abandonment Notices must be final inspection.)  18# H-40 @ 519' casing - cm 18" 32# J-55 @ 3810' - cmt 18" 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 2000 1b/gal mud.	wide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface to surface to surface to 5475' by temp survey 03, csg test winessed by BLM of 100' Class "C" cmt plug act	ion or recompletion	a in a new interval, mation, have been	a Form 3160-4 must be filed once completed and the operator has
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4 Intermediate - 8-5/Production 5-1/2" CIBP @ 7650 w/ 3 1/6/C 2. Cut off and pull 3. Tag cement plu 4. Set 100' Class 5. Set 100' Class 7.	work will be performed or proved operations. If the operation I Abandonment Notices must be of final inspection.)  18# H-40 @ 519' casing - cm to 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 200 of lb/gal mud.  15-1/2" casing @ 5400', spoug.  18	wide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface to surface to surface to 5475' by temp survey 03, csg test winessed by BLM of 100' Class "C" cmt plug act	ion or recompletion	a in a new interval, mation, have been	a Form 3160-4 must be filed once completed and the operator has
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4 Intermediate - 8-5// Production 5-1/2" CIBP @ 7650 w/ 3 7600 w/ 3	work will be performed or proved operations. If the operation I Abandonment Notices must be of final inspection.)  18# H-40 @ 519' casing - cm 8" 32# J-55 @ 3810' - cmt to 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 200 0 lb/gal mud.  15-1/2" casing @ 5400', spoug.  10"C" cmt plug 3860' to 3760'.  11"C" cmt plug 569' to 469'.  12"C" cmt plug 13' to 3'.	wide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface	ion or recompletion	a in a new interval, mation, have been	a Form 3160-4 must be filed once completed and the operator has
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4 Intermediate - 8-5// Production 5-1/2" CIBP @ 7650 w/ 3 7600 w/ 3	work will be performed or proved operations. If the operation I Abandonment Notices must be of final inspection.)  18# H-40 @ 519' casing - cm to 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 200 of lb/gal mud.  15-1/2" casing @ 5400', spoug.  18	wide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface	ion or recompletion	a in a new interval, mation, have been	a Form 3160-4 must be filed once completed and the operator has
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4 Intermediate - 8-5// Production 5-1/2" CIBP @ 7650 w/ 3 7600 w/ 3	work will be performed or proved operations. If the operation I Abandonment Notices must be of final inspection.)  18# H-40 @ 519' casing - cm 18" 32# J-55 @ 3810' - cmt 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 200 0 lb/gal mud.  15-1/2" casing @ 5400', spour 19 and	ovide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface to surfac	ion or recompletion	a in a new interval, mation, have been	a Form 3160-4 must be filed once completed and the operator has
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4. Intermediate - 8-5/Production 5-1/2" CIBP @ 7650" w/ 3-1/4/10" w/ 3-1/4	work will be performed or proved operations. If the operation I Abandonment Notices must be of final inspection.)  18# H-40 @ 519' casing - cm is 32# J-55 @ 3810' - cmt to 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 200 0 lb/gal mud.  15-1/2" casing @ 5400', spour is 5-1/2" casing @ 5400', spour is 6.1/2" cmt plug 3860' to 3760'.  18"C" cmt plug 3860' to 469'.  19"C" cmt plug 13' to 3'.  19"C" cmt plug 13' to 3'.  19"C" below GL and install dry he true and correct.	ovide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface to surfac	ion or recompletion its, including reclar including reclar including reclar including reclar including reclar including reclarity.	a in a new interval, mation, have been	a Form 3160-4 must be filed once completed and the operator has
following completion of the involtesting has been completed. Final determined that the site is ready for Current casing: Surface - 13-3/8" 4. Intermediate - 8-5/Production 5-1/2" CIBP @ 7650" w/ 3 1/6/10" 2. Cut off and pull 3. Tag cernent plu 4. Set 100' Class 5. Set 100' Class 6. Spot 10' Class 7. Cut off casing 3. Tag certify that the foregoing is 1 Name (Printed/Typed) Carlton Wheeler	work will be performed or proved operations. If the operation I Abandonment Notices must be of final inspection.)  18# H-40 @ 519' casing - cm 18" 32# J-55 @ 3810' - cmt 17# N-80 @ 9200' - TOC @ 35' cmt on top in August 200 0 lb/gal mud.  15-1/2" casing @ 5400', spour 19.  10"C" cmt plug 3860' to 3760'.  10"C" cmt plug 13' to 3'.  11"C" cmt plug 13' to 3'.  12" below GL and install dry he true and correct.	wide the Bond No. on file with on results in a multiple complet be filed only after all requirement to surface	ion or recompletion its, including reclar including reclar including reclar including reclar including reclar including reclarity including reclar	a in a new interval, mation, have been to the control of the contr	a Form 3160-4 must be filed once completed and the operator has

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

(Instructions on page 2)

entitle the applicant to conduct operations thereon.

fictitious or fraudulent statements Or representations as to any matter within its jurisdiction.