## Submit 3 copies

## State of New Mexico

Form C-103

to Appropriate District Office	Energy, Minerals and Natural Re	esources Department		Rev	rised 1-1-89
DISTRICT I	OIL CONSERVATION	ON DIVISION	WELL API NO.		
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088			0-025-35562	
DISTRICT II	Santa Fe, New Mexico		Indicate Type of Let		
P.O. Box Drawer DD, Artesia, NM 88210	Jama I J, NOW WEXIO	000004 2000		STATE 🗹	FEE 🗌
DISTRICT III  1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lea	ase No.	
	TICES AND REPORTS ON WELI	10			and the property
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.			7. Lease Name or Unit Agreement Name		
			VACUUM GRAYBURG SAN ANDRES UNIT		
1. Type of Well: OIL GAS WELL WELL					, 0,
2. Name of Operator		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	8. Well No.		
CHEVRON U	ISA INC			235	
3. Address of Operator 15 SMITH RD, MIDLAND, TX 79705			9. Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES		
Well Location					
Unit Letter H::	2610' Feet From The NORT	H Line and 660'	Feet From Thef	EAST Line	
Section 1	Township 18-S R	ange <u>34-E</u> NM	1PM	LEA COUNT	Υ
	10. Elevation (Show whether DF, RKB,	RT,GR, etc.)			
11. Check Ar	opropriate Box to Indicate Nati	ure of Notice. Report.	or Other Data	· · · · · · · · · · · · · · · · · · ·	
NOTICE OF INTENTIO	•		JBSEQUENT F	DEDODT OF:	
	PLUG AND ABANDON				
PERFORM REMEDIAL WORK	CHANGE PLANS	REMEDIAL WORK	_	ERING CASING	NT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPE		G AND ABANDONMEN	vi []
PULL OR ALTER CASING		CASING TEST AND CEMEN		CTIMUL ATE	
OTHER:		OTHER:	CLEAN OUT & ACID	STIMULATE	
<ul> <li>12. Describe Proposed or Completed Open proposed work) SEE RULE 1103.</li> <li>2-19-07: MIRU. HOOK UP CHOKE @ V2-20-07: REL PKR. BLEED BACK TO F2-21-07: MOVE IN 131 JTS 2 7/8" NEW 2-22-07: TIH W/MILL, TBG TO TAG @ 42-23-07: MILL ON BAD CSG @ 4249, 42-26-07: TIH W/PKR, SN, TBG TO 41452-27-07: REL PKR @ 4145. PULL UP. F2-28-07: TIH W/MILL TO 4249. TAG ON 3-01-07: TIH W/MILL &amp; TAG @ 4249. M3-02-07: TIH W/PKR &amp; SET @ 4135.</li> <li>3-05-07: TEST TO 500# FOR 35 MINS.</li> </ul>	WELL & TIE IN FLOW BACK LINE @ FRAC TANK. CIRC W/10# BW. / TBG. TIH W/BIT & TAG FILL @ 424 4249. MILL ON BAD CSG @ 4249, 4 .380. FELL THRU TO 5414. C/O FILL 5 & SET. ACIDIZE W/8000 GALS HO RESET PKR @ 4135. TIH W/MILL & N BAD CSG. MILL CSG 4249-4380. TE MILL ON BAD CSG FR 4249-4380. FE	D HEADER. 40. C/O FR 4240-4386. 4360, 4380, 4390. C/O TO - TO 4760. CL. TBG TO 2670. FAG SALT @ 4712. C/O T ELL THRU TO 4732.	4514. O 4792.		g any
			122	3031-1238	

MKerton TITLE Regulatory Specialist SIGNATURE

TYPE OR PRINT NAME

Denise Pinkerton

CONDITIONS OF APPROVAL, IF ANY:


OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE

De MARiois 12-939 er 2007

DATE

3/12/2007

Ferephone No. 632-687-7375



Single Company of place of the service of the servi THE SER THE SERVICE SE