Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103				
District I Energy 1625 N. French Dr., Hobbs, NM 88240	v, Minerals and Natural Resources	March 4, 2004 WELL API NO. 20,025,24781				
District II	CONSERVATION DIVISION	30-025-34781 5. Indicate Type of Lease				
District III 1000 Rio Brazos Rd., Aztec, NM 87410	220 South St. Francis Dr.	STATE X FEE				
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.				
87505 SUNDRY NOTICES AND R	EDODTS ON WELLS	7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL DIFFERENT RESERVOIR. USE "APPLICATION FOR P. PROPOSALS.)	Hawkeye 30 State					
1. Type of Well:	8. Well Number					
Oil Well Gas Well X Other	1					
2. Name of Operator ConocoPhillips Company		9. OGRID Number 217817				
3. Address of Operator P. O. Box 51810		10. Pool name or Wildcat				
Midland, TX 79710		Vacuum; Morrow (Gas)				
4. Well Location						
Unit Letter J : 1980 feet from the South line and 1970 feet from the East line						
Section 30 T	ownship 17S Range 34E	NMPM CountyLea				
4086' GR						
Pit or Below-grade Tank Application (For pit or below-gr           Pit Location:         ULSectTwpRng						
Distance from nearest surface water Below-g						
feet from theline andfeet from		0				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASI						
	ABANDON 🗌 🛛 REMEDIAL WC	RK   ALTERING CASING				
		RILLING OPNS. PLUG AND ABANDONMENT				
PULL OR ALTER CASING DULTIPLE COMPLET		AND				
OTHER:	OTHER: Added	perfs, Run SL				
		and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
or recompletion. 10/13/04 - 10/21/04 - Added perfs in the Morrow formation per the attached daily summary of work.						
6/28/05: Conducted logging run as shown on the attached daily summary of work.						
0/20/05. Conducted logging run as shown on the attached dany summary of work.						
I hereby certify that the information above is true	and complete to the best of my knowled	lge and belief. I further certify that any pit or below-				
grade tank has been/will be constructed or closed according to NMOCD guidelines 🗌, a general permit 🗍 or an (attached) alternative OCD-approved plan 🗌.						
SIGNATURE July Cogu	TITLE Agent	DATE 03/21/2007				
Type or print name Judy Bagwell	E-mail address: judybagwe	ll@conocophillips.@etephone No.(432)688-6942				
(This space for State use)						
- All		ND/OFNIEDAL 114514 OF5				
APPPROVED BY Mus William	OC DISTRICT SUPERVISO	DR/GENERAL MANAGER				

HAWKEYE 30	STATE 01 RECOMPLETION Daily Summary
API / UWI	County State/Province Surface Legal Location N/S Dist (ft) N/S Ref E/W Dist (ft) E/W Ref
300253478100	LEA         NEW MEXICO         Sec. 30, T-17 S, R-43 E         1,980.00         S         1,970.00         E
round Elevation (ft)	Original Spud Date Rig Release Date Latitude (DMS) Longitude (DMS) 2/3/2000
4,086.00	12/13/1999 2/3/2000
eport Start Date	Last 24hr Summary Drove Rig to location, Held safety meeting, MIRU DDU, MIRU wireline crew, Tubing 360 psi, casing 400 psi, RIH w/ sinker ba
10/13/2004	and jars tag fill @ 13,499'. POOH w/ sinker bar. RBIH w/ 2.28"gauge ring, sinker bar and jars to 13,372'. POOH w/ 2.28"gaug ring. RBIH w/ XN blanking plug to 2.313" X-nipple @ 13,004'. Could not get through X-nipple, sheared off, POOH. RBIH to retreive plug, POOH. RBIH w/ XN blanking plug to 2.313" X-nipple @ 13,004'. Could not get through, Sheared off, POOH. RIBH to retreive plug. RD wireline crew. SISD.
lime Log	
Dur (hrs)	Operation
Report Start Date	Last 24hr Summary
10/14/2004	Drove crew to location and held safety meeting. Waited for further instruction. RU pump truck Tubing psi 360, Casing psi 380 Bled down well. Pumped 20 bbls condensate down tubing to kill. ND wellhead, NU BOP. Rigup tubing equipment. SISD
Fime Log	
Dur (hrs)	Operation
leport Start Date	Last 24hr Summary
10/15/2004	Drove crew to location and held safety meeting. Tubing pressure 200 psi, Casing pressure 160 psi. Bled pressure off well. R pump truck and pump 20 bbls condensate down tubing to kill well.Release packer start OOH. Shutdown for rig repairs. Finish POOH w/ tubing and packer.Laid down packer. RBIH w/ kill string SISD.
Time Log	
Dur (hrs)	Operation
teport Start Date	
10/16/2004	Drove Crew to location and held safety meeting. Tubing 0 Psi, Casing 0 Psi. POOH w/ kill string. RU tubing testers. RIH testing in hole to 5,000lbs below slips. Found pin hole in jt # 383. Laid jt down and replaced. Continue testing. all other tubing good. RD testers. SISD.
Time Log	
Dur (hrs)	Operation
Report Start Date 10/18/2004	Last 24hr Summary Drove crew to location and held safety meeting. Tubing 0 psi, Casing 0 psi. PU 8' tbg sub and 1 jt of 2 7/8" tbg RIH. Set packer @13,179'. Rig up floor. ND BOP, NU wellhead and flowline. RU wireline crew to set standing valve in packer @ 13,344'. First run could not get thruogh gudgeon w/ X profile cut in it @ 13,175'. POOH, PU retreiving tool and RBIH, Catch valve, POOH. Modify packing on standing valve, RBIH and set in XN nipple @ 13,344'. POOH, RD wireline crew. SISD
Time Log	
Dur (hrs)	Operation
Report Start Date 10/19/2004	Last 24hr Summary Ru pump truck to load tubing w/ condensate. Pumped 70 bbls down tubing. Pressured tubing up to 500 psi. Held good. RD pump truck. MIRU Schluberger wireline truck. Pressure test 10K lubricator to 6,200 psi. Good test. RD testers. Loaded 1 11/16" x 6' strip gun w/ 36 shots. RIH and perforate 13,294' - 13,300'. Well on vacuum. POOH, all shots fired. Load 1 11/16" 20' strip gun w/ 120 shots. RIH and perforate 13,260' - 13,280'. Well on vacuum. POOH, all shots fired. Load 1 11/16" gun w/ 36 shots. RIH and perforate 13,260' - 13,280'. Well on vacuum. POOH, all shots fired. Load 1 11/16" strip gun w/ 36 shots. RIH perforate 13,246' - 13,252'. Well had slight blow. POOH, all shots fired. (Unable to detect fluid level afte each run).RDMO wireline truck. SISD. 10/20/2004 @ 6:00 am open well up, Well on vacuum.
Time Log	
Dur (hrs)	Operation
Report Start Date 10/20/2004	Last 24hr Summary MIRU Swab unit. Open well, Well on a vacuum. Start in hole w/ swab, tag fuild @ 1,700' from surface. Made eight runs w/ swab. Fluid level @ 4,700' from surface. Well open to tank flowed for 20 min. RIH w/ swab tag fluid @ 8,700' from surface. Made three more runs w/ swab. Well dry down to 13,100'. Recovered total of 63.45 bbls. SISD
Time Log	
Dur (hrs)	Operation
teport Start Date 10/21/2004	Last 24hr Summary Drove to location. Held safety meeting. Open well, Tubing pressure 1400 psi. Blew down well to tank. Took 30 min to blow we down to 30 psi. RIH w/ swab and tag scattered fluid @ 9,600'. Made three runs. Well dry, Recovered 1.4 bbls fluid. Well low flow to tank. SISD. 10/22 @ 06:00 well SITP 1,600 psi.
Time Log	
Dur (hrs)	Operation
VellView®	Page 1 Report generated on 3/21/20

HAWKEYE 30 ST			ummary	CHANGE OF	
	County State/Prov LEA NEW N	IEXICO Sec. 30,	T-17 S, R-43 E	N/S Dist (ft) N/S Ref 1,980.00 S	E/W Dist (ft) E/W Ref 1,970.00 E
Ground Elevation (ft) 4,086.00	Original Spud Date 12/15/1999		Latitude (DMS)	Longitude (DMS)	
7,000.00	12/10/1999	20,2000		I	
	Last 24hr Summary Daily Summary Report: 6	-28-05			
				ni waa 600 aaiy. Drianta atart	af iah, wall waa blown
	down, RIH with GF retriev	ring tool, tagged at 133	27' (slickline measurem	si was 600 psig. Prior to start ent ground level) Note: KB is <sup>2</sup>	16'. Unable to get
	through bottom packer. W psig during operation. RD	orked tool up and down	n for two hours, without	latching onto check valve. Su	rface Psi built up to 160
Time Log Dur (hrs)			Operation		
WellView®		P	age 1	Report	generated on 3/21/2007