	******	Admin Off Com	gruztion Division,	The stand of the stand
	TAGM	1625 N	. French Extva	
Form 3160-5 (September 2001)	n 3160-5 UNITED STATES HUBBER PLATE COLUMN			FORM APPROVED OMB No. 1004-0135
BUREAU OF LAND MANAGEMENT			Expires January 31, 2004 5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS				NM13418
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name
- 그는 동네는 이번 것은 <u>이 가</u> 동안에서 있는 것을 하는 것이 좋겠다.	RIPLICATE – Othe	er instructions on re	verse side	7. If Unit or CA/Agreement, Name and/or No.
				8. Well Name and No.
Oil Well Gas Well Other				Amoco Federal #010
John R. Stearns dba Stearn's   3a. Address   3b. Phone No. (include area code)				9. API Well No.
		505-675-2356	040)	30-005-20790 10. Field and Pool, or Exploratory Area
HC 65, Box 988, Crossroads, NM 88114     505-675-2356       4. Location of Well (Footage, Sec., T., R., M., or Survey Description)     505-675-2356				Tom-Tom, San Andres
990 FSL, 990 FEL				11. County or Parish, State
Unit Letter P, Sec. 26, T7S, R31E NMPM				Chaves, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION			TYPE OF ACTION	
_	Acidize	Deepen	Production (Start/Resume	Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	Reclamantion	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	
	Convert to Injection	Plug Back	Water Disposal	
determined that the site is ready for final inspection.) 3/01/07 MIRU. NU BOP RIH w/ tbg. set CIBP. Set @ 3940. SDFN. 3/02/07 Circulate well w/ mud laiden fluid. Spot 25 sx cement on top CIBP. POH to 3250, Spot 25 sx cement. Stand up 1450' tbg. lay down rest SDFN. 3/05/07 Perf. 4 1/2 csg. @ 1700'. RIH w/ packer @ 1450'. SQZ. 40 sx cement. WOC 4 hrs. Tag plug @ 1575'. Lay down tbg. Perf. csg. @ 350'. Sqz. 110 sx cement down 4 1/2 & up 8 5/8 to surface. Top off casing with 5 sx. cement. SDFN. 3/06/07 Tag plug @ 30'. Spot 5 sx cement to surface. Cut off wellhead and weld on Dry Hole Marker, Rig down.				
			Approved as to plug	ging of the well See . 2
14. I hereby certify that the foregoing is t Name (Printed/Typed)	enero s		e owner 3-16-07	55 V 58 59 5 4 58 59 5 7 59 59 5 7 59 59 5 7 59 59 5 7 59 59 5 7 59 59 5 7 59 59 5 7 59 59 5 7 50 5 7 5
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by /S/ ALEXIS C. SWOBODA Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			le Office	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent sta				y department or agency of the United
GWW				