State of New Mexico Form C-103 Energy, Minerals and Natural Resources Department Revised 5-27-2004 FILE IN TRIPLICATE OIL CONSERVATION DIVISION WELL API NO. DISTRICT I 1220 South St. Francis Dr. 30-025-07431 1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505 5. Indicate Type of Lease DISTRICT II STATE X FEE 1301 W. Grand Ave, Artesia, NM 88210 6. State Oil & Gas Lease No. DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form G101) for such proposals.) Section 29 8. Well No. 1. Type of Well: 321 Oil Well Gas Well Other Injector 9. OGRID No. 2. Name of Operator 157984 Occidental Permian Ltd. 10. Pool name or Wildcat Hobbs (G/SA) 3. Address of Operator HCR 1 Box 90 Denver City, TX 79323 12131415200 4. Well Location Feet From The Line Unit Letter G Feet From The 1650 2310 North 0 NMPM County Section 29 Township 18-S Range 38 Lea **h**EK 11. Elevation (Show whether DF, RKB, RT GR, etc.) ശ 3655' GL Kecer ŝ Hobbs Ņ ഹ Pit or Below-grade Tank Application or Closure 0CD Distance from nearest orface water Pit Type Depth of Ground Water Distance from nearest fresh water well Below-Grade Tank: Volume _bbls; Construction Material 06 67 87 179 Pit Liner Thickness mil 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS **PLUG & ABANDONMENT** CASING TEST AND CEMENT JOB PULL OR ALTER CASING **Multiple Completion** OTHER: OTHER: Squeeze/Open additional Perfs/Acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU. ND wellhead/NU BOP. Pull out of hole with tbg & packer. 2. RIH w/scraper & tag @4297'. POOH w/scraper. 3. RU wireline & RIH w/CIBP set @4168'. Dump 1 sxs sand on top. Top of sand @4158'. RD wireline. 4. RIH w/cement retainer set @4076'. RU HES & squeeze perfs @4137' w/150 sxs. Locked up @2500# w/65 sxs in perfs. 5. RIH w/fast drill RT to 2837'. Pumped 122 sxs in perfs. RD HES. 6. RIH w/ bit & drill collars, tag CICR @2837'. Drill out CR & cement down to 2906'. Fell out of cement. POOH w/bit & drill collars. Test casing to 800# OK. 7. RIH w/bit & collars, tag CICR @4076'. Drill out retainer & cement to 4105'. Circ well clean. 8. Drill on cement from 4105-4152'. Drill out CIBP @4168'. Continue drilling to 4295'. Circ hole clean. 9. RU wireline & perforate w/180 degree phase spiral @4150-52', 4156-61' 1 JSPF (9 holes) & 4217-22', 4232-36', 4242-46' 2 JSPF (32 holes). RD wireline. ***additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. If urther certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 03/08/2007 TYPE OR PRINT NAME TELEPHONE NO. Mendy Johnson E-mail address: mendy johnson@oxy.com 806-592-6280 For State Use Only APPROVED BY TITLE MAR 3 0 2007 OC FIELD REPRESENTATIVE IL/STAFF MANAGER CONDITIONS OF APPROVAL IF ANY:

NHU 29-321 03/08/2007

< . .

10. RIH w/PPI packer set @4009'. RU HES & pump 1500 gal of 15% PAD acid in two settings. RD HES. POOH w/PPI packer.

- 11. RIH w/Guiberson G-6 w/1.875 F Profile on 127 jts of 2-7/8" Duoline tubing. Packer set @4050'
- 12. ND BOP/NU wellhead.
- 13. Test casing to 560# for 30 minutes and chart for NMOCD.
- 14. RDPU & RU. Clean location.

RUPU 02/01/07 RDPU 02/15/07



