	, r	•		
Submit 3 Copies To Appropriate District	3 Copies To Appropriate District State of New Mexico		Form C-103	
Office District I	Energy, Minerals and Natural Resources		May 27, 2004	
625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-35577		
District II 1301 W. Grand Ave., Artesia, NM 88210	Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Leas	se e
District III	1220 South St. Francis Dr.		STATE	FEE 🛛
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Leas	e No.
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			LANGLIE JAL UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			0. 77/ 11.77 1 120	
1. Type of Well: Oil Well Gas Well Other			8. Well Number 120	
2. Name of Operator			9. OGRID Number 188483	
PHOENIX HYDROCARBONS OPERATING CORPORATION			10. Pool name or Wildcat LANGLIE	
3. Address of Operator			MATTIX, 7 RVRSQ	
1 0 BOX 5050, MIDELEUS, 111 75762				
4. Well Location	1100 Coat form the Courth	line and	2365 feet from the	East line
	1100feet from theSouth	Range 37E	NMPM Lea Co	
Section 31	Township 24S 11. Elevation (Show whether DR,			Addity 14141
	3232' GL	MD, KI, OK, etc)	
Pit or Below-grade Tank Application or G				
Pit typeDepth to Groundwate		water well D	Distance from nearest surface w	ater
Pit Liner Thickness: mil	Below-Grade Tank: Volume		Construction Material	
	propriate Box to Indicate N	ature of Notice	Report or Other Data	
12. Check Ap	propriate box to indicate iv			
NOTICE OF INTENTION TO: SUBSEQUE				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				RING CASING
TEMPORARILY ABANDON				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			NT JOB L	
OTHER: CONDUCT MIT OTHER: Conve			rt to Injection well	X
			-	
13 Describe proposed or comple	ted operations. (Clearly state all	pertinent details, a	nd give pertinent dates, inc	luding estimated date
of starting any proposed work	x). SEE RULE 1103. For Multip	le Completions: A	Attach wellbore diagram of	proposed completion
or recompletion.				
2-6-07 TO 2-7-07				
1. MIRU				01-122
2. GIH w/tension set packer on 103 jts of poly lined 2-7/8" tbg.				
2. GIH w/tension set packer on 103 jts of poly lined 2-7/8" tbg. 3. Set packer @ 3233'. 4. Load backside w/packer fluid and test to 300 psi, held OK. 3/13/07 5. Conduct MIT. See attached chart. (WITNESSED BY BUDDY HILL) 6. Well ready for injection when surface injection line is completed.				
1. MIRU 2. GIH w/tension set packer on 103 jts of poly lined 2-7/8" tbg. 3. Set packer @ 3233'. 4. Load backside w/packer fluid and test to 300 psi, held OK. 3/13/07 5. Conduct MIT. See attached chart. (WITNESSED BY BUDDY HILL) 6. Well ready for injection when surface injection line is completed.				
3/13/07				
5. Conduct MIT. See attached chart. (WITNESSED BY BUDDY HILL)				
6. Well ready for injection	when surface injection line is con	npleted.	125	
	_		/52	
	822		<u>., , , , , , , , , , , , , , , , , , , </u>	505EF81 17 81 24
1.	1FX-825			
ν	, ,			
I hereby certify that the information algrade tank has been/will be constructed or c	pove is true and complete to the blosed according to NMOCD guidelines	est of my knowled □, a general permit	lge and belief. I further certi	fy that any pit or below- OCD-approved plan □.
SIGNATURE Phillip	2) Shintage	AGENT	DATE	3/16/07
Type or print name Phyllis R. Gunte	r E-mail address: <u>bsne</u>	ed@t3mid.com	TAFF MANAGER Telephon	ne No. 432-686-9869
APPROVED BY:	Wink OCFIETETREET	resentative II/s	DA	ATE
U			Y	R 3 0 2007

PhoENIX 1 0-31-24-37

DINGLE JAH 120 3-13-07

LANGLE LAT 120 RAPE ON THIS PAR. MER. MER.