Submit 3 Copies To Appropriate District Office	State of Nev			Form C-103	
District I	Energy, Minerals and	Natural Resources	TYPET A DYNA	May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-025-37955		
District II 1301 W. Grand Ave., Artesia, NM 88210	1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type	of Lease	
District III 1220 South St. Francis Dr.			FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, N	M 87505	6. State Oil & Ga		
1220 S. St. Francis Dr., Santa Fe, NM					
87505 SLINDRY NOT	TICES AND REPORTS ON W	FIIS	7 Lease Name o	r Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name o	1 Omt / igreement / tune	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			New Mexico "AA	A" State	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number 7			
2. Name of Operator	Gas Well 🖂 Other		9. OGRID Numb	per 237788	
Plantation Operating, LLC). OGIGE IVamo	237700	
3. Address of Operator				Wildcat Jalmat (Gas)	
	229, The Woodlands, TX 7738	30	(79240) ; Langlie	(79240); Langlie Mattix (37240)(Oil)	
4. Well Location		16	50		
Unit Letter 4: 660	feet from theNorth	line and	feet from the	Eastline	
Section 22	Township 23S	Range 36E	NMPM I	ea County	
	11. Elevation (Show whether	r DR, RKB, RT, GR, et	c.)	Signature of the state of the s	
	3373' GR			All All San Comments	
Pit or Below-grade Tank Application					
Pit type Depth to Ground	water Distance from neares	t fresh water well	Distance from nearest s	urface water	
Pit Liner Thickness: mi	Below-Grade Tank: Volume	bbls;	Construction Material		
12. Check	Appropriate Box to Indica	te Nature of Notice	e, Report or Other	Data	
	** *		•		
	NTENTION TO:		BSEQUENT RE		
	PLUG AND ABANDON	REMEDIAL WO	RK II	ALTERING CASING	
PERFORM REMEDIAL WORK	· · · · · · · · · · · · · · · · · · ·			5 4 1 5	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE D	RILLING OPNS.	P AND A	
	CHANGE PLANS	COMMENCE D	RILLING OPNS.	P AND A	
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS	COMMENCE D	RILLING OPNS.	P AND A COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS	COMMENCE D CASING/CEME OTHER:	RILLING OPNS.	COMPLETION 🛛	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v	CHANGE PLANS MULTIPLE COMPL	COMMENCE D CASING/CEME OTHER: e all pertinent details, a	RILLING OPNS. NT JOB und give pertinent dat	COMPLETION es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state	COMMENCE D CASING/CEME OTHER: e all pertinent details, a	RILLING OPNS. NT JOB und give pertinent dat	COMPLETION es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state	COMMENCE D CASING/CEME OTHER: e all pertinent details, a	RILLING OPNS. NT JOB und give pertinent dat	COMPLETION es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v or recompletion.	CHANGE PLANS MULTIPLE COMPL Discription Clearly state Clearly state	COMMENCE D CASING/CEME OTHER: e all pertinent details, a	RILLING OPNS. NT JOB und give pertinent dat	COMPLETION es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v	CHANGE PLANS MULTIPLE COMPL Discription Clearly state Clearly state	COMMENCE D CASING/CEME OTHER: e all pertinent details, a	RILLING OPNS. NT JOB und give pertinent dat	COMPLETION es, including estimated date	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed or or recompletion. 11/21/2006 through 12/6/06:	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions:	RILLING OPNS. NT JOB and give pertinent dat Attach wellbore diagram	COMPLETION es, including estimated date ram of proposed completion	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v or recompletion.	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state ork). SEE RULE 1103. For Mark 1945'-3738' w/55 holes w/3-1/8	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions:	RILLING OPNS. NT JOB and give pertinent dat Attach wellbore diagram	COMPLETION es, including estimated date ram of proposed completion	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed or or recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state ork). SEE RULE 1103. For Mark 1945'-3738' w/55 holes w/3-1/8	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions:	RILLING OPNS. NT JOB and give pertinent dat Attach wellbore diagram	COMPLETION es, including estimated date ram of proposed completion	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers. Sand and 240,000 pounds of 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers.	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tor	RILLING OPNS. NT JOB	COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v or recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HO	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers. Sand and 240,000 pounds of 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers.	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tor	RILLING OPNS. NT JOB	COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers. Sand and 240,000 pounds of 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers.	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tor	RILLING OPNS. NT JOB	COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers. Sand and 240,000 pounds of 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers.	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tor	RILLING OPNS. NT JOB	COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers. Sand and 240,000 pounds of 1945'-3738' w/55 holes w/3-1/8 Lacid dropping ball sealers.	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tor	RILLING OPNS. NT JOB	COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or North). SEE RULE 1103. For North of 1945'-3738' w/55 holes w/3-1/8 L acid dropping ball sealers. Sand and 240,000 pounds of 1945' tog set at 3758'. TIH w/pump	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tor o and rods. Wait on pi	RILLING OPNS. NT JOB	COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or North). SEE RULE 1103. For North of 1945'-3738' w/55 holes w/3-1/8 L acid dropping ball sealers. Sand and 240,000 pounds of 1945' tog set at 3758'. TIH w/pump	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tor o and rods. Wait on pi	RILLING OPNS. NT JOB	COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or North). SEE RULE 1103. For North of 1945'-3738' w/55 holes w/3-1/8 L acid dropping ball sealers. Sand and 240,000 pounds of 1945' tog set at 3758'. TIH w/pump	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tor	RILLING OPNS. NT JOB	COMPLETION	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v or recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HC Frac well with 60,000 pounds 20/4 PBTD 3790'. TIH w/116 jts 2-3/8	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North of 1945'-3738' w/55 holes w/3-1/8 L acid dropping ball sealers. Sand and 240,000 pounds of 1946' to the sealer of 1946'. Till w/pump	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "select fire gun loaded and rods. Wait on picture of the best of my knowled."	RILLING OPNS. NT JOB NT JO	completion es, including estimated date ram of proposed completion es, 1 SPF (.46" hole size). ged at 3587'. Clean out to ll on production.	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v or recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HC Frac well with 60,000 pounds 20/4 PBTD 3790'. TIH w/116 jts 2-3/8	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North of 1945'-3738' w/55 holes w/3-1/8 L acid dropping ball sealers. Sand and 240,000 pounds of 1946' to the sealer of 1946'. Till w/pump	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "select fire gun loaded and rods. Wait on picture of the best of my knowled."	RILLING OPNS. NT JOB NT JO	completion es, including estimated date ram of proposed completion es, 1 SPF (.46" hole size). ged at 3587'. Clean out to ll on production.	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HC Frac well with 60,000 pounds 20/4 PBTD 3790'. TIH w/116 jts 2-3/8 I hereby certify that the information grade tank has been/will be constructed of the constructed of th	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state ork). SEE RULE 1103. For Management of the second	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "select fire gun loaded 2/20 sand with 311 tor and rods. Wait on pi the test of molecular permit the test of molecular permit	RILLING OPNS. NT JOB NT JO	COMPLETION Ses, including estimated date ram of proposed completion es, 1 SPF (.46" hole size). Ged at 3587'. Clean out to all on production. See certify that any pit or belownstive OCD-approved plan	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed v or recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from 2 Acidize perfs w/4910 gals 15% HC Frac well with 60,000 pounds 20/4 PBTD 3790'. TIH w/116 jts 2-3/8	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state or Nork). SEE RULE 1103. For North of 1945'-3738' w/55 holes w/3-1/8 L acid dropping ball sealers. Sand and 240,000 pounds of 1946' to the sealer of 1946'. Till w/pump	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "select fire gun loaded and rods. Wait on picture of the best of my knowled."	RILLING OPNS. NT JOB NT JO	completion es, including estimated date ram of proposed completion es, 1 SPF (.46" hole size). ged at 3587'. Clean out to ll on production.	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4 PBTD 3790'. TIH w/116 jts 2-3/8 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state ork). SEE RULE 1103. For Management of the second	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tore and rods. Wait on picture of the best of my kerosile.	RILLING OPNS. NT JOB nt JO	COMPLETION Ses, including estimated date ram of proposed completion es, 1 SPF (.46" hole size). ged at 3587'. Clean out to all on production. The certify that any pit or belownative OCD-approved plan DATE 2/22/2007	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4 PBTD 3790'. TIH w/116 jts 2-3/8 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Kimberly	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state ork). SEE RULE 1103. For Management of the second	COMMENCE D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "" select fire gun loaded 2/20 sand with 311 tore and rods. Wait on picture of the best of my kerosile.	RILLING OPNS. NT JOB nt JO	COMPLETION es, including estimated date ram of proposed completion es, 1 SPF (.46" hole size). ged at 3587'. Clean out to ll on production. er certify that any pit or belownative OCD-approved plan DATE 2/22/2007 phone No. 281-296-7222	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4 PBTD 3790'. TIH w/116 jts 2-3/8 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Kimberly For State Use Only	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state of the control of	commence D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "select fire gun loaded 2/20 sand with 311 tor o and rods. Wait on pi the test of more permit Rroduction Tech ddress: kfald morplant	RILLING OPNS. NT JOB nt JO	COMPLETION es, including estimated date ram of proposed completion es, 1 SPF (.46" hole size). ged at 3587'. Clean out to ll on production. er certify that any pit or belownative OCD-approved plan DATE 2/22/2007 phone No. 281-296-7222	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 11/21/2006 through 12/6/06: TIH and run logs. Perforate from Acidize perfs w/4910 gals 15% HO Frac well with 60,000 pounds 20/4 PBTD 3790'. TIH w/116 jts 2-3/8 I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Kimberly	CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state ork). SEE RULE 1103. For Management of the second	commence D CASING/CEME OTHER: e all pertinent details, a fultiple Completions: "select fire gun loaded 2/20 sand with 311 tor o and rods. Wait on pi the test of more permit Rroduction Tech ddress: kfald morplant	RILLING OPNS. NT JOB nt JO	COMPLETION Ses, including estimated date ram of proposed completion es, 1 SPF (.46" hole size). ged at 3587'. Clean out to all on production. The certify that any pit or belownative OCD-approved plan DATE 2/22/2007	