1025 N. French Drive Hobbs, NM 83740

Form 3160-5 (April 2004)

UNITED STATES
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side				5. Lease Serial No. NM - 044216-A		
				6. If Indian, Allottee or Tribe Name		
				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well						
Oil Well X Gas Well Other				8. Well Name and No.		
2. Name of Operator			~	Orbit Federal	AB #1	
John A. Yates Jr.				9. API Well No.	-	
3a. Address	No. (include area code)		30-041-20204			
105 S. 4th Str., Artesia, NM 88	505-748-1471		10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)				Bluitt San Andres Assoc.		
			11. County or Parish, State			
2130'FSL and 660'FEL of Section			Roosevelt, Ni			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE				EPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION						
	Acidize	Deepen	Production (S	Start/Resume)	Water Shut-Off	
		J 1		i y		
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	*	Well Ategrity	
X	X Casing Repair	New Construction	Recomplete	. 3		
Subsequent Report	Change Plans	Plug and Abandon	Temporarily A	Abandon	\$ 5.50 P	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos	sal \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	20/	
3/5/07 Received approval from 500 psi, OK. POH to seals. Set RBP at 22 Pulled RBP at 2211'. #2, 50 gals #1 and 10 #2, 50 gals #1, 50 gal off, wait 10 min and posystem and pressured RBP at 2370'. TIH with tubing.	cker to find hole in casing. om Mr. Hogwood (BLM) to get 2115' and pressured up on 11' and tested to 500 psi, Ce TIH with packer to 2243' and gals #3, 50 gals #2, 50 gals #2, 100 gals #1, 50 gals #3 ressured up to 500 psi and dedup overnight at 380 psi. Ged chart at 540 psi, held go	Tested RBP to 5 go ahead with tre backside and w DK. POH with pa nd spotted 300 F als #1, 50 gals # #2, 50 gals #1. F pressure slowly Called Mr. Hogwe	500 psi. Found attment. Move attment. Move attment of the following the following the following following following the following follow	nd hole in casing yed RBP to 23 pressure due and test casing as follows: 50, 2.5 gals micred to 500 psi a 200 psi. Set ove notice of Minal Chart atta	ng at 2179'. 70' and tested to to BOP leaking in g, held 500 psi. gals #1, 50 gals o seal, 100 gals and small leak up nitrogen IIT for next day.	
3/8/07 RIH with pump and ro				——————————————————————————————————————	FILVEINION	
14. I hereby certify that the foregoing is true a Name (Printed/Typed)	and correct				•	
Tina Hu	erta r	Title Regula	atory Complia	ince Superviso	or	
Signature (Signature	eura	Date March	16, 2007	ACC	EPTED FOR RECO	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
					MAR 2 3 2007	
Approved by Title Conditions of approval if any are stocked. Approval of this nation does not warrent or				Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					ALEXIS C. SWOBODA	

