Submit 3 Copies To Appropriate District  Office  State	of New Mexico		Form C-103
District I Energy, Miner	als and Natural Resources	1000	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	DIATION DIVICION	WELL API NO. 30-025-23943	
District III 1000 Rio Proce Rd. Artes NM 87410 1220 South St. Francis Dr.		5. Indicate Type of Lease	
		STATE S FEE	
District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		1159006	
SUNDRY NOTICES AND REPORTS		7. Lease Name or Unit Agre	eement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Warrior State	
1. Type of Well: Oil Well		8. Well Number 001	
2. Name of Operator Finley Resources, Inc.		9. OGRID Number 180387	
3. Address of Operator		10. Pool name or Wildcat	
1308 Lake Street, Ste. 200, Fort Worth, Texas 76102		Eumont: Yates-7 Rivers-Queen	
4. Well Location			
Unit LetterJ:3226'feet from the	heNorth line and198	)'feet from theEa	stline
Section 2 Township	21S Range 35E	NMPM Cour	nty Lea
11. Elevation (Show 3,590' GL	whether DR, RKB, RT, GR, etc.,		
Pit or Below-grade Tank Application or Closure			
	nearest fresh water well Dis	ance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank:		nstruction Material	
12. Check Appropriate Box to	Indicate Nature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO:	SUB	SEQUENT REPORT C	F:
PERFORM REMEDIAL WORK ☐ PLUG AND ABAND	ON 🗌 REMEDIAL WOR	K 🗌 ALTERING	G CASING 🔲
TEMPORARILY ABANDON	☐ COMMENCE DRI	LLING OPNS. ☐ P AND A	$\boxtimes$
PULL OR ALTER CASING	☐ CASING/CEMEN	r Job □	
1 022 01(7)2121( 0)(0)(10			
	OTHER:		
OTHER:	OTHER:	l civo montinont dotos includin	a agtimated data
OTHER:  13. Describe proposed or completed operations. (Cle	arly state all pertinent details, and		
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103	arly state all pertinent details, and		
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.	arly state all pertinent details, and B. For Multiple Completions: At	tach wellbore diagram of prop	osed completion
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103	arly state all pertinent details, and B. For Multiple Completions: At	tach wellbore diagram of prop	osed completion
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the completion with the completion of the completion o	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pumplempt. Pump 75sx cmt @ 800# @	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on to the completion of the completion	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pumplempt. Pump 75sx cmt @ 800# @	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the completion with the completion of the completion o	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pumplempt. Pump 75sx cmt @ 800# @	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t ½" casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pumplempt. Pump 75sx cmt @ 800# @	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t ½" casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pumplempt. Pump 75sx cmt @ 800# @	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t ½" casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pumplempt. Pump 75sx cmt @ 800# @	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t ½" casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pumplempt. Pump 75sx cmt @ 800# @	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t ½" casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pumplempt. Pump 75sx cmt @ 800# @	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t ½" casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/35/07	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	tach wellbore diagram of prop o 2 <sup>nd</sup> 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the "casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/30/07  Approved as to plugging of the Well Bore.	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	tach wellbore diagram of proposition 2nd 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Percut off wellhead 3' BGL. Well 2007	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t '/2'' casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/30/07  Approved as to plugging of the Well Bore Liability under bond is retained until	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	tach wellbore diagram of proposition 2nd 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Wel	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the "casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/30/07  Approved as to plugging of the Well Bore.	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	tach wellbore diagram of proposition 2nd 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Well 2007	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t '/2'' casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/30/07  Approved as to plugging of the Well Bore Liability under bond is retained until	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	tach wellbore diagram of proposition 2nd 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Wel	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t '/2'' casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/30/07  Approved as to plugging of the Well Bore Liability under bond is retained until	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	tach wellbore diagram of proposition 2nd 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Well 2007	@3199'. Cut 4 rf sqz holes @
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t '/2'' casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/30/07  Approved as to plugging of the Well Bore Liability under bond is retained until	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	2007 Ceived  contact wellbore diagram of property and 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Well well well well be a series of the contact of the con	osed completion  @3199'. Cut 4  rf sqz holes @  d dry hole
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the "casing @ 1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/35/07  Approved as to plugging of the Well Bore Liability under bond is retained until surface restoration is completed.	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	2007 Ceived  Contact wellbore diagram of property 2nd 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Well colors and the contact of the colors	@3199'. Cut 4 rf sqz holes @ d dry hole
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the "casing @ 1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/30/07  Approved as to plugging of the Well Bore Liability under bond is retained until surface restoration is completed.  I hereby certify that the information above is true and completed.	arly state all pertinent details, and B. For Multiple Completions: At op of CIBP. Unable to tag. Pump empt. Pump 75sx cmt @ 800# @ 10sx surface cmt plug 60'- 3'.	2007 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	osed completion  @3199'. Cut 4  rf sqz holes @ d dry hole  t any pit or below- pproved plan □.
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the "casing @ 1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/35/07  Approved as to plugging of the Well Bore Liability under bond is retained until surface restoration is completed.  I hereby certify that the information above is true and com grade tank has been/will be constructed or closed according to NMO SIGNATURE	plete to the best of my knowleds CD guidelines \( \), a result a general permit	2007 2 and 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Well below by the company of the company	@3199'. Cut 4 rf sqz holes @ d dry hole  t any pit or below- pproved plan
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the starting and the second of the starting and the second of the	plete to the best of my knowleds CD guidelines \( \), a result a general permit	2007 2 agerDATE4/5/2	@3199'. Cut 4 rf sqz holes @ d dry hole  t any pit or below- pproved plan
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the "casing @ 1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/35/07  Approved as to plugging of the Well Bore Liability under bond is retained until surface restoration is completed.  I hereby certify that the information above is true and com grade tank has been/will be constructed or closed according to NMO SIGNATURE	plete to the best of my knowletted guidelines \( \), a general permit \( \)  TITLE: Western District Manus: jim.nance@finleyresources.c	2007 2014 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Well color well	a3199'. Cut 4 rf sqz holes @ d dry hole  t any pit or below- pproved plan □.
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on t ½" casing @1782'. Unable to pull csg. OCD ok'd sqz att 497'. Sqz 75sx cmt plug @ 497'. Tag TOC @ 245'. Pump marker.  3/30/07  Approved as to plugging of the Well Bore Liability under bond is retained until surface restoration is completed.  I hereby certify that the information above is true and com grade tank has been/will be constructed or closed according to NMO SIGNATURE  Type or print name  James L. Nance  E-mail address  For State Use Only	plete to the best of my knowletted guidelines \( \), a general permit \( \)  TITLE: Western District Manus: jim.nance@finleyresources.c	2007 2014 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Well color well	a3199'. Cut 4 rf sqz holes @ d dry hole  t any pit or below- pproved plan □.
OTHER:  13. Describe proposed or completed operations. (Cle of starting any proposed work). SEE RULE 1103 or recompletion.  Tag CIBP @ 3719'. Circ P&A mud. Pump 25 sx cmt on the starting and the second of the starting and the second of the	plete to the best of my knowleds CD guidelines \( \), a result a general permit	2007 2014 25sx cmt plug. Tag TOC 1782'. Tag TOC @1492'. Per Cut off wellhead 3' BGL. Well color well	a3199'. Cut 4 rf sqz holes @ d dry hole  t any pit or below- pproved plan □.