

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Oil Conservation Division
1220 S. St. Francis Drive

Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☒

2. Name of Operator

CHESAPEAKE OPERATING

3. Address of Operator

P.O. Box 548806, Oklahoma City, OK 73154

4. Well Location

Unit Letter I : 1980 feet from the SOUTH line and 660 feet from the EAST line

Section 17

Township 17 S

Range 37 E

NMPM

County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3770 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type STEEL Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-16-07 Set pkr. @4,774'. Sqz. 40 sx. cmt. Tag & plug @4,947'. Circ. hole w/mud. Spot 40 sx. cmt. @ 3,629'.

3-19-07 Tag & plug @3,363'. Spot 30 sx. cmt. @3,202'. Spot 30 sx. cmt. @2,137'. Spot 110 sx. cmt. from 400' to surface.

3-20-07 Install Dryhole Marker

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Randall Minear TITLE P & A Supv. DATE 3-27-07

E-mail address:

Type or print name RANDALL MINEAR

Telephone No. 432 - 530-0907

For State Use Only

APPROVED BY Langston Work OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE APR 30 2007

Conditions of Approval, if any: