Office District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 887 829 30 37	WELL API NO. 3002501305
1301 W. Grand Ave., Artesia MM 88210 OLL CONSERVATION DIVISION	5. Indicate Type of Lease
District III	STATE XX FEE
District IV 1220 S. St. Francis De Santa Folloceivan	6. State Oil & Gas Lease No.
SUNDRY CES AND EPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION OF PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	Aztec State 8. Well Number
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	9. OGRID Number
Latigo Petroleum, Inc.	227001
3. Address of Operator	10. Pool name or Wildcat
P.O. 10304, Midland, Texas 79702	Maljamar, GB & SA
4. Well Location	
Unit Letter A : 660 feet from the North line and 660 feet from the East line	
Section 7 Township 17 S Range 33 E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or Closure	
Pit type Steel Depth to Groundwater 173 Distance from nearest fresh water well 1000 Dis	tance from nearest surface water 7100
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A NOT COMMENCE DRILLING OPNS. P AND A NOT CASING/CEMENT JOB CASING/CEMENT JOB P AND A NOT CASING/CEMENT JOB NOT CASING P AND A NOT CASING/CEMENT JOB P AND A NOT CASING P AND A P AND A	
OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	trach wellbore diagram of proposed completion proved as to plugging of the well hore.
1. Move in & rig up. 3/27/07 Ver HB surface restoration is completed.	
 RIH w/ Bit & Scraper, tag @ 145', work down to 425'. RIH w/ Mule Shoe, work & hit bridge, worked down to 4075' 	
Maxey Brown, OCD, OK'd to spot 50 sx cement, WOC, Tag @ 4035'	
spot Plug @ 4035', POOH w/ tubing & SI.	
4. RIH, Tag cement @ 3,628', mix & circulate 10# Salt Gel mud.	
5. RIH w/ $5\frac{1}{2}$ " Packer to 2700'w/ W.L., perforate csg. at 3100' Sqz 40sx,SI 1500PSI, Tag cement @ 2970'.	
6. Perforate $5\frac{1}{2}$ " casing @ 1500', set Packer @ 100', sqz 60 sx	
cement STP 800 PST. WOC. Tag cement @ 1280'. Perforate csg	
@550', set Packer at 30', mix & circulate 150sx cement w/	
circulation up 8 5/8" to Surface. Displaced $\frac{1}{2}$ bbl, pressured	
up to 1500 PSI & POOH w/ Packer.	
7. Cut off wellhead 4' below ground level. F	illed casing w/
 Cut off wellhead 4' below ground level. F 20sx cement, set Dry Hole Marker, cut off 	illed casing w/
7. Cut off wellhead 4' below ground level. F 20sx cement, set Dry Hole Marker, cut off location & moved. 4/4/07 Der HB	illed casing w/ Anchors, clean
 Cut off wellhead 4' below ground level. F 20sx cement, set Dry Hole Marker, cut off 	illed casing w/ Anchors, clean ge and belief. I further certify that any pit or below-
7. Cut off wellhead 4' below ground level. F 20sx cement, set Dry Hole Marker, cut off location & moved. 4400 per HB I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Agent	illed casing w/ Anchors, clean ge and belief. I further certify that any pit or below-
7. Cut off wellhead 4' below ground level. F 20sx cement, set Dry Hole Marker, cut off location & moved. 4/4/07 Oper HB I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit SIGNATURE	illed casing w/ Anchors, clean ge and belief. I further certify that any pit or below- l or an (attached) alternative OCD-approved plan DATE 04/04/07 432-6170-0208 Telephone No.
7. Cut off wellhead 4' below ground level. F 20sx cement, set Dry Hole Marker, cut off location & moved. I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit SIGNATURE TITLE Agent Type or print name E-mail address:	illed casing w/ Anchors, clean ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan DATE 04/04/07 432-6170-0208