State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISIO	ON		Revised 3-27-2004	
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL A	WELL API NO. 30-025-28309		
DISTRICT II	Suitu i O,	14141 07505	5. Indic	ate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210				STATE	FEE X	
DISTRICT III			6. State	Oil & Gas Lease No.	1 1	
1000 Rio Brazos Rd, Aztec, NM 87410						
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form G101) for such proposals.)				Hobbs (G/SA) Unit	1	
1. Type of Well:				No. COOP 6		
Oil Well Gas Well Other Injector						
2. Name of Operator Occidental Permian Ltd.				ID No. 157984		
3. Address of Operator				l name or Wildcat	Hobbs (G/SA)	
HCR 1 Box 90 Denver City, TX	79323					
4. Well Location						
Unit Letter E : 1950	Feet From The North	535	Feet From The	West	_ Line	
Section 34	Township 18-S	Range	38-E	NMPM	Lea County	
	11. Elevation (Show whether DF, RK	(B, RT GR, etc.)				
	3637' GL					
Pit or Below-grade Tank Application	or Closure					
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water						
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material						
12. Check Appropriate Box to Indicate Nature of Notice Report or Other Data						
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	[ALTERING	CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS.	PLUG & A	BANDONMENT	
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND C	EMENT JOB		<u></u>	
OTHER: Clean out & acid treat	X	OTHER:	•		[
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any						
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
1. Kill well. NU BOP. Pull out of hole w/injection equipment.						
2. Clean out well to PBTD @4408'.						
3. Acid treat well with 3300 gal of 159	% PAD acid.					
4. Swab/flow back. Circ well clean.				7. (
5. Run back in hole with injection equipment.6. Test casing and chart for the NMOCD.				and the same	()	
+ COUDS						
				penie	*16H	
				gar. P		
				No.		
I hereby certify that the information above is t	rue and complete to the best of my know	ledge and belief. Ifurther o	ertify that any pit	or below-grade tank h	as been/will be	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. Ifurther certify that any pit or below-grade tank has been/will be constructed or						
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved						
SIGNATURE Mundy Associate DATE 04/24/2007						
TYPE OR PRINT NAME Mendy A. Jo	hnson E-mail address:	mendy_johnson@oxy	com/.com	TELEPHONE NO.	806-592-6280	
For State Use Only						
APPROVED BY HOUND TITLE DATE						
CONDITIONS OF APPROVALE ANY: OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE						