## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV.	ATION DIVISION		
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-28943	
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	<u> </u>
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreem	ent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form G-101) for such proposals.)		North Hobbs (G/SA) Unit Section 32		
1. Type of Well:		(or) for such proposais.)	8. Well No. 143	
Oil Well X Gas Well Other			2	
Name of Operator     Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323			110005 (G/5/1)
4. Well Location				_
Unit Letter M: 1185	Feet From The South	Feet	From The West	Line
Section 32 Township 18-S Range 38-E NMPM Lea County  11. Elevation (Show whether DF, RKB, RT GR, etc.)				
3641' KB				
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Mat	terial	
12. Check	k Appropriate Box to Indicate Na ENTION TO:		Other Data SEQUENT REPORT OF	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT			
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	T JOB	,
OTHER:		OTHER: Log/Squee	ze & Acid Treat	X
13. Describe Proposed or Completed Opproposed work) SEE RULE 1103.  1. Kill well. RU wireline & shoot dra 2. RUPU & RU. ND WH & NU BOF 3. RIH w/ bit & casing scraper, tagged 4. Dump pea gravel down casing. Tag 5. RIH w/cement retainer set @4017'. Reverse out 22 bbl of cement. RD HE 6. RIH w/bit & drill collars. Tag CIC 7. Drill out cement to 4109'. Clean 8. RU wireline & run CNL/GR/CCL 1	For Multiple Completions: Attach win holes & 3790'. RD wireline. P. POOH w/ESP equipment. d @4311'. POOH w/bit & scraper. gged plug back 36' bw. Dumped r. RU HES & mix & pump 100 sxs SS. R @4017'. RU power swivel. Driut pea gravel from 4121-4346' (PB ogs from 4346-3300'. RD wireling	wellbore diagram of proposed common gravel. Tagged plug ba Premium plus 6% Halad, 20 ll out cement from 4025-410 TD). Circ clean. RD power	ck @4109'. Pullup to 4105 0 sxs 2% Cal Chloride, .3 su 5'. Test squeeze to 1000 R\$	er CBL. Stingout.
	RU HES acid truck. Perform 6 se	etting PPI acid job w/55 bbl o ***see additional o	data on attached sheet***	<b>V</b>
I hereby certify that the information above is constructed or	true and complete to the best of my know	etting PPI acid job w/55 bbl o ***see additional o	data on attached sheet***	<b>V</b>
I hereby certify that the information above is	true and complete to the best of my know	etting PPI acid job w/55 bbl o ***see additional o	data on attached sheet*** hat any pit or below-grade tank ha	<b>V</b>
I hereby certify that the information above is constructed or	true and complete to the best of my know	etting PPI acid job w/55 bbl of ***see additional of the second s	data on attached sheet***  hat any pit or below-grade tank hat OCD-approved	<b>V</b>
I hereby certify that the information above is constructed or closed according to NMOCD guidelines  SIGNATURE  TYPE OR PRINT NAME Mendy A. Jo	true and complete to the best of my know	etting PPI acid job w/55 bbl of ***see additional of the see additional of the see and belief. Further certify the see and cattached alternative plan	data on attached sheet***  hat any pit or below-grade tank hat OCD-approved	s been/will be
I hereby certify that the information above is constructed or closed according to NMOCD guidelines  SIGNATURE  TYPE OR PRINT NAME Mendy A. J.  For State Use Only	, a general permit	etting PPI acid job w/55 bbl of ***see additional of seed and belief. If the certify the dedge and belief. If the certify the dedge and seed alternative plan of the dedge and seed attached alternative of the dedge and seed attached alternative of the dedge and belief. If	hat any pit or below-grade tank hat any pit or below-grade tank hat OCD-approved  Associate  DATE  TELEPHONE NO.	04/25/2007 806-592-6280
I hereby certify that the information above is constructed or closed according to NMOCD guidelines  SIGNATURE  TYPE OR PRINT NAME Mendy A. Jo	, a general permit	etting PPI acid job w/55 bbl of ***see additional of seed and belief. If the certify the dedge and belief. If the certify the dedge and seed alternative plan of the dedge and seed attached alternative of the dedge and seed attached alternative of the dedge and belief. If	hat any pit or below-grade tank hat any pit or below-grade tank hat OCD-approved  Associate  TELEPHONE NO.	04/25/2007 806-592-6280

## NHU 32-143 04/07/2007

- 10. Pump 200 gal of 6490 mixed w/100 bbl of fresh water. Flush w/500 bbl fresh water. 11. POOH w/PPI packer.
- 12. Run back in hole w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4032'
- 13. ND BOP & NU WH.
- 14. RDPU & RU. Clean location.

RUPU 03/14/2007 RDPU 03/23/2007