State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

DISTRICT 1220 South St. Francis Dr. Santa Fe, NM 87505 Santa Fe, NM 87505 Sulf. APINO South St. Francis Dr. South	FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION			
DISTRICT II JOS W Grand Ave, Arteria, NM 8210 DISTRECT III JOS W Grand Ave, Arteria, NM 8210 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THE KOME FOR PROPOSALS TO DRILL OR TO DESPETS ON WELLS (DO NOT USE THE KOME FOR PROPOSALS TO DRILL OR TO DESPETS OR PLUC BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (Form CIO)" for such proposals.) 1 Type of Welt Occidental Permian Ltd. 3 Address of Operator Occidental Permian Ltd. 3 Address of Operator HICR 1 Row 90 Denver City, TX 79323 4 Well Location HICR 1 Row 90 Denver City, TX 79323 4 Well Location HICR 1 Row 90 Denver City, TX 79323 5 Township Hich Location 11 Expansion (Show whether DF, RKS, RT GR, etc.) 16 OF Blow-grade Tank Application Or Closure Pit Type Pit Type Pit Type Distance from nearest fresh water well Distance from nearest surface water Pit Type NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUS ADA DARADON ORABINE COMMENCE ORILLING OPNS PILLOR ATTERIOR GASING Maniple Completion CASING TEST AND CEMENT JOB 13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULLs 1103. For Multiple Completions. Attach wellhore diagram of proposed completion or recompletion. 14 Kill well. NU BOP, Pull out of hole winspection equipment. 2 Clean out well or PBTD 264430: 3 Acid treat well work 980 gat or 12% PAD acid. 3 Representative Associate PIT Type Or RRINT NAME PROPER TO THE Administrative Associate PATE OLIVARION PRICE OR PRINT NAME PROPER TO THE Administrative Associate PATE OLIVARION PATE OLIVARION PATE OR PRINT NAME PATE OLIVARION PATE OR PRINT NAME PATE OLIVARION PATE OR PRINT NAME PATE OLIVARION PATE OLIVAR						
State Oil & Gis Lawe No.	DISTRICT II	Juliu : 4,		5. Indicate Type of Lease		
County C	1301 W. Grand Ave, Artesia, NM 88210				FEE X	
SINDRY NOTICES AND REPORTS ON WELLS ODITY PERFORMANCE PROPOSALS TO DRIEL OR TO DEEPEN OR PLUG BACK TO A DITY PERST RESERVOR USE "APPLICATION POR FERMIT" (Frem Cito) for such proposals.) 1. Type of Well OLI Well Gas Well Obty Injector Occidental Permian Ltd. 3. Address of Operator Unit Letter Section 34 Township 18-S Range 38-E NMPM Lea County 11. Elevation (Show whether DF, RKB, RT GR, etc.) 21. Township 18-S Range 38-E NMPM Lea County 11. Elevation (Show whether DF, RKB, RT GR, etc.) 21. Type Depth of Ground Water Distance from nearest fresh water well NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG & ABANDONMENT PULL OR ALTER CASINO Multiple Completion CHANGE PLANS COMMENCE DRILLING OPNS PLUG & ABANDONMENT CASING Excellent of the winder of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole w/injection equipment. 2. Clean out & acid treat The Experiment Augment of the plans Commence of the plans or an (attached) alternative Associate DATE TITLE DATE OCHECK PRESENTATIVE IUSTAFT MANAGER DATE DATE TITLE DATE TI	DISTRICT III			6. State Oil & Gas Lease No.		
(DO NOT USE TRIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Section 3.4 Type of Well Oil Well Oil Well Osby Disperior Occidental Permian Ltd. 10 Pool name or Wildox Hobbs (G/SA) Unit Section 3.4 Well No. Coop 12 2. Name of Operator Occidental Permian Ltd. 10 Pool name or Wildox Hobbs (G/SA) Well Location Unit Letter N				7 Lease Name on Unit Agran	ment Nama	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (From Ci01) for such proposals.) 1. Type of West Oil West Oil West Gas Well Other Injector 2. Nume of Operator Occidental Permian Ltd. 3. Address of Operator HCR1 Box 09 Denver City, TX 79323 4. Well Location HICH Box 09 Section 34 Township 18-S Range Rang						
1. Type of Well	(DO NOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A	, , ,		
Oil Well Gas Well Objus Injector 2. Name of Operator Occidental Permian Ltd. 3. Address of Operator HCR I Box 90 Denver City, TX 79323 4. Well Location HCR I Box 90 Denver City, TX 79323 4. Well Location Unit Letter N 636 Feet From The South 2348 Feet From The West Line Section 34 Township 18-S Range 38-E NMFM Lea County 310 °CI 3310 °CI. Pit or Below-grade Tank Application Or Closure Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mil Below-Grade Tank: Volume bbls: Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS: PLUG & ABANDONMENT PULL OR ALTER CASING Multiple Completion CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS: PLUG & ABANDONMENT CASING TEST AND CEMENT						
Occidental Permian Ltd. 3. Address of Operator IICR I Box 90 Denver City, TX 79323 4. Well Location Unit Letter N 636 Feet From The South 2348 Feet From The West Line Section 34 Township 18-5 Range 38-E NMPM Lea County 11. Elevation (Show whether DF. R.R.B., RT GR. etc.) 15(10° GL.) Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mil Below-Grade Tank. Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT THE Clean out & acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed ovorty Stee Rull. 1103. For Multiple Completions: Atlach wellbore diagram of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole winjection equipment. 2. Clean out well to PBTD @#4310: 3. Acid treat well wy3800 gal of 15% PAD acid. 4. S				•	,	
3. Address of Operator IICR 1Box 90 Denver City, TX 79323 4. Well Location Unit Letter N 636 Feet From The South 2348 Feet From The West Line Section 34 Township 18-S Range 38-E NMPM Lea County 11. Elevation (Show whether DF. R.K.B., RT GR. etc.) 3610' GL Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well Distance from nearest surface water Pit I. Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit I. Depth of Ground Water Distance from nearest fresh water well NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUS AND ABANDON REMEDIAL WORK ALTERING CASING OTHER: Clean out & acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed world SEE RULE [103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole w/injection equipment. 2. Clean out well to PBITD @4430'. 3. Acid treat well w/3800 gal of 15% PAD acid. 4. Swah/Tow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test easing & chart for the NMOCD. 1. Kill well. NU BOP. Pull out of hole w/injection equipment. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. 1. Kill well. Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy J hinson E-mail address: mendy johnson@oxy.com TELEPHONE NO 806-592-6280 POS SHEED REPRESENTATIVE II/STAFF MANAGEM. OCHER STAND COMMENCE DRUCH II/STAFF MANAGEM. OCHER STAND COMMENCE II/STAFF MANAGEM. OCHER STAND COMMENCE DRUCH II/STAFF MANAGEM. OCHER STAND COMMENC				9. OGRID No. 157984		
West Line Unit Letter N 636 Feet From The South 2348 Feet From The West Line Section 34 Township 18-S Range 38-E NMPM Lea County				10. Pool name or Wildcat	Hobbs (G/SA)	
Unit Letter N 636 Feet From The South 2348 Feet From The West Line Section 34 Township 18-S Range 38-E NMPM Lea County 3610' GL Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well Distance from nearest surface water Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mill Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING Multiple Completion Tother: Clean out & acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole winjection equipment. 2. Clean out well to PBID @4430. 3. Acid treat well will 8080 gai of 15% PAD acid. 4. Syab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below-grade State has been/will be constructed or closed according to NMOCD guidelines and a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 mendy johnson@exy.com TELEPHONE NO 806-592-6280 For State Use Only APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANUAL ALTER DATE		79323			, , , , , , , , , , , , , , , , , , ,	
Section 34 Township 18-S Range 38-E NMPM Lea County 3610 GL Pit or Below-grade Tank Application or Closure bit 19 or October 1	4. Well Location					
Pit or Below-grade Tank Application	Unit Letter N : 636	Feet From The South			_	
Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well Distance from nearest surface water Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mill Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Clean out & acid treat Thereby control the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole w/injection equipment. 2. Clean out well to PBTD @4430. 3. Acid treat well w/3800 gal of 15% PAD acid. 4. Swah7how back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. There of the NMOCD guidelines are general permit or an (attached) alternative OCD approved plan. SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy J. phnson E-mail address: mendy johnson@xxy.com TeLEPHONENO 806-592-6280 OC FIELD REPRESENTATIVE II/STAFF MANAGET TITLE DATE.	Section 34			NMPM	Lea County	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	The ingressive states of					
Pit Liner Thickness	Pit or Below-grade Tank Application or Closure					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK	Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK	Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG & ABANDONMENT OTHER: Clean out & acid treat X OTHER: Clean out well to PBTD @4430'. 1. Kill well. NU BOP. Pull out of hole winjection equipment. 2. Clean out well to PBTD @4430'. 3. Acid treat well w/380 gal of 15% PAD acid. 4. Swab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below ghad Man-Has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 OC FIELD REPRESENTATIVE II/STAFF MANAGEMENT AND ADATE TITLE.						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING Multiple Completion OTHER: Clean out & acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole w/injection equipment. 2. Clean out well to PBTD @4430'. 3. Acid treat well w/3800 gal of 15% PAD acid. 4. Swab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below grade Table has been/will be constructed or closed according to NMOCD guidelines a general permit or an (attached) alternative OCD approved plan SIGNATURE TYPE OR PRINT NAME Mendy Alphnson E-mail address: mendy johnson@oxy.com TelePHONE No. 806-592-6280 OC FIELD REPRESENTATIVE II/STAFF MANAGEMENT AND ADDRESS. TITLE DATE OF TITLE DATE.						
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB OTHER: Clean out & acid treat Title Administrative Associate DATE OATE PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER CASING TEST AND CEMENT J	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERIN	G CASING	
OTHER: Clean out & acid treat IX OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole w/injection equipment. 2. Clean out well to PBTD @4430'. 3. Acid treat well w/3800 gal of 15% PAD acid. 4. Swab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test easing & chart for the NMOCD. 1. hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below that this been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD approved plan SIGNATURE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TelePhone No. 806-592-6280 OC FIELD REPRESENTATIVE II/STAFF MANAGEMENT AND APPROVED BY TITLE DATE DATE OA/24/2007	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP			NS. PLUG & A	ABANDONMENT	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole w/injection equipment. 2. Clean out well to PBTD @4430'. 3. Acid treat well w/3800 gal of 15% PAD acid. 4. Swab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below grade fame has been/will be constructed or closed according to NMOCD guidelines agency agency agency of an (attached) alternative OCD-approved plan SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 OC FIELD REPRESENTATIVE II/STAFF MANAGEMENT AND DATE DATE DATE DATE DATE	PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	IT JOB		
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. NU BOP. Pull out of hole w/injection equipment. 2. Clean out well to PBTD @4430°. 3. Acid treat well w/3800 gal of 15% PAD acid. 4. Swab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below grade that has been/will be constructed or closed according to NMOCD guidelines agency agency or an (attached) alternative OCD approved plan SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 OC FIELD REPRESENTATIVE II/STAFF MANAGER OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE DATE	OTHER: Clean out & acid treat	X	OTHER:			
2. Clean out well to PBTD @4430'. 3. Acid treat well w/3800 gal of 15% PAD acid. 4. Swab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TYPE OR PRINT NAME Mendy / Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY APPROVED BY TITLE DATE DATE DATE DATE DATE	13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
3. Acid treat well w/3800 gal of 15% PAD acid. 4. Swab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD approved plan SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY APPROVED BY APPROVED BY APPROVED BY TITLE DATE DATE DATE DATE		e w/injection equipment.		16 to 18		
4. Swab/flow back. Circ well clean. 5. Run back in hole with injection equipment. 6. Test casing & chart for the NMOCD. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below grade tank has been/will be constructed or closed according to NMOCD guidelines a general permit or an (attached) alternative OCD approved plan SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY APPROVED BY APPROVED BY TITLE DATE	2. Clean out well to PBTD @4430'.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. Further certify that any pit or below grade nanchas been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD approved plan SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY APPROVED BY APPROVED BY APPROVED BY TITLE DATE DATE DATE DATE DATE DATE DATE	3. Acid treat well w/3800 gal of 15% F	AD acid.		(0)		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. If urther certify that any pit or below-grade rank-has been/will be constructed or closed according to NMOCD guidelines ageneral permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY APPROVED BY APPROVED BY TITLE DATE DATE DATE DATE		ipment.		Chart as	À	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. If urther certify that any pit or below-grade rank-has been/will be constructed or closed according to NMOCD guidelines ageneral permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY APPROVED BY APPROVED BY TITLE DATE DATE DATE DATE				10 200	Maria de la companya della companya della companya della companya de la companya della companya	
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGED DATE DATE DATE				681.	e 3)	
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGED DATE DATE DATE	·				, 39	
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGED DATE DATE DATE						
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGED DATE DATE DATE				COC 67 97 17	9 ⁽²⁾	
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/24/2007 TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGET DATE DATE DATE DATE						
SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: Mendy A. Johnson TITLE Administrative Associate DATE 04/24/2007 TELEPHONE NO. 806-592-6280 TITLE DATE DATE DATE DATE DATE DATE DATE 04/24/2007 TITLE TITLE DATE DA		, a general permit	or an (attached) alternativ	re OCD-approved	7	
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy_iohnson@oxy.com TELEPHONE.NO. 806-592-6280 For State Use Only APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGET DATE DATE	Magal		<u>.</u>		J	
APPROVED BY CONSTITUTE OF TITLE DATE		1 Announ				
APPROVED BY THE DATE		hnson E-mail address:	mendy_johnson@oxy.com	I II/STAFF MANAGER	o. 800-392-0280	
CONTROL OF A PROPERTY AND A PROPERTY OF A PR	APPROVED BY LOW WITH OC FIELD REPRESENTATIVE TO DATE					